



2D Extrinsic Calibration (Section 8.4.2)

Sensor Trajectories



After Calibration (Aligned)



Extrinsic Calibration Results:

True Rotation Angle: 30.00 deg
Estimated Rotation: 30.06 deg
Error: 0.0620 deg

True Lever-arm: [0.500, 0.300] m
Estimated Lever-arm: [0.499, 0.298] m
Error: 0.0025 m

Rotation Matrix (Estimated):

[0.8655, -0.5009]
[0.5009, 0.8655]

Calibration Residuals (RMSE: 0.1021 m)

