



Care Net Consultants (Pty) Ltd
Reg no: 2012 / 038468 / 07
VAT no: 4620265191

 www.carenetconsultants.co.za
 +27 60 070 2723
 salesdesk@carenetconsultants.co.za
 154 Allan Road, Midrand 1684



EXAMPLE DOCUMENT. Castavel Coatings (Pty) Ltd is a fictitious company. Every company, person, address, date, figure and reference number in this example is made up; only the Care Net letterhead and any public emergency number are real. For guidance only; not a document to sign or rely on.

Example for a Health and Safety File, Section J: Occupational hygiene

Occupational Hygiene Monitoring Summary: Hazardous Chemical Agents

Solvent vapour survey, spray booth and mixing room, Castavel Coatings, Jacobs, Durban. Survey of 3 and 4 February 2026

About this example	Detail
Company in the example	Castavel Coatings (Pty) Ltd, a fictitious company
Where it is filed	Section J: Occupational hygiene
Published by	Care Net Consultants, as guidance for companies building a Health and Safety File

How to use this example


This example shows the form and content Care Net recommends for this document in a Health and Safety File. Adapt it to your company, your sites and your appointments; your registered Health and Safety practitioner confirms it before your File is released. Not legal advice.

Contents

1. Purpose
2. Who did the survey
3. What was measured
4. Results as the approved inspection authority reported them
5. Actions taken
6. Next survey



YOUR PARTNER IN WORKPLACE HEALTH.



Occupational Hygiene Monitoring Summary: Hazardous Chemical Agents

Solvent vapour survey, spray booth and mixing room, Castavel Coatings, Jacobs, Durban. Survey of 3 and 4 February 2026

1. Purpose

This summary records the airborne solvent exposure survey in the spray booth and paint mixing room, done because the company's risk assessment identified hazardous chemical agents in the paints and thinners used. It sits in front of the full survey report in this section and tells the reader what was measured, by whom, what the approved inspection authority concluded, and what the company did about it.

2. Who did the survey

Item	Detail
Approved inspection authority	Nimbalo Occupational Hygiene (Pty) Ltd (fictitious), an approved inspection authority for hazardous chemical agents; approval certificate on file with the report
Occupational hygienist who signed the report	Priya Govender (fictitious), registered occupational hygienist; registration proof on file with the report
Company contact	Sanele Mthembu, Health and Safety Officer
Report reference and date	NOH 2026 031, issued 20 February 2026



3. What was measured

- Personal air samples in the breathing zone of spray painters and the paint mixer over a full shift on both days
- Static samples at the spray booth doorway and in the mixing room
- Solvent components named in the safety data sheets of the paints and thinners in use
- Airflow at the spray booth extraction face


4. Results as the approved inspection authority reported them

The limits used and the interpretation are the approved inspection authority's, from its report. This summary does not add limits of its own.

Similar exposure group	Samples	Interpretation in the report	Controls in place
Spray painters (4 people)	8 personal	Within the occupational exposure limits for all agents measured (personal breathing zone samples)	Spray booth extraction; supplied air respirators; coveralls and gloves
Paint mixer (1 person)	2 personal	One agent above the occupational exposure limit on 4 February during bulk thinning	General ventilation only; half mask respirator worn part of the shift
Mixing room (static)	2 static	Elevated background levels; ventilation inadequate	Door open; one wall fan
Spray booth extraction face	Airflow readings	Below the design airflow stated by the booth supplier at two of six points	Filters last changed in December 2025

5. Actions taken

No.	Action	Owner	Due	Status
1	Local exhaust ventilation hood fitted over the mixing bench, designed and tested by a ventilation contractor	Operations Manager	31/03/2026	Closed 26/03/2026
2	Paint mixer to wear the respirator for all thinning until the retest confirms the new extraction works; fit test done	Sanele Mthembu	23/02/2026	Closed 23/02/2026



No.	Action	Owner	Due	Status
3	Spray booth filters changed and airflow rebalanced; filter changes added to the maintenance plan	Maintenance Supervisor	06/03/2026	Closed 04/03/2026
4	Retest of the paint mixer and the mixing room by the approved inspection authority after the new hood	Sanele Mthembu	30/04/2026	Closed; retest of 21/04/2026 reported within the occupational exposure limits
5	Survey results shared with the occupational medical practitioner, who set the medical surveillance for the exposed groups; outcomes only (fit, fit with restrictions, unfit) are filed in Section E	Sanele Mthembu	28/02/2026	Closed 25/02/2026
6	Results explained to the affected employees and the health and safety representative; attendance register filed	Sanele Mthembu	27/02/2026	Closed 26/02/2026

6. Next survey

The next survey is done at the interval the approved inspection authority recommends in its report and the registered Health and Safety practitioner confirms, and sooner if a product, process or control changes. The due date is entered in the occupational hygiene survey programme at the front of this section.

Health and Safety Officer

Sanele Mthembu, Date: 28/04/2026

Operations Manager (actions approved)

Thandeka Ngcobo, Date: 29/04/2026

End of the example. The company, people and records in it are fictitious; the cover page explains how to use it.



YOUR PARTNER IN WORKPLACE HEALTH.

