Car Damage Assessment Report

Image: 000320.jpg

Date: 2026-03-15 15:13

Damages found: 1



Damage Summary

#	Type	Severity	Location	Cost Range	Repair Method
1	glass shatter	severe	windshield	$400-$1,500	Full glass replacement (OEM)

Estimated Total: $400 - $1,500

Best estimate (midpoint): $950

Car Damage Assessment Report

Individual Damage Details

Damage #1: Glass Shatter

Type: glass shatter
Severity: severe (confidence: 70%)
Location: windshield (confidence: 83%)
Cost estimate: $400 - $1,500
Repair method: Full glass replacement (OEM)

Disclaimer: Cost estimates are approximate and based on US market averages. Actual repair costs depend on vehicle make/model, location, parts availability, and shop rates. Severity and location are assessed by CLIP zero-shot classification and may not be fully accurate. This report is for informational purposes only.