



JOURNAL OF RARE EARTHS

www.re-journal.com/en/

JOURNAL OF RARE EARTHS, Vol. 32, No. 4, Apr. 2014, P. 352

Lanthanum-exchanged zeolite and clay as anticorrosive pigments for galvanized steel

S. Roselli, N. Bellotti, C. Deyá*, M. Revuelta, B. del Amo, R. Romagnoli

(CIDEPINT (Centro de Investigación y Desarrollo en Tecnología de Pinturas) (CONICET-CIC), Calle 52 entre 121 y 122 (B1900AYB) La Plata, Argentina)
Received 4 July 2013; revised 6 January 2014

Abstract: A wide variety of inhibitive pigments is now being offered as possible alternatives to chromate and lead compounds for painted metals protection. Unfortunately, the most wide spread of these substitute pigments, zinc phosphate, has, at present, raised some environmental concern because phosphate causes the eutrophication of water courses and zinc itself is toxic. The aim of this research was to study the anticorrosive performance of a mixture consisting of zinc phosphate, modified zeolite and clay (bentonite) in order to diminish phosphate content in paints. The zeolite and the clay were exchanged with La(III) ions, as inorganic green inhibitor. In the first step, the anticorrosion protection by La(III) ions in solution was assessed by electrochemical tests. In the second step, an epoxy-polyamide paint formulated with the pigment mixture applied on galvanized panels was studied by salt spray test and electrochemical noise measurements (ENM). The results showed that it was possible to replace part of the zinc phosphate content in the paint with the exchanged zeolite and the clay.

Keywords: exchanged pigments; corrosion; anticorrosive paints; electrochemical noise measurements; rare earths

A wide variety of inhibitive pigments is now being offered as possible alternatives to chromate and lead compounds for painted metals protection. Unfortunately, the most wide spread of these phosphate substitute pigments. zinc phosphate, has, at present, raised some environmental concern because it causes the eutrophication of water courses^[1,2]. This process is originated by an excess of nutrients which produces changes in the biological community. An attempt to eliminate or, at least, diminish phosphate content in paints is one of the main focuses of the scientific research in this field. In this sense each component of the pigment system is carefully evaluated for its influence on the overall paint performance^[3–5]. Particularly attention is given to silicate extenders, like talcs and clays. For example, the partial replacement (~75%) of the corrosion inhibitor with surface modified clay improved the performance of paints formulated with basic lead silico chromate or zinc phosphate^[4]. The performance of a synergistic blend of zinc phosphate and modified clay was comparable with that of strontium chromate and basic lead silico chromate^[4]. Other researchers also studied the incorporation of polyaniline or quaternary alkylphosphonium salts in clays as anticorrosive pigments [6-8].

The employment of extender pigments modified with rare earth metal (REM) cations such as cerium or lanthanum is of particular interest. Zeolites and bentonite are naturally occurring aluminosilicates. They share the capacity for ion-exchanging and may be employed as reservoirs for inhibitive cations. The use of a cerium-exchanged bentonite on galvanized steel has been reported by Bohm, et al.^[9]. This exchanged-bentonite corrosion ability rests on the fact that it exchanged REM cations for Na⁺ present in the attacking electrolyte.

REM salts may constitute alternative to phosphates as they are found to posses excellent inhibitive properties^[10,11]. Lanthanum ions have proved to be efficient as corrosion inhibitor in chloride solutions of several metals^[13]. The mechanism of operation of these inhibitors seems to be related with kinetic modifications of the cathodic reduction of oxygen^[6]. Besides, lanthanide salts like nitrates were reported to have low toxicity comparable to that of sodium chloride^[12] and can be considered as "green" inhibitors.

Zeolites are crystalline-aluminosilicates which consist in an array of corner-sharing $\mathrm{SiO_4}^{-4}$ or $\mathrm{AlO_4}^{-5}$ tetrahedrals. These building blocks become arranged in a periodic way to form channels and cages with large specific surface areas, typically above $300~\mathrm{m^2/g}$, being the volume of internal voids above $0.1~\mathrm{cm^3/g^{[12,14]}}$. The aluminum ion is small enough to occupy the center of the tetrahedron of four oxygen atoms. The isomorphous replacement of $\mathrm{Si^{4+}}$ by $\mathrm{Al^{3+}}$ produces a negative charge in the lattice which could be balanced by the exchangeable cation. In previous studies, zeolites exchanged with mo-

Foundation item: Project supported by CONICET (Consejo Nacional de Investigaciones Científicas y Técnicas), UNLP (Universidad Nacional de La Plata) and CICPBA (Comisión de Investigaciones Científicas de la Provincia de Buenos Aires)

lybdenum were used to replace part of the zinc phosphate in smart anticorrosive paints^[15].

The aim of this research work was to study the anticorrosive performance of an epoxy-polyamide paint formulated with zinc phosphate, modified zeolite and clay (bentonite) applied on galvanized steel. The zeolite and the clay were exchanged with La(III) ions as inorganic green inhibitor. The anticorrosion protection by La(III) ions was assessed by electrochemical tests (corrosion potential, polarization resistance and polarization curves). Salt spray test and electrochemical noise measurements (ENM) were done on painted panels. The results showed that it was possible to replace part of the zinc phosphate content in the paint with exchanged zeolite and clay.

1 Materials and methods

1.1 Minerals characterization

The zeolite used in this research was extracted from Tasajera's reservoir in Cuba. The qualitative mineralogical composition was obtained by X-ray diffraction (XRD) in rock samples. The clay was a commercial one: Bentone $107^{\text{(B)}}$, by Elementis. It was smectite clay, surface modified by an organic treatment [16]. The texture of the minerals was examined by scanning electron microscopy (SEM) in order to observe the morphology, surface structure and particles size.

The density of the natural zeolite and the commercial clay was obtained by a pycnometric method according to ASTM G 1475 to formulate the paints.

1.2 Preparation of lanthanum-exchanged pigments

The zeolitic rock was ground to obtain a fine grain powder with particles size less than 10 µm. The ground zeolite was washed with distilled water (DW) twice and placed in a beaker with 0.2 mol/L HNO3 which was heated up to the boiling temperature and kept at that temperature for 1 h in order to eliminate ferric compounds. The acid solution was added from time to time to keep the solution volume constant. The zeolite was separated from the supernatant by centrifugation at 2200 X g for 10 min and washed with DW several times. Afterwards, it was placed in a beaker with 2 mol/L NaCH₃COO for 3 h under continuous stirring to put it back in the Na⁺-form. Then the zeolite was separated by centrifugation and washed with DW. Finally the zeolite was exchanged with La(III) ions by bringing it into contact with 1 mol/L La(NO₃)₃ in 1×10⁻³ mol/L HNO₃, under constant stirring, for 24 h. The exchanged zeolite was separated by centrifugation, washed four times with DW and dried in an oven at 90 °C. Similar procedure was done with the clay, except the milling pretreatment.

1.3 Lanthanum-exchanged capacity

The sorbed La(III) was back extracted into solution with 100 mL of 1 mol/L CH₃COONH₄ from 1 g of treated zeolite or bentonite by continuous stirring for 24 h. Then the solid was separated by centrifugation and La was quantified in the supernatant by a gravimetric technique^[17]. Briefly, an aliquot of 70 mL of the solution containing lanthanum ion was acidified with 10 mL of 2 mol/L acetic acid and treated with a slight excess of a 3% (w/v) 8-hydroxyquinoline (C₉H₇NO) in ethyl alcohol. Then, lanthanum "oxinate" was precipitated by adding 20 mL of 10% (w/v) ammonium hydroxide and the solution was heated to boiling. The yellow precipitate was separated by centrifugation at 2200 X g for 5 min, washed with hot water, dried at 110 °C and weighed in an analytical balance (precision 0.1 mg). The precipitated has the formula La(C₉H₆ON)₃ and contains 24.33 wt.% of lanthanum. The control sample was prepared with 70 mL of an aqueous solution of lanthanum nitrate containing 0.1 g of lanthanum ions.

1.4 Electrochemical assays

The protective behavior of La(III) ions was assessed by d.c. electrochemical techniques. Corrosion potential of commercial galvanized steel electrodes (120 g/m² of Zn) was measured as a function of time with respect to the saturated calomel electrode (SCE). Lanthanum(III) nitrate concentration was varied from 3.3×10⁻⁵ to 1.0×10⁻² mol/L. These solutions were employed in order to simulate the lanthanum concentration leached from zeolite or from the clay. The supporting electrolyte was NaCl 0.025 mol/L. Measurements were performed for 4 h and after 24 h. Exposed panels were observed by SEM and the composition of the protective layer determined by EDX analysis.

Galvanized steel corrosion rate in the same electrolyte was obtained from polarization curves (with IR-drop compensation). A SCE and a platinum grid were used as reference and counterelectrode, respectively. The swept amplitude was ±0.020 V from the open circuit potential and the scan rate 0.166 mV/s. The area exposed was 0.28 cm². Measurements were carried out with the 273A EG&G PAR Potentiostat/Galvanostat in combination with model SOFTCORR 352 software (EG&G PAR). Measurements were carried out after 2, 5 and 24 h of immersion.

1.5 Formulation, elaboration and application of paints

A bisphenol epoxy-polyamide resin (1:1 ratio v/v) was employed as the film forming material. The solvent was the mixture of xylene/methyl isobutyl ketone/butyl cellosolve (13/45/42% w/w). Paints composition can be seen in Table 1. Paints labeled with L are the ones containing the exchanged zeolite while the ones labeled with B are the control paints containing the unexchanged zeo-

Table 1 Paints composition as percentage by volume

Components		Paints								
Components	L1	L2	L3	B1	B2	В3				
Zeolite	5.2	5.2	2.6	5.2	5.2	_				
Clay	-	_	2.6	_	_	_				
Zinc phosphate	2.6	_	2.6	2.6	-	_				
Barium sulfate	7.4	8.5	7.4	7.4	8.5	10.7				
Talc	7.4	8.5	7.4	7.4	8.5	10.7				
Titanium dioxide	2.9	3.3	2.9	2.9	3.3	4.1				
Resin	35.7	35.7	35.7	35.7	35.7	35.7				
Solvent	38.8	38.8	38.8	38.8	38.8	38.8				

lite. Moreover, paints with number 1 contained zinc phosphate. Paint L3 had a certain amount of exchanged clay besides the exchanged zeolite and zinc phosphate. Barium sulfate, talc and titanium dioxide were incorporated to complete the pigment formulas. Paint B3 had only inert pigments (barium sulfate, talc and titanium oxide). In every case, the pigment volume concentration (PVC) was 41.2%.

Pigments were dispersed in the vehicle (resin and solvent) for 24 h, employing a ball mill, to achieve an acceptable dispersion degree.

Commercial galvanized steel panels (15.0 cm×7.5 cm× 0.2 cm) were degreased firstly with toluene and, then, by immersion in boiling 5% (w/v) CaCO₃ for 5 min. Then, the panels were washed with DW and dried. Previous to painting, panels were coated with a polyvinylbutiral wash primer pigmented with aluminium phosphosilicate. Details about this formulation and its performance may be found elsewhere^[18]. Finally, panels were painted by brush, up to a dry film thickness of 65±5 μ m, and were kept indoors for 14 d before testing.

1.6 Accelerated and electrochemical tests on painted panels

A set of three panels per paint was placed in a salt spray chamber (Atlas Model SF850, USA) in accordance with ASTM B 117 (Standard Method of Salt Spray (Fog) Testing). Rusting (ASTM D 610) and blistering (ASTM D 714) degrees were evaluated after 340, 840, 1536, 1920 and 2350 h of exposure.

The ionic resistance between the coated steel substrate and a platinum electrode was measured in a cell obtained by fixing an acrylic tube, 2 cm diameter, on the painted specimen and filling it with 0.5 mol/L sodium chloride. Measurements were carried out employing an ATI Orion, model 170, conductivity meter at 1000 Hz.

The cell for ENM was constituted by two nominally identical electrodes and a reference electrode. A low value resistor was placed between the two specimens and current noise was measured through the voltage fluctuation across the resistor, on the grounds that interference from the electronic circuitry will be diminished. The three electrodes were in the same container which made

it easier to control the effect of temperature fluctuations. The edges of the specimens were blanked off leaving 26 cm² of the painted panel exposed to a 0.5 mol/L NaCl solution. Data were acquired with a NICOLET 310 digital oscilloscope and the corresponding software 310RFWFT. Adequate filtering was provided just to eliminate undesirable signals like line signals^[19–21]. The sensitivity of the measuring device in the E-scale was 100 µV and 100 nA in current measurements. The sampling frequency was 5 Hz, which is commonly used to study corroding systems^[19-21]. Data were collected during 800 s and each data set was controlled to verify they distribute normally^[22]. Statistical analysis of each time series were performed and the noise resistance (R_n) was calculated as the quotient $R_n = \sigma_E/\sigma_i$, where σ_E is the dispersion of the potential data and oi the dispersion of current density data^[18–21]. Although the mean values of raw data were plotted, the d.c. trend was removed to perform R_n calculation by the moving average removal procedure described by Tan et al. [23].

2 Results and discussion

2.1 Characterization of the minerals

Physical properties of the selected materials can be seen in Table 2. Tasajera's zeolite was composed of clinoptilolite, quartz and calcite: ~30 wt.% of each mineral. Clay and plagioclase were also detected but in a lower low proportion (5 wt.%–15 wt.%). These results are similar to those reported in other studies^[24,25].

The SEM micrographs of the zeolite and the clay are shown in Fig. 1. It can be seen that the particle size distribution of both minerals, zeolite (Fig. 1(a)) and clay (Fig. 1(b)) was broad, with sizes varying from 6 to 100 μ m. Despite the bigger size of some particle (>10 μ m) as the materials were quite soft, no inhomogeneities appeared after painting the substrates.

2.2 Lanthanum-exchanged capacity

Table 2 shows that the exchange capacity of the zeolite, 10.90~mg of La(III)/g $_{\text{mineral}}$, was higher than that of the clay, 5.70~mg/g $_{\text{mineral}}$. Results were also expressed as molar concentration in order to prepare the La(III) solutions for the electrochemical tests.

2.3 Electrochemical assay

Fig. 2 shows that the corrosion potential values were shifted from ~ -0.970 to ~ -0.870 V when the La(III)

Table 2 Physical properties of minerals

Min1	Density/	La-exchanged capacity				
Mineral	(g/mL)	mg/g mineral	mol/L			
Zeolite	2.18	10.9± 0.1	7.8×10 ⁻⁴			
Clay	1.70	5.7± 0.4	4.1×10 ⁻⁴			




Fig. 1 Minerals SEM micrographs
(a) Zeolite; (b) Clay




Fig. 2 Corrosion potential of the samples immersed in 0.025 mol/L NaCl at different concentrations (mol/L) of La(III) nitrate (1) 3.3×10⁻⁵; (2) 6.6×10⁻⁵; (3) 1.0×10⁻⁴; (4) 4.0×10⁻⁴; (5) 1.0×10⁻³; (6) 1.0×10⁻²; (7) Blank

concentration increased from 3.0×10^{-5} to 10^{-4} mol/L. In every case, $E_{\rm corr}$ was shifted to more positive values comparing with the blank ($\sim-1.000~\rm V$). Peaks observed in Fig. 2 could be attributed to active-passive transitions. When La(III) concentration increased to 10^{-3} or 10^{-2} mol/L, the corrosion potential was also shifted to less active values $\sim-0.100~\rm V$. The oscillations presented in the corrosion potential when the La(III) concentration employed was 6.6×10^{-5} mol/L were due to the instability of the protective film which was suspected to a passivation-break down-repassivation process.

The most striking effect of La(III) on i_{corr} was appreciated at early immersion times. Steel corrosion rate was diminished after two hours of testing by lanthanum nitrate. However, the protective efficiency for La(III) concentration higher than 3.3×10^{-5} mol/L was, as a general rule, higher than 70%. Steel corrosion rate did not vary significantly when La(III) was increased from 6.6×10^{-5} to 4.0×10^{-4} mol/L. A further increased of La(III) concentration

tration up to 1.0×10^{-2} mol/L, caused i_{corr} to diminish a little bit more (Table 3).

2.4 Observation and characterization of the exposed surface

Galvanized steel panels that were in contact with the different La(III) solutions were observed by SEM after 24 h of immersion. They presented similar features. A more or less uniform film with a granule-like appearance was formed on the metallic surface together with agglomerates constituted by corrosion products (Fig. 3).

Table 3 Corrosion current of the samples immersed in NaCl 0.025 mol/L and different concentrations of La(III) as a function of time

I - (A)(A)	Corrosion current/(µA/cm²)					
La(NO ₃) ₃ concentration/(mol/L)	2 h	5 h	24 h			
0 (blank)	110.80	18.70	14.8			
3.3×10 ⁻⁵	8.32	5.72	7.97			
6.6×10^{-5}	4.36	4.31	4.44			
4.0×10^{-4}	3.19	4.95	5.30			
1.0×10^{-4}	4.82	4.50	4.20			
1.0×10^{-3}	2.87	3.09	1.01			
1.0×10^{-2}	1.77	2.72	3.10			



Fig. 3 SEM micrograph of protective film formed on galvanized steel after 24 h of immersion in La(III) solution

The agglomerations were formed by zinc oxide partially carbonated (Fig. 4). Lanthanum could not be detected accurately in these formations because its signal was superimposed with the base line. The film underneath had similar composition. The granular morphology could be appreciated, in greater detail, in Fig. 5(a), corresponding to galvanized steel immersed in 6.6×10^{-5} mol/L La(III) solution. Granules were formed on a more or less uniform film and rice grain-like morphology can be seen. These granules presented other morphologies (Fig. 5(b)). At higher concentration, the presence of La was detected




Fig. 4 EDX spectrum of agglomerations formed by zinc oxide partially carbonated




Fig. 5 SEM micrographs of film formed on galvanized steel immersed in $6.6{\times}10^{-5}$ mol/L

(a) Details of the granular morphology of the film; (b) Other morphologies

in the globular formation (\sim 2.4%) and in the granular texture film (\sim 1.2%) (Fig. 6) but no La was detected on the base film. Besides, some agglomerations with Cl (0.7%) and Fe (1.2%) in low proportions were found.

When La concentration was raised, the number of the agglomerations per unit area diminished, however they did not disappear completely but the zinc oxide film grew in an ordered way (Fig. 7(a)). La content in the agglomerations and in the base film increased sensibly being in both cases close to ~14%. Petal-like formations grew on localized points of the surface (Fig. 7(b)) in such




Fig. 6 EDX spectrum of globular formations




Fig. 7 SEM micrographs

(a) Granular appearance and agglomerations of the film formed on galvanized steel after 24 h of immersion in 1.3×10^{-4} mol/L La solution; (b) Zinc oxide formations with a "petal" morphology

a way that they did not cover the oxidized surface of galvanized steel. La concentration in these formations was found to be rather high (~22%). Fig. 8 shows the EDX spectra of these formations.

2.5 Performance of anticorrosive paints in accelerated and electrochemical test

2.5.1 Salt spray chamber

Except paint B1, all the paints blistered before 340 h but none of the panels showed corrosion. The size of the blisters varied from 6 (medium) to 2 (big) while the frequency degree was F (few) or M (medium). The size and frequency of the blisters increased with time in every panel, reaching the qualification 2 MD (medium dense) or 2D (dense) after 2350 h of essay but the most important changes occurred at early exposure times. The higher blistering degree presented in the case of L1 and L3, regarding their control paints (B1 and B3, respectively) could be due to the incorporation of soluble species (La ions) that increase the osmotic pressure and enhance the entrance and accumulation of water. However, it must be taken into account that anticorrosive paints are never used alone but with a topcoat which highly restrains water penetration and, as a consequence blistering.

Corrosion of painted panels was detected after 1920 h of exposure but the rusted area was small (~0.03%, qualification 9), except in the case of the panels coated with paint L1 (exchanged zeolite+zinc phosphate) which qualification was 8 (Table 4). However, this corrosion degree kept constant along time while in the other cases the rusted area increased and, concomitantly, the qualification diminished, especially in the case of the control panels (paints B1, B2 and B3) and in the case of L2, the paint with the exchanged zeolite. Panels with paints L1 and L3 were qualified with 8 after 2350 h of exposure. The results revealed that the best anticorrosive performance was achieved when the three pigments were included in the paint and that the presence of zinc phosphate can not be avoided but it may be significantly reduced with respect to the values suggested in the literatures[26, 27].

2.5.2 Ionic resistance

The ionic resistance (R_i) did not vary significantly during




Fig. 8 EDX spectrum of the "petal" formations

Table 4 Rusting (ASTM D 610) and blistering (ASTM D 714) degrees of painted panels after the salt spray test (ASTM B 117)

		Time of exposure/h										
Paints		340		840 1536			1		2350			
	\mathbb{R}^{a}	\mathbf{B}^{b}	Rª	\mathbf{B}^{b}	Rª	\mathbf{B}^{l})	R^{a}	\mathbf{B}^{b}	R	a	\mathbf{B}^{b}
L1	10	6F	10	4MD	10	2M	D	8	2MD	8	2	MD
L2	10	4F	10	2MD	10	2M	2MD		2MD	7	2MD	
L3	10	2M	10	2D	10	2Γ)	9	2D	8		2D
B1	10	10	10	2M	10	2M	D	9	2MD	7	2	MD
B2	10	4M	10	4D	10	20	2D		2D	6	6 2D	
В3	10	2MD	10	2D	10	2Γ	2D		2D	5		2D
^a Rusting degree		10	9	8	7	6	5	4	3	2	1	
Rusted area/%		0	0.03	0.1	0.3	1	3	10	16	33	50	
^b Blistering degree												
Frequency		Dense	;	M II 1 (157)				Medium Few		ew		
		(D)	(D)			ium dense (MD)			(M)		(F)	
Size		10		8			6, 4			2		
Commo	mto.	No		Smaller size blister easily			Progressively					
Comments		blisterii	ng	seen by unaided eye				larger sizes				

the immersion period. Measured values were decreased from 5.3 to $1.9~\text{m}\Omega\text{-cm}^2$ as time went on. The area of direct contact between metal and electrolyte solution at the bottom of pores and fissures (S_p) could be calculated, as a rough approximation, with the equation proposed by Szauer^[28]:

$$S_{p} = d/(k*R_{i}) \tag{1}$$

where d is the coating thickness, k the specific conductivity of the testing solution (NaCl 0.5 mol/L).

In all the cases the exposed area was rather small: $S_p \sim 3.0-6.0\times10^{-8}~\text{cm}^2$. The ionic resistance fluctuated between 2.8 and 5.6 m Ω ·cm² indicating that paints had certain barrier effect. The employment of nanoclay did not improve this barrier effect.

2.5.3 Electrochemical noise

The mean corrosion noise potential oscillated between -0.93 and -0.98 V; no significant differences appeared in the behavior of the metal coated with the paints under study (Fig. 9). However, the mean coupling current oscillated in the cases of the panels painted with paints L1, L3, and B2 during 11 d of immersion probably due to active-passive transitions. After this time, the coupling current reached the lowest value. Then it began to increase slowly and till the end of the first fortnight of immersion. By this time, corrosion points appeared on all panels but the current density remained rather low, fluctuating around 9 μ A/cm², from the beginning of the essay (Fig. 10).

The noise resistance seems to evaluate the charge transfer process^[29]. The R_n values (Fig. 11) for tested coating corrected by the area of the bare metal exposed directly to the electrolyte (S_p) , were high pointing out




Fig. 9 Mean corrosion noise potential of the painted panels, as a function of time, in 0.5 mol/L NaCl




Fig. 10 Coupling current of the painted panels, as a function of time, in 0.5 mol/L NaCl




Fig. 11 Noise resistance of the painted panels, as a function of time, in 0.5 mol/L NaCl

that the corrosion process was inhibited. As was mentioned before, the electrochemical active area was small ($\sim 3 \times 10^{-8}$ – 4×10^{-8} cm²) and most of the surface was blocked by the coating. It is also possible that the kinetics and the reaction mechanism at the bottom of the pores and fissures contacting the metal base could be influenced by the formation of a corrosion products layer coupled with diffusion mechanisms through this layer^[27]. Paints L which contained inhibitive substances presented R_n values slightly higher, especially at long exposure times.

3 Conclusions

The protective behavior of La(III) towards galvanized steel, at room temperature, did not depend on the concentration of the salt nor on the immersion time in NaCl solution when the concentration was comprised between 6.6×10^{-5} and 4.0×10^{-4} mol/L. Increasing La(III) concentration by two orders of magnitude diminished i_{corr} only a little bit more. In brief, not much was gained with rather high concentration of La(III).

All the paints containing La exchanged zeolite protected galvanized steel in a satisfactory way, indicating that zinc phosphate content could be partially replaced by the modified zeolite. In addition, the protection of the substrate was achieved with very small amounts of lanthanum which allowed to replace important volumes of zinc phosphate in paint formulation.

It was also clear that La-exchanged zeolite introduced upgrade in the corrosion resistance of the epoxy paints.

Two thirds of the zinc phosphate content might be replaced by exchanged zeolite or by exchanged zeolite+ exchanged clay, without impairing paint performance.

Electrochemical tests supported the results obtained in the salt spray chamber.

Paint performance was improved incorporating zeolites and clays exchanged with passivating ions in epoxy paints.

Acknowledgements: The authors thanks to POLIDUR S.A. for providing the alkyd resin and Gonzalo Selmi for his technical support.

References:

- Odum E P. Ecología. Edited Nueva Editorial Interamericana, México DF, 1972, 117.
- [2] Mc Grath J W, Quinn J P. Phosphate removal: a novel approach, Edited by Queen's University, Belfast, www.qub.ac.uk/envres/EarthAirwater/phosphate-removal. htm.
- [3] Hare C. Extender pigments, Anatomy of paints, JPCL, 1990, 7(6): 43.
- [4] Hare C H. Synergistic effects of wollastonite/inhibitor concentrations in epoxy metal primers. *Journal of Protec*tive Coatings and Linings, 1989, 6(9): 43.
- [5] El-Sawy S. Egyptian kaolin as a filler and extender pigment for anticorrosive paints. *Corrosion Prevention & Control*, 1994, (April): 31.
- [6] Yeh J M, Liou S J, Lin C Y, Cheng C Y, Chang Y W, Lee K R. Anticorrosively enhance PMMA-clay nanocomposite materials with quaternary alkylphosphonium salt as an intercalating agent. *Chem. Mater.*, 2002, 14: 154.
- [7] Yeh J M, Liou S J, Lay C Y, Wu P C, Tsai T Y. Enhancement of corrosion protection effect in polyaniline via the formation of polyaniline-clay nanocomposite materials. *Chem. Mater.*, 2001, 13: 1131.
- [8] Trinh A T, To T X H, Vu K O, Dantras E, Lacabanne C,

- Oquab D, Pèbère N. Incorporation of an indole-3-butyric acid modified clay in epoxy resin for corrosion protection of carbon steel. *Surf. Coat. Techn.*, 2008, **202**(20): 4945.
- [9] Bohm S, McMurray H N, Powell S M, Worsley D A. Novel environment friendly corrosion inhibitor pigments based on naturally occurring clay minerals. *Materials and Corrosion*, 2001, 52(12): 896.
- [10] Kesavan D, Gopiraman M, Sulochana N. Green inhibitors for corrosion of metals: a review. *Chem. Sci. Rev. Lett.*, 2012, 1(1): 1.
- [11] Bethencourt M, Botana F, Calvino J, Marcos M, Rodriguez-Chacon M A. Lanthanide compounds as environmentally-friendly corrosion inhibitors of aluminium alloys: A review. *Corr. Sci.*, 1998, 40: 1803.
- [12] Barer R M. Zeolites and Clay Minerals as Sorbent and Molecular Sieves. New York; Academic Press, 1987, 221.
- [13] Bernal S, Botana F J, Calvino J J, Marcos M, Pérez-Omil J A, Vidal H. Lanthanide salts as alternative corrosion inhibitors. J. Alloys Compd., 1995, 225: 638.
- [14] Breck D W. Crystalline molecular sieves. J. Chem. Edu., 1964, 41: 678.
- [15] Deya C, Romagnoli R, del Amo B. A new pigment for smart anticorrosive coatings. J. Coat. Technol. Res., 2007, 4(2): 167.
- [16] Benthone®107, technical sheet, http://www.specialchem4 polymers.com/product-directory/ fillers_0_10079/index. aspx?did=0>
- [17] Welcher F J. Organic Analytical Reagents, Volume I. New York USA: D. Van Nostrand Company Inc, 1948. 311.
- [18] Simões A M P, Carbonari R O, Di Sarli A R, del Amo B, Romagnoli R. An environmentally acceptable primer for galvanized steel: formulation and evaluation by SVET. *Corr. Sci.*, 2011, 53: 464.
- [19] Reichert D. Electrochemical noise measurements for determining corrosion rates. In: Kearns J R, Scully J R, Roberge P R, Reichert D L, Dawson J L, ed. Electrochemical Noise Measurements for Corrosion Applications.

- 1996. 79.
- [20] Cottis R A. Interpretation of electrochemical noise data. Corrosion, 2001, 57(3): 265.
- [21] Huet F. The electrochemical noise technique. In: P. Marcus, F. Mansfeld, ed. Analytical Methods in Corrosion Science and Engineering, CRC Taylor & Francis, 2005. 507.
- [22] Mabbutt S, Mills D J, Woodcock C P. Developments of the electrochemical noise method (ENM) for more practical assessment of anti-corrosion coatings. *Progress in Or*ganic Coatings, 2007, 59: 192.
- [23] Tan Y J, Bailey S, Kinsella B. The monitoring of the formation and destruction of corrosion inhibitor films using electrochemical noise analysis (ENA). Corr. Sci., 1996, 38: 1681.
- [24] Milán Z, Montalvo S, Ilangovan K, Monroy O, Chamy R, Weiland P, Sánchez E, Borja R. The impact of ammonia nitrogen concentration and zeolite addition on the specific methanogenic activity of granular and flocculent anaerobic sludges. *J Environ Sci Health A Tox Hazard Subst Environ* Eng, 2010, 45(7): 883.
- [25] Carballo F. The zeolitas in Ecuador coast (Guayaquil) geology, characterization and applications. Universidad Politécnica de Madrid, 1-400, 2004.
- [26] Gerhard A, Bittner A. Second generation phosphate anticorrosive pigments. Formulating rules for full replacement of new anti-corrosive pigments. *J. Coat. Technol.*, 1986, 58(740): 59.
- [27] Bittner A. Advanced phosphate anticorrosive pigments for compliant primers. J. Coat. Technol., 1989, 61(777): 114.
- [28] Szauer T. Impedance measurements for the evaluation of protective nonmetallic coatings. *Prog. Org. Coat.*, 1982, 10: 171
- [29] Hernandez M, Genescá J, Uruchurtu J, Barba A. Correlation between electrochemical impedance and noise measurements of waterborne coatings. *Corr. Sci.*, 2009, 51: 499.