

Film Calibration Report

Film infos:

Author: JFC Unit: Salle 2 Film lot: C2

Scanner ID: Epson 72000XL Date exposed: 2019/03/07 Date scanned: 2019/03/08 Wait time: 24 heures

Calibration options:

Images path: .\DemoReflexionLatCorr\Calibration


Nominal doses: [0.0, 25.0, 50.0, 100.0, 150.0, 200.0, 250.0, 300.0, 400.0, 800.0]

Output factor:

Scanner lateral response correction applied: True

Beam profile correction applied: .\DemoReflexionLatCorr\Calibration\ICProfiler 9MeV 25x25 1,9cm.txt

Median filter kernel size: 0



Notes:

Scan en réflexion.