

Film Calibration Report

Film infos:

Author: JFC Unit: Salle 4 Film lot: C9-XD

Scanner ID: Epson 72000XL Date exposed: 2019/11/12 17h Date scanned: 2019/11/13 11h

Wait time: 18 heures


Calibration options:

Images path: .\DemoCalibrationTransmissionNoLatCorr

Nominal doses: [0.0, 78.7, 236.1, 472.2, 787.0, 1180.5, 1653.5, 2204.4, 2834.0]

Scanner lateral response correction applied: False Beam profile correction applied: None

Median filter kernel size: 0



Notes:

Scan en transmission avec la vitre.