Car PDI Masters

SAMPLE REPORT

CPM-SAMPLE-001

INDEPENDENT · CAR INSPECTION

Comprehensive Car Inspection Report

- **Photo evidence**
  Photos of this car for every key checkpoint
- **Weighted condition checks**
  Category-wise ratings
- **Deal-breakers checked**
  Structure, water damage, engine, brakes
- **Doorstep inspection**
  Inspected on site in Delhi



Mahindra XUV 7XO AX7L

March 2026 · AMT · Petrol · Blue

Inspection location	Delhi
Inspected on	01 Oct 2026
Odometer	3,224 km
Report type	Comprehensive car inspection

4.9
OUT OF 5

EXCELLENT

Book your inspection ›
www.carmasters.co.in · +91 99711 16411

SAMPLE REPORT · Sample report: a real inspection with personal and vehicle identifiers hidden.

INSIDE THIS REPORT

Content of report

01 **Your report at a glance**
Overall rating and vehicle details

02 **Key checks & inspection summary**
Deal-breakers and category ratings

03 **Vehicle images**
Reference photos of the car

04 **Detailed evaluation of each category**
1. Exterior & Tyres
2. Electricals & Interiors
3. Engine & Transmission
4. Steering, Suspension & Brakes
5. Air Conditioning
6. Other details

05 **Features verified on this car**
Feature checks and their results

How to read this report

Perfect
Checked and found in order

Imperfect
Needs attention: cosmetic or severe

N/A
Not applicable to this vehicle; not rated

A camera mark next to a parameter means a photo of it is included in this report.

About this sample. This is a real inspection report of a privately owned car, published with the owner's permission. Number plates, the chassis number, the booking reference, the inspector and the exact address have been hidden; every checkpoint, rating and finding is unchanged.

01 · OVERVIEW

Your report at a glance

Mahindra XUV 7XO · Blue



Mahindra XUV 7XO

AX7L · March 2026 · AMT · Petrol

4.9
EXCELLENT

ODOMETER	MANUFACTURED	OVERALL RATING
3,224 km	March 2026	4.9 / 5

3 ITEMS NEED ATTENTION
1 severe, 2 cosmetic


Chassis embossing	Waterlogged	Duplicate key available?
OK	No	No

Health report summary

No structural damage was recorded: all pillars, aprons, apron legs, the firewall, cowl top and roof are OK, the car is not waterlogged, it is in running condition, the engine showed no blow-by at idle or 2000 RPM, no abnormal engine sound. Electricals & Interiors, Engine & Transmission, Steering, Suspension & Brakes and Air Conditioning passed every check. 3 items need attention (1 severe, 2 cosmetic), listed below.

- COSMETIC **Rear Bumper** – Scratch
- SEVERE **LHS Tail Light** – Broken
- COSMETIC **RHS Running Board** – Scratch

WHERE TO LOOK



1. Rear Bumper – scratch (cosmetic)
2. LHS Tail Light – broken (severe)
3. RHS Running Board – scratch (cosmetic)

Vehicle & booking details

Booking ID: CPM-SAMPLE-001	Vehicle condition: Used	Make: Mahindra
Model: XUV 7XO	Variant: AX7L	Manufactured: March 2026
Fuel type: Petrol	Transmission: AMT	Emission: BS-VI (Phase 2)
Colour: Blue	Inspection at: Doorstep	City: Delhi
Inspector: Hidden	Inspected on: 01 Oct 2026	Odometer: 3,224 km

02 · KEY CHECKS

Key checks

Deal-breakers checked on every car

Chassis embossing OK	Water damage Not waterlogged	Running condition Yes	Structural damage None found
Engine blow-by None	Brakes & ABS OK	Tyre life 80% or more	Duplicate key available? No

Inspection summary

Category-wise ratings

Exterior & Tyres
3 items need attention: Rear Bumper (Scratch), LHS Tail Light (Broken), RHS Running Board (Scratch).

4.7
/5 · EXCELLENT

Electricals & Interiors
All checked parameters passed inspection.

5.0
/5 · EXCELLENT

Engine & Transmission
All checked parameters passed inspection.

5.0
/5 · EXCELLENT

Steering, Suspension & Brakes
All checked parameters passed inspection.

5.0
/5 · EXCELLENT

Air Conditioning
All checked parameters passed inspection.

5.0
/5 · EXCELLENT

03 · GALLERY


Vehicle images



Front of car



Rear of car


LHS Front Side


LHS Side


LHS Rear Side



RHS Rear Side


RHS Front Side



Roof



Open Dikki


Boot Floor Inside


Engine Compartment


Interior Front


Interior Center


Interior Left

CATEGORY 01

Exterior & Tyres

Perfect parts: 42 · Imperfect parts: 03

Structure 5.0 | Body, Glass & Lights 4.3 | Tyres & Wheels 5.0

4.7
EXCELLENT

Front

PARAMETERS	PERFECT	IMPERFECT
Front Windshield	✓	
Wiper	✓	
Front Bumper	✓	
Front Grille	✓	
Bonnet Hood	✓	
LHS Headlight	✓	
RHS Headlight	✓	
LHS Fog Lamp	✓	
RHS Fog Lamp	✓	
LHS Apron	✓	
LHS Apron Leg	✓	
RHS Apron	✓	
RHS Apron Leg	✓	
Cowl Top	✓	
Firewall	✓	

Left side (LHS)

PARAMETERS	PERFECT	IMPERFECT
LHS Fender	✓	
Alloy Wheel	✓	
LHS ORVM	✓	
LHS Front Tyre — 90% life	✓	
LHS Front Door	✓	
LHS A Pillar	✓	

PARAMETERS	PERFECT	IMPERFECT
LHS B Pillar	✓	
LHS Rear Door	✓	
LHS C Pillar	✓	
LHS Rear Tyre — 80% life	✓	
LHS Quarter Panel	✓	
LHS Running Board	✓	
Roof Photo	✓	

Rear

PARAMETERS	PERFECT	IMPERFECT
Rear Boot Door (Dikki)	✓	
Rear Bumper — COSMETIC — Scratch		!
Rear Windshield	✓	
LHS Tail Light — SEVERE — Broken		!
RHS Tail Light	✓	
Spare Tyre	✓	
Is The Car Waterlogged?	✓ No	
Tolls Available	✓ Yes	

Right side (RHS)

PARAMETERS	PERFECT	IMPERFECT
RHS Quarter Panel	✓	
RHS Rear Tyre — 80% life	✓	
RHS Rear Door	✓	
RHS C Pillar	✓	
RHS B Pillar	✓	
RHS Running Board — COSMETIC — Scratch		!

PARAMETERS	PERFECT	IMPERFECT
RHS Front Gate	✓	
RHS A Pillar	✓	
RHS Fender	✓	
RHS Front Tyre — 80% life	✓	
RHS ORVM	✓	

Tyre life



90%

LHS Front tyre
90% life remaining



80%

LHS Rear tyre
80% life remaining



80%

RHS Rear tyre
80% life remaining



80%

RHS Front tyre
80% life remaining

Exterior & Tyres – imperfect parts



Rear Bumper: Scratch




LHS Tail Light: Broken



RHS Running Board: Scratch

Inspection photos 39


Front Windshield


Front Bumper


LHS Headlight


RHS Headlight


LHS Fog Lamp


RHS Fog Lamp


LHS Apron


LHS Apron Leg


RHS Apron


RHS Apron Leg


LHS Front Side


LHS Side


Alloy Wheel


LHS ORVM



LHS Front Tyre


LHS Front Door


LHS A Pillar


LHS B Pillar



LHS Rear Door


LHS C Pillar


LHS Rear Tyre


LHS Rear Side



Roof


Rear Windshield


RHS Tail Light


Open Dikki


Boot Floor Inside



Spare Tyre



Tolls Available


RHS Rear Side



RHS Rear Tyre


RHS Rear Door



RHS C Pillar


RHS B Pillar


RHS Front Gate


RHS A Pillar


RHS Front Tyre


RHS ORVM


RHS Front Side

CATEGORY 02

Electricals & Interiors

Perfect parts: 26 · Imperfect parts: 00 · Not applicable (N/A): 02

5.0
EXCELLENT

PARAMETERS	PERFECT	IMPERFECT
No. Of Power Windows	✓ 4	
Power Windows Front RHS	✓	
Power Windows Front LHS	✓	
Power Windows Rear RHS	✓	
Power Windows Rear LHS	✓	
Drive Safety Door Panel Control	✓	
Wiring	✓	
Cruise Control	✓ Working	
Speedo Meter	✓ Working	
Dashboard	✓	
Electrical/Instrument Cluster	✓	
No. Of Air Bags	✓ 12	
Music System	✓	
Navigation System	N/A	
Leather Seat	✓	
Fabric Seats	N/A	
Ventilated Seat	✓ Working	
Keyless Start	✓ Yes	
Sunroof/ Moonroof	✓	
Steering Mounted Controls	✓	
ABS	✓	
Rear Defogger	✓ Working	
Reverse Camera	✓	
360 Camera	✓	
Odometer Reading (Kms)	✓ 3224 km	
Fuel Level	✓ More than 50%	

PARAMETERS	PERFECT	IMPERFECT
Parking Sensor	✓	
Front Armrest	✓	
Rear Armrest	✓	
Front LHS Door Inner	✓	
Front RHS Door Inner	✓	
Rear LHS Door Inner	✓	
Rear RHS Door Inner	✓	


Inspection photos 17


Drive Safety Door Panel Control


Cruise Control


Speedo Meter


Dashboard


Music System


Leather Seat




Keyless Start


Sunroof/ Moonroof


Steering Mounted Controls


Reverse Camera


360 Camera


Odometer Reading (Kms)


Front Armrest


Rear Armrest


Interior Front


Interior Center


Interior Left

CATEGORY 03

Engine & Transmission

Perfect parts: 18 · Imperfect parts: 00 · Not applicable (N/A): 01

5.0
EXCELLENT

PARAMETERS	PERFECT	IMPERFECT
Engine Oil	✓	
Engine Oil Level (Dipstick)	✓	
Coolant	✓	
Radiator	✓	
Engine Mounting	✓	
Fuel Injector	✓	
Air Filter	✓	
Turbo Charger	✓	
Clutch	N/A	
Gear Shifting	✓	
Battery & Alternator	✓	
Start Motor	✓	
Engine Normal	✓	
Exhaust Smoke	✓	
RPM Fluctuations	✓	
Silencer	✓	
Engine Blow-By Normal To Idle	✓ No Blow-by	
Engine Blow-by At 2000 RPM	✓ No Blow-by	
Any Abnormal Sound	✓ No Abnormal Sound	
Is The Car in Running Condition	✓ Yes	

Inspection photos 4


Engine Compartment


Engine Compartment (Side)


Gear Shifting


Battery & Alternator

CATEGORY 04

Steering, Suspension & Brakes

Perfect parts: 08 · Imperfect parts: 00

5.0
EXCELLENT

PARAMETERS	PERFECT	IMPERFECT
Steering	Normal	
Suspension	✓	
Brake	✓	
Hand Brake	✓	
Front Left Shocker	✓	
Front Right Shocker	✓	
Rear Left Shocker	✓	
Rear Right Shocker	✓	

Inspection photos 2



Steering



Hand Brake

CATEGORY 05

Air Conditioning

Perfect parts: 06 · Imperfect parts: 00

5.0
EXCELLENT

PARAMETERS	PERFECT	IMPERFECT
Ac Switch	Working	
Ac Cooling		
Heater		
Climate Control	Working	
Ac Vent Front		
Ac Vent Rear		

Inspection photos 5


Ac Switch


Ac Vent Right


Ac Vent Center


Ac Vent Left


Ac Vent Rear

CATEGORY 06

Other details

Available: 04 · Not available: 01

PARAMETERS	AVAILABLE	NOT AVAILABLE
Chassis Embossing	OK	
Duplicate Key available?		No
Tool Kit	Yes	
Keyless Start	Yes	
Inspector Verification Photo	Captured	



Chassis embossing: OK (number hidden)



Tool kit



Keyless start

CHASSIS VERIFICATION

Chassis number hidden in this sample

First characters	Hidden
Last characters	Hidden
Embossing	OK

INSPECTION LOCATION

Delhi

Inspection at	Doorstep
Fuel level	More than 50%
Odometer	3,224 km

05 · FEATURES

Features verified on this car

As recorded during the inspection

POWER WINDOWS	AIRBAGS	KEYLESS START
4	12	Yes

Safety

- **ABS** — Checked, working
- **Fog lamps** — Checked, working
- **Parking sensors** — Checked, working
- **Reverse camera** — Checked, working
- **360° camera** — Checked, working
- **Rear defogger** — Checked, working

Comfort & convenience

- **Sunroof** — Checked, working
- **Ventilated seats** — Checked, working
- **Leather seats** — Checked, working
- **Fabric seats** — Not applicable (N/A)
- **Climate control** — Checked, working
- **Cruise control** — Checked, working
- **Rear AC vents** — Checked, working
- **Front armrest** — Checked, working
- **Rear armrest** — Checked, working

Infotainment

- **Music system** — Checked, working
- **Navigation** — Not applicable (N/A)
- **Steering mounted controls** — Checked, working

Exterior

- **Alloy wheels** — Checked, working
- **Spare tyre** — Checked, working

CAR PDI MASTERS

Get this report for your car

This sample shows the format of a Car PDI Masters inspection report: every category rated, photos of the key checkpoints and a clear list of anything that needs attention. To book an inspection or ask about this sample, call 99711 16411 or visit www.carmasters.co.in.

Services by Car PDI Masters

New Car PDI | New Car Inspection | Used Car Inspection | Pre-Purchase Inspection | 360° Inspection | Luxury Car PDI | EV Car PDI

Car PDI Masters
+91 99711 16411
www.carmasters.co.in
Book an Inspection ›

Disclaimer: This inspection is a visual and functional assessment carried out without dismantling any component, to the best of the inspector's ability at the time of inspection on 01 Oct 2026. Items marked N/A (not applicable) did not apply to this vehicle's inspection and are left out of its rating; N/A does not mean the item is missing. Findings reflect the condition observed during inspection and are not a warranty or guarantee of future performance. Hidden or internal components that cannot reasonably be accessed are not covered. SAMPLE REPORT: a real inspection with personal and vehicle identifiers hidden. Number plates, the chassis number, people in photos, the booking reference, the inspector and the exact address have been masked; the inspection videos are not included.