

TEST REPORT

APPLICANT : ZHUHAI KELITONG ELECTRONIC CO.,LTD.

ADDRESS : YONGAN SECOND ROAD, LIANGANG INDUSTRY ZONE,
JINWAN DISTRICT, ZHUHAI CITY, GUANGDONG
PROVINCE ,CHINA 519090

SAMPLE DESCRIPTION : VACUUM CONTAINER WITH ELECTRIC VACUUM PUMP,
AUTOMATIC WINE VACUUM SEALER

ITEM NO. : KVS-21-X,KVS-21A, KVS-21-B, KVS-21A,KVS-21-B1, KVS-21-
B2, KV-001,CJ-VSTXX("XX" CANBE:01-99),KZ-YYY("YYY"
CAN BE:001-099),KVS-21-Y("Y CAN BE X1...X99), KVS-X("X"
CAN BE 1-99), CJ-VST04,CJ-VST02, CJ-VSP01
KVS-21-X1,KVS-21-X2,KVS-21A,KVS-21-A1, KVS-21-A2.

AGE REQUESTED ON APPLICATION FORM : NOT PRESENT

SAMPLE RECEIVED DATE : 25-Jul-2024; 07-Aug-2024; 13-Aug-2024

TEST PERIOD : 26-Jul-2024 to 20-Aug-2024

The following test item(s) was/were performed on submitted sample(s) and/or component(s) confirmed by applicant

TEST REQUESTED	RESULT
RoHS Directive 2011/65/EU and its amendment Directive (EU) 2015/863.	PASS

The above sample(s) and sample information was/were submitted and identified on behalf of the applicant. Eurofins will not be liable for the authenticity of the information. This test report is valid for the tested sample only. Without permission of the test center this test report is not permitted to be duplicated in extracts.

Unless otherwise required by the applicant or method/regulation, decision rule in this report did not consider the measurement uncertainty.

***** FOR FURTHER DETAILS, PLEASE REFER TO THE FOLLOWING PAGE(S) *****


SIGNED FOR AND ON BEHALF OF
EUROFINS TESTING TECHNOLOGY (SHENZHEN) CO., LTD.







Coco Luo
Senior Lab Manager



Harry Chen
Senior R&D Manager

TESTED SAMPLE PHOTO(S)**EFSN24071922-C-0101**

TESTED SAMPLE PHOTO(S)

	
Material No. 1-5	Material No. 6-13
	
Material No. 14-22	Material No. 23-25
	
Material No. 26-31	Material No. 32-40



EFSN24071922-C-0101

TO BE CONTINUED

Eurofins Testing Technology (Shenzhen) Co., Ltd.

4/F., Building 3, Building 2, Runheng Electronic Park, Liuxian 2nd Road, Xin'an Street, Bao'an District, Shenzhen, Guangdong, China
Tel.: +86 755 8358 5700 • Fax: +86 755 8358 5701 • Email: Info.HK@cpt.eurofinscn.com • Website: www.eurofins.com / www.pt.eurofins.com

TESTED SAMPLE PHOTO(S)

	
Material No. 41-45	Material No. 46-51
	
Material No. 52-59	Material No. 60-72
	
Material No. 73-77	Material No. 78-82

EFSN24071922-C-0101

TO BE CONTINUED

TESTED SAMPLE PHOTO(S)

	
Material No. 83-90	Material No. 91,92
	
Material No. 93,94	

EFSN24071922-C-0101

TO BE CONTINUED

COMPONENT LIST

Component No.	Component	Sample No.
1	White plastic hull of main body	A
2	Red plastic holder ring of button	A
3	Translucent white plastic button with white coating	A
4	Transparent plastic/glue sticker with black printing on main body	A
5	Red soft plastic ring on main body	A
6	Black plastic inner frame of main body	A
7	Dull silvery metal screw	A
8	Translucent soft plastic hose	A
9	Silvery metal spring inside of hose	A
10	Black foam/glue sticker	A
11	White plastic fixture of water pump	A
12	Silvery metal spring of water pump	A
13	Translucent blue plastic water pump	A
14	White soft plastic flat wire jacket with pink printing-2 nd submission	A
15	Silvery metal core wire	A
16	White plastic wire connector	A
17	Silvery metal clamp of wire connector	A
18	Green PCB of type-c socket (plastic/printing/metal)	A
19	Brown chip capacitor on PCB (ceramic/metal)	A
20	Black chip resistor on PCB (ceramic/metal)	A
21	Black U1 on PCB (ceramic/metal)	A
22	Black TVS1 on PCB (ceramic/metal)	A
23	Silvery metal hull of type-c socket	A
24	Black plastic plate of type-c socket	A
25	Silvery metal pin of type-c socket	A
26	Orange soft plastic thin wire jacket	A
27	Black soft plastic thin wire jacket	A
28	Green PCB of microswitch (plastic/printing/metal)	A
29	Silvery metal cover of microswitch	A
30	Black plastic head and frame of microswitch	A
31	Silvery metal pin of microswitch	A
32	Red soft plastic thin wire jacket	A
33	Green main PCB (plastic/printing/metal)	A
34	Silvery metal pin of wire connector	A
35	Black U4 on PCB (ceramic/metal)	A
36	Black U3 on PCB (ceramic/metal)	A
37	Black MOS on PCB (ceramic/metal)	A
38	Black D1,D2 on PCB (ceramic/metal)	A
39	Black U0 on PCB (ceramic/metal)	A
40	Black Q1 on PCB (ceramic/metal)	A
41	Multi-color plastic of buzzer on PCB	A
42	Black metal magnet of buzzer on PCB	A
43	Silvery metal chip of buzzer on PCB	A
44	Silvery metal base of buzzer on PCB	A
45	Copper metal coil of buzzer on PCB	A
46	Silvery metal soldering tin	A
47	Transparent plastic LED on PCB	A
48	Silvery metal pin of LED on PCB	A

TO BE CONTINUED

Component No.	Component	Sample No.
49	Golden metal head of KEY1 on PCB	A
50	Silvery metal cover of KEY1 on PCB	A
51	Silvery metal pin of KEY1 on PCB	A
52	Silvery metal long screw on water pump	A
53	Silvery metal washer on long screw	A
54	Beige plastic frame of water pump	A
55	Black soft plastic cover and stopper of water pump	A
56	Grey plastic fixture of water pump	A
57	Silvery metal axis of water pump	A
58	Silvery metal short screw on water pump	A
59	Green plastic cap of water pump	A
60	Multi-color plastic of motor cover and motor axis	A
61	Silvery metal cover of motor	A
62	Silvery metal brush of motor cover	A
63	Silvery metal pin of motor cover	A
64	Golden metal ring of motor cover and motor hull	A
65	Silvery metal hull of motor	A
66	Black soft plastic magnet of motor hull	A
67	Silvery metal axis of motor	A
68	Silvery metal tube plate of motor axis	A
69	Black and silvery ceramic ring of motor axis	A
70	Red paper ring of motor axis	A
71	Silvery metal frame of motor axis	A
72	Copper metal coil of motor axis	A
73	Black soft plastic thick wire jacket of battery	A
74	Red soft plastic thick wire jacket of battery	A
75	Transparent yellow plastic/glue tape on battery	A
76	Green PCB of battery (plastic/printing/metal)	A
77	Black IC on PCB of battery (ceramic/metal)	A
78	White soft plastic plug	A
79	White soft plastic cable jacket	A
80	Silvery metal hull of USB plug	A
81	White plastic plate of USB plug	A
82	Silvery metal pin of USB plug	A
83	Silvery metal hull of type-c plug	A
84	Silvery metal frame of type-c plug	A
85	Black plastic plate of type-c plug	A
86	Silvery metal pin of type-c plug	A
87	Blue PCB of type-c plug of white cable (plastic/printing/metal)	A
88	Black soft plastic wire jacket inside of cable	A
89	Red soft plastic wire jacket inside of cable	A
90	Copper metal core wire	A
91	Black soft plastic plug	A
92	Black soft plastic cable jacket	A
93	Translucent plastic block inside of plug	A
94	Blue PCB of type-c plug of black cable (plastic/printing/metal)	A

TO BE CONTINUED

TEST RESULT

RoHS

Test Method : (1) Screening by XRF Spectroscopy:
IEC 62321-3-1: 2013, Lead, Mercury, Cadmium, total Chromium and total Bromine by X-ray fluorescence spectrometry

(2) Wet Chemical test:
Cadmium, Lead: IEC 62321-5: 2013, determined by ICP-OES.
Mercury: IEC 62321-4: 2013/AMD1: 2017, determined by ICP-OES.
Chromium (VI): IEC 62321-7-1: 2015 and IEC 62321-7-2: 2017, determined by UV/VIS.
PBBs & PBDEs: IEC 62321-6: 2015, determined by GC-MS.

(3) DBP, BBP, DEHP and DiBP: IEC 62321-8:2017

Test Result :

Test No.	Material No.	XRF Results (mg/kg) (1)		Screening Results of PHTH (mg/kg) (2)	Wet Chemical Confirmation Result (mg/kg) (3)
1	1	Cd	BL	--	--
		Pb	BL	--	--
		Hg	BL	--	--
		Cr(VI)	BL	--	--
		PBBs	BL	--	--
		PBDEs	BL	--	--
		DBP	--	BL	--
		BBP	--	BL	--
		DEHP	--	BL	--
		DiBP	--	BL	--
2	2	Cd	BL	--	--
		Pb	BL	--	--
		Hg	BL	--	--
		Cr(VI)	BL	--	--
		PBBs	BL	--	--
		PBDEs	BL	--	--
		DBP	--	BL	--
		BBP	--	BL	--
		DEHP	--	BL	--
		DiBP	--	BL	--

TO BE CONTINUED

Eurofins Testing Technology (Shenzhen) Co., Ltd.

4/F., Building 3, Building 2, Runheng Electronic Park, Liuxian 2nd Road, Xin'an Street, Bao'an District, Shenzhen, Guangdong, China
Tel.: +86 755 8358 5700 • Fax: +86 755 8358 5701 • Email: Info.HK@cpt.eurofinscn.com • Website: www.eurofins.com / www.pt.eurofins.com

TEST RESULT

Test No.	Material No.	XRF Results (mg/kg) (1)		Screening Results of PHTH (mg/kg) (2)	Wet Chemical Confirmation Result (mg/kg) (3)
3	3	Cd	BL	--	--
		Pb	BL	--	--
		Hg	BL	--	--
		Cr(VI)	BL	--	--
		PBBs	BL	--	--
		PBDEs	BL	--	--
		DBP	--	BL	--
		BBP	--	BL	--
		DEHP	--	BL	--
		DiBP	--	BL	--
4	4	Cd	BL	--	--
		Pb	BL	--	--
		Hg	BL	--	--
		Cr(VI)	BL	--	--
		PBBs	BL	--	--
		PBDEs	BL	--	--
		DBP	--	BL	--
		BBP	--	BL	--
		DEHP	--	BL	--
		DiBP	--	BL	--
5	5	Cd	BL	--	--
		Pb	BL	--	--
		Hg	BL	--	--
		Cr(VI)	BL	--	--
		PBBs	BL	--	--
		PBDEs	BL	--	--
		DBP	--	IN	N.D.
		BBP	--	IN	N.D.
		DEHP	--	IN	N.D.
		DiBP	--	IN	N.D.
6	6	Cd	BL	--	--
		Pb	BL	--	--
		Hg	BL	--	--
		Cr(VI)	BL	--	--
		PBBs	BL	--	--
		PBDEs	BL	--	--
		DBP	--	BL	--
		BBP	--	BL	--
		DEHP	--	BL	--
		DiBP	--	BL	--

TO BE CONTINUED

Eurofins Testing Technology (Shenzhen) Co., Ltd.

4/F., Building 3, Building 2, Runheng Electronic Park, Liuxian 2nd Road, Xin'an Street, Bao'an District, Shenzhen, Guangdong, China
Tel.: +86 755 8358 5700 • Fax: +86 755 8358 5701 • Email: Info.HK@cpt.eurofinscn.com • Website: www.eurofins.com / www.pt.eurofins.com

TEST RESULT

Test No.	Material No.	XRF Results (mg/kg) (1)		Screening Results of PHTH (mg/kg) (2)	Wet Chemical Confirmation Result (mg/kg) (3)
7	7	Cd	BL	--	--
		Pb	BL	--	--
		Hg	BL	--	--
		Cr(VI)	IN	--	Negative
		PBBs	NA	--	--
		PBDEs	NA	--	--
		DBP	--	NA	--
		BBP	--	NA	--
		DEHP	--	NA	--
		DiBP	--	NA	--
8	8	Cd	BL	--	--
		Pb	BL	--	--
		Hg	BL	--	--
		Cr(VI)	BL	--	--
		PBBs	BL	--	--
		PBDEs	BL	--	--
		DBP	--	IN	N.D.
		BBP	--	IN	N.D.
		DEHP	--	IN	N.D.
		DiBP	--	IN	N.D.
9	9	Cd	BL	--	--
		Pb	BL	--	--
		Hg	BL	--	--
		Cr(VI)	IN	--	Negative
		PBBs	NA	--	--
		PBDEs	NA	--	--
		DBP	--	NA	--
		BBP	--	NA	--
		DEHP	--	NA	--
		DiBP	--	NA	--
10	10	Cd	BL	--	--
		Pb	BL	--	--
		Hg	BL	--	--
		Cr(VI)	BL	--	--
		PBBs	BL	--	--
		PBDEs	BL	--	--
		DBP	--	BL	--
		BBP	--	BL	--
		DEHP	--	BL	--
		DiBP	--	BL	--

TO BE CONTINUED

Eurofins Testing Technology (Shenzhen) Co., Ltd.

4/F., Building 3, Building 2, Runheng Electronic Park, Liuxian 2nd Road, Xin'an Street, Bao'an District, Shenzhen, Guangdong, China
Tel.: +86 755 8358 5700 • Fax: +86 755 8358 5701 • Email: Info.HK@cpt.eurofinscn.com • Website: www.eurofins.com / www.pt.eurofins.com

TEST RESULT

Test No.	Material No.	XRF Results (mg/kg) (1)		Screening Results of PHTH (mg/kg) (2)	Wet Chemical Confirmation Result (mg/kg) (3)
11	11	Cd	BL	--	--
		Pb	BL	--	--
		Hg	BL	--	--
		Cr(VI)	BL	--	--
		PBBs	BL	--	--
		PBDEs	BL	--	--
		DBP	--	BL	--
		BBP	--	BL	--
		DEHP	--	BL	--
		DiBP	--	BL	--
12	12	Cd	BL	--	--
		Pb	BL	--	--
		Hg	BL	--	--
		Cr(VI)	IN	--	Negative
		PBBs	NA	--	--
		PBDEs	NA	--	--
		DBP	--	NA	--
		BBP	--	NA	--
		DEHP	--	NA	--
		DiBP	--	NA	--
13	13	Cd	BL	--	--
		Pb	BL	--	--
		Hg	BL	--	--
		Cr(VI)	BL	--	--
		PBBs	BL	--	--
		PBDEs	BL	--	--
		DBP	--	BL	--
		BBP	--	BL	--
		DEHP	--	BL	--
		DiBP	--	BL	--
14	14	Cd	BL	--	--
		Pb	BL	--	--
		Hg	BL	--	--
		Cr(VI)	BL	--	--
		PBBs	BL	--	--
		PBDEs	BL	--	--
		DBP	--	IN	N.D.
		BBP	--	IN	N.D.
		DEHP	--	IN	58
		DiBP	--	IN	N.D.

TO BE CONTINUED

Eurofins Testing Technology (Shenzhen) Co., Ltd.

4/F., Building 3, Building 2, Runheng Electronic Park, Liuxian 2nd Road, Xin'an Street, Bao'an District, Shenzhen, Guangdong, China
Tel.: +86 755 8358 5700 • Fax: +86 755 8358 5701 • Email: Info.HK@cpt.eurofinscn.com • Website: www.eurofins.com / www.pt.eurofins.com

TEST RESULT

Test No.	Material No.	XRF Results (mg/kg) (1)		Screening Results of PHTH (mg/kg) (2)	Wet Chemical Confirmation Result (mg/kg) (3)
15	15	Cd	BL	--	--
		Pb	BL	--	--
		Hg	BL	--	--
		Cr(VI)	BL	--	--
		PBBs	NA	--	--
		PBDEs	NA	--	--
		DBP	--	NA	--
		BBP	--	NA	--
		DEHP	--	NA	--
		DiBP	--	NA	--
16	16	Cd	BL	--	--
		Pb	BL	--	--
		Hg	BL	--	--
		Cr(VI)	BL	--	--
		PBBs	BL	--	--
		PBDEs	BL	--	--
		DBP	--	BL	--
		BBP	--	BL	--
		DEHP	--	BL	--
		DiBP	--	BL	--
17	17	Cd	BL	--	--
		Pb	BL	--	--
		Hg	BL	--	--
		Cr(VI)	BL	--	--
		PBBs	NA	--	--
		PBDEs	NA	--	--
		DBP	--	NA	--
		BBP	--	NA	--
		DEHP	--	NA	--
		DiBP	--	NA	--
18	18	Cd	BL	--	--
		Pb	BL	--	--
		Hg	BL	--	--
		Cr(VI)	BL	--	--
		PBBs	IN	--	N.D.
		PBDEs	IN	--	N.D.
		DBP	--	BL	--
		BBP	--	BL	--
		DEHP	--	BL	--
		DiBP	--	BL	--

TO BE CONTINUED

Eurofins Testing Technology (Shenzhen) Co., Ltd.

4/F., Building 3, Building 2, Runheng Electronic Park, Liuxian 2nd Road, Xin'an Street, Bao'an District, Shenzhen, Guangdong, China
Tel.: +86 755 8358 5700 • Fax: +86 755 8358 5701 • Email: Info.HK@cpt.eurofinscn.com • Website: www.eurofins.com / www.pt.eurofins.com

TEST RESULT

Test No.	Material No.	XRF Results (mg/kg) (1)		Screening Results of PHTH (mg/kg) (2)	Wet Chemical Confirmation Result (mg/kg) (3)
19	19	Cd	BL	--	--
		Pb	BL	--	--
		Hg	BL	--	--
		Cr(VI)	BL	--	--
		PBBs	NA	--	--
		PBDEs	NA	--	--
		DBP	--	NA	--
		BBP	--	NA	--
		DEHP	--	NA	--
		DiBP	--	NA	--
20	20	Cd	BL	--	--
		Pb	BL	--	--
		Hg	BL	--	--
		Cr(VI)	BL	--	--
		PBBs	NA	--	--
		PBDEs	NA	--	--
		DBP	--	NA	--
		BBP	--	NA	--
		DEHP	--	NA	--
		DiBP	--	NA	--
21	21	Cd	BL	--	--
		Pb	BL	--	--
		Hg	BL	--	--
		Cr(VI)	BL	--	--
		PBBs	NA	--	--
		PBDEs	NA	--	--
		DBP	--	NA	--
		BBP	--	NA	--
		DEHP	--	NA	--
		DiBP	--	NA	--
22	22	Cd	BL	--	--
		Pb	BL	--	--
		Hg	BL	--	--
		Cr(VI)	BL	--	--
		PBBs	NA	--	--
		PBDEs	NA	--	--
		DBP	--	NA	--
		BBP	--	NA	--
		DEHP	--	NA	--
		DiBP	--	NA	--

TO BE CONTINUED

Eurofins Testing Technology (Shenzhen) Co., Ltd.

4/F., Building 3, Building 2, Runheng Electronic Park, Liuxian 2nd Road, Xin'an Street, Bao'an District, Shenzhen, Guangdong, China
Tel.: +86 755 8358 5700 • Fax: +86 755 8358 5701 • Email: Info.HK@cpt.eurofinscn.com • Website: www.eurofins.com / www.pt.eurofins.com

TEST RESULT

Test No.	Material No.	XRF Results (mg/kg) (1)		Screening Results of PHTH (mg/kg) (2)	Wet Chemical Confirmation Result (mg/kg) (3)
23	23	Cd	BL	--	--
		Pb	BL	--	--
		Hg	BL	--	--
		Cr(VI)	IN	--	Negative
		PBBs	NA	--	--
		PBDEs	NA	--	--
		DBP	--	NA	--
		BBP	--	NA	--
		DEHP	--	NA	--
		DiBP	--	NA	--
24	24	Cd	BL	--	--
		Pb	BL	--	--
		Hg	BL	--	--
		Cr(VI)	BL	--	--
		PBBs	BL	--	--
		PBDEs	BL	--	--
		DBP	--	BL	--
		BBP	--	BL	--
		DEHP	--	BL	--
		DiBP	--	BL	--
25	25	Cd	BL	--	--
		Pb	BL	--	--
		Hg	BL	--	--
		Cr(VI)	BL	--	--
		PBBs	NA	--	--
		PBDEs	NA	--	--
		DBP	--	NA	--
		BBP	--	NA	--
		DEHP	--	NA	--
		DiBP	--	NA	--
26	26	Cd	BL	--	--
		Pb	BL	--	--
		Hg	BL	--	--
		Cr(VI)	BL	--	--
		PBBs	BL	--	--
		PBDEs	BL	--	--
		DBP	--	BL	--
		BBP	--	BL	--
		DEHP	--	BL	--
		DiBP	--	BL	--

TO BE CONTINUED

Eurofins Testing Technology (Shenzhen) Co., Ltd.

4/F., Building 3, Building 2, Runheng Electronic Park, Liuxian 2nd Road, Xin'an Street, Bao'an District, Shenzhen, Guangdong, China
Tel.: +86 755 8358 5700 • Fax: +86 755 8358 5701 • Email: Info.HK@cpt.eurofinscn.com • Website: www.eurofins.com / www.pt.eurofins.com

TEST RESULT

Test No.	Material No.	XRF Results (mg/kg) (1)		Screening Results of PHTH (mg/kg) (2)	Wet Chemical Confirmation Result (mg/kg) (3)
27	27	Cd	BL	--	--
		Pb	BL	--	--
		Hg	BL	--	--
		Cr(VI)	BL	--	--
		PBBs	BL	--	--
		PBDEs	BL	--	--
		DBP	--	BL	--
		BBP	--	BL	--
		DEHP	--	BL	--
		DiBP	--	BL	--
28	28	Cd	BL	--	--
		Pb	BL	--	--
		Hg	BL	--	--
		Cr(VI)	BL	--	--
		PBBs	BL	--	--
		PBDEs	BL	--	--
		DBP	--	BL	--
		BBP	--	BL	--
		DEHP	--	BL	--
		DiBP	--	BL	--
29	29	Cd	BL	--	--
		Pb	BL	--	--
		Hg	BL	--	--
		Cr(VI)	BL	--	--
		PBBs	NA	--	--
		PBDEs	NA	--	--
		DBP	--	NA	--
		BBP	--	NA	--
		DEHP	--	NA	--
		DiBP	--	NA	--
30	30	Cd	BL	--	--
		Pb	BL	--	--
		Hg	BL	--	--
		Cr(VI)	BL	--	--
		PBBs	BL	--	--
		PBDEs	BL	--	--
		DBP	--	BL	--
		BBP	--	BL	--
		DEHP	--	BL	--
		DiBP	--	BL	--

TO BE CONTINUED

Eurofins Testing Technology (Shenzhen) Co., Ltd.

4/F., Building 3, Building 2, Runheng Electronic Park, Liuxian 2nd Road, Xin'an Street, Bao'an District, Shenzhen, Guangdong, China
Tel.: +86 755 8358 5700 • Fax: +86 755 8358 5701 • Email: Info.HK@cpt.eurofinscn.com • Website: www.eurofins.com / www.pt.eurofins.com

TEST RESULT

Test No.	Material No.	XRF Results (mg/kg) (1)		Screening Results of PHTH (mg/kg) (2)	Wet Chemical Confirmation Result (mg/kg) (3)
31	31	Cd	BL	--	--
		Pb	BL	--	--
		Hg	BL	--	--
		Cr(VI)	IN	--	Negative
		PBBs	NA	--	--
		PBDEs	NA	--	--
		DBP	--	NA	--
		BBP	--	NA	--
		DEHP	--	NA	--
		DiBP	--	NA	--
32	32	Cd	BL	--	--
		Pb	BL	--	--
		Hg	BL	--	--
		Cr(VI)	BL	--	--
		PBBs	BL	--	--
		PBDEs	BL	--	--
		DBP	--	BL	--
		BBP	--	BL	--
		DEHP	--	BL	--
		DiBP	--	BL	--
33	33	Cd	BL	--	--
		Pb	BL	--	--
		Hg	BL	--	--
		Cr(VI)	BL	--	--
		PBBs	IN	--	N.D.
		PBDEs	IN	--	N.D.
		DBP	--	BL	--
		BBP	--	BL	--
		DEHP	--	BL	--
		DiBP	--	BL	--
34	34	Cd	BL	--	--
		Pb	BL	--	--
		Hg	BL	--	--
		Cr(VI)	BL	--	--
		PBBs	NA	--	--
		PBDEs	NA	--	--
		DBP	--	NA	--
		BBP	--	NA	--
		DEHP	--	NA	--
		DiBP	--	NA	--

TO BE CONTINUED

Eurofins Testing Technology (Shenzhen) Co., Ltd.

4/F., Building 3, Building 2, Runheng Electronic Park, Liuxian 2nd Road, Xin'an Street, Bao'an District, Shenzhen, Guangdong, China
Tel.: +86 755 8358 5700 • Fax: +86 755 8358 5701 • Email: Info.HK@cpt.eurofinscn.com • Website: www.eurofins.com / www.pt.eurofins.com

TEST RESULT

Test No.	Material No.	XRF Results (mg/kg) (1)		Screening Results of PHTH (mg/kg) (2)	Wet Chemical Confirmation Result (mg/kg) (3)
35	35	Cd	BL	--	--
		Pb	BL	--	--
		Hg	BL	--	--
		Cr(VI)	BL	--	--
		PBBs	NA	--	--
		PBDEs	NA	--	--
		DBP	--	NA	--
		BBP	--	NA	--
		DEHP	--	NA	--
		DiBP	--	NA	--
36	36	Cd	BL	--	--
		Pb	BL	--	--
		Hg	BL	--	--
		Cr(VI)	BL	--	--
		PBBs	NA	--	--
		PBDEs	NA	--	--
		DBP	--	NA	--
		BBP	--	NA	--
		DEHP	--	NA	--
		DiBP	--	NA	--
37	37	Cd	BL	--	--
		Pb	BL	--	--
		Hg	BL	--	--
		Cr(VI)	BL	--	--
		PBBs	NA	--	--
		PBDEs	NA	--	--
		DBP	--	NA	--
		BBP	--	NA	--
		DEHP	--	NA	--
		DiBP	--	NA	--
38	38	Cd	BL	--	--
		Pb	BL	--	--
		Hg	BL	--	--
		Cr(VI)	BL	--	--
		PBBs	NA	--	--
		PBDEs	NA	--	--
		DBP	--	NA	--
		BBP	--	NA	--
		DEHP	--	NA	--
		DiBP	--	NA	--

TO BE CONTINUED

Eurofins Testing Technology (Shenzhen) Co., Ltd.

4/F., Building 3, Building 2, Runheng Electronic Park, Liuxian 2nd Road, Xin'an Street, Bao'an District, Shenzhen, Guangdong, China
Tel.: +86 755 8358 5700 • Fax: +86 755 8358 5701 • Email: Info.HK@cpt.eurofinscn.com • Website: www.eurofins.com / www.pt.eurofins.com

TEST RESULT

Test No.	Material No.	XRF Results (mg/kg) (1)		Screening Results of PHTH (mg/kg) (2)	Wet Chemical Confirmation Result (mg/kg) (3)
39	39	Cd	BL	--	--
		Pb	BL	--	--
		Hg	BL	--	--
		Cr(VI)	BL	--	--
		PBBs	NA	--	--
		PBDEs	NA	--	--
		DBP	--	NA	--
		BBP	--	NA	--
		DEHP	--	NA	--
		DiBP	--	NA	--
40	40	Cd	BL	--	--
		Pb	BL	--	--
		Hg	BL	--	--
		Cr(VI)	BL	--	--
		PBBs	NA	--	--
		PBDEs	NA	--	--
		DBP	--	NA	--
		BBP	--	NA	--
		DEHP	--	NA	--
		DiBP	--	NA	--
41	41	Cd	BL	--	--
		Pb	BL	--	--
		Hg	BL	--	--
		Cr(VI)	BL	--	--
		PBBs	BL	--	--
		PBDEs	BL	--	--
		DBP	--	BL	--
		BBP	--	BL	--
		DEHP	--	BL	--
		DiBP	--	BL	--
42	42	Cd	BL	--	--
		Pb	BL	--	--
		Hg	BL	--	--
		Cr(VI)	IN	--	Negative
		PBBs	NA	--	--
		PBDEs	NA	--	--
		DBP	--	NA	--
		BBP	--	NA	--
		DEHP	--	NA	--
		DiBP	--	NA	--

TO BE CONTINUED

Eurofins Testing Technology (Shenzhen) Co., Ltd.

4/F., Building 3, Building 2, Runheng Electronic Park, Liuxian 2nd Road, Xin'an Street, Bao'an District, Shenzhen, Guangdong, China
Tel.: +86 755 8358 5700 • Fax: +86 755 8358 5701 • Email: Info.HK@cpt.eurofinscn.com • Website: www.eurofins.com / www.pt.eurofins.com

TEST RESULT

Test No.	Material No.	XRF Results (mg/kg) (1)		Screening Results of PHTH (mg/kg) (2)	Wet Chemical Confirmation Result (mg/kg) (3)
43	43	Cd	BL	--	--
		Pb	BL	--	--
		Hg	BL	--	--
		Cr(VI)	BL	--	--
		PBBs	NA	--	--
		PBDEs	NA	--	--
		DBP	--	NA	--
		BBP	--	NA	--
		DEHP	--	NA	--
		DiBP	--	NA	--
44	44	Cd	BL	--	--
		Pb	BL	--	--
		Hg	BL	--	--
		Cr(VI)	BL	--	--
		PBBs	NA	--	--
		PBDEs	NA	--	--
		DBP	--	NA	--
		BBP	--	NA	--
		DEHP	--	NA	--
		DiBP	--	NA	--
45	45	Cd	BL	--	--
		Pb	BL	--	--
		Hg	BL	--	--
		Cr(VI)	BL	--	--
		PBBs	NA	--	--
		PBDEs	NA	--	--
		DBP	--	NA	--
		BBP	--	NA	--
		DEHP	--	NA	--
		DiBP	--	NA	--
46	46	Cd	BL	--	--
		Pb	BL	--	--
		Hg	BL	--	--
		Cr(VI)	BL	--	--
		PBBs	NA	--	--
		PBDEs	NA	--	--
		DBP	--	NA	--
		BBP	--	NA	--
		DEHP	--	NA	--
		DiBP	--	NA	--

TO BE CONTINUED

Eurofins Testing Technology (Shenzhen) Co., Ltd.

4/F., Building 3, Building 2, Runheng Electronic Park, Liuxian 2nd Road, Xin'an Street, Bao'an District, Shenzhen, Guangdong, China
Tel.: +86 755 8358 5700 • Fax: +86 755 8358 5701 • Email: Info.HK@cpt.eurofinscn.com • Website: www.eurofins.com / www.pt.eurofins.com

TEST RESULT

Test No.	Material No.	XRF Results (mg/kg) (1)		Screening Results of PHTH (mg/kg) (2)	Wet Chemical Confirmation Result (mg/kg) (3)
47	47	Cd	BL	--	--
		Pb	BL	--	--
		Hg	BL	--	--
		Cr(VI)	BL	--	--
		PBBs	IN	--	N.D.
		PBDEs	IN	--	N.D.
		DBP	--	BL	--
		BBP	--	BL	--
		DEHP	--	BL	--
		DiBP	--	BL	--
48	48	Cd	BL	--	--
		Pb	BL	--	--
		Hg	BL	--	--
		Cr(VI)	BL	--	--
		PBBs	NA	--	--
		PBDEs	NA	--	--
		DBP	--	NA	--
		BBP	--	NA	--
		DEHP	--	NA	--
		DiBP	--	NA	--
49	49	Cd	BL	--	--
		Pb	BL	--	--
		Hg	BL	--	--
		Cr(VI)	BL	--	--
		PBBs	NA	--	--
		PBDEs	NA	--	--
		DBP	--	NA	--
		BBP	--	NA	--
		DEHP	--	NA	--
		DiBP	--	NA	--
50	50	Cd	BL	--	--
		Pb	BL	--	--
		Hg	BL	--	--
		Cr(VI)	IN	--	Negative
		PBBs	NA	--	--
		PBDEs	NA	--	--
		DBP	--	NA	--
		BBP	--	NA	--
		DEHP	--	NA	--
		DiBP	--	NA	--

TO BE CONTINUED

Eurofins Testing Technology (Shenzhen) Co., Ltd.

4/F., Building 3, Building 2, Runheng Electronic Park, Liuxian 2nd Road, Xin'an Street, Bao'an District, Shenzhen, Guangdong, China
Tel.: +86 755 8358 5700 • Fax: +86 755 8358 5701 • Email: Info.HK@cpt.eurofinscn.com • Website: www.eurofins.com / www.pt.eurofins.com

TEST RESULT

Test No.	Material No.	XRF Results (mg/kg) (1)		Screening Results of PHTH (mg/kg) (2)	Wet Chemical Confirmation Result (mg/kg) (3)
51	51	Cd	BL	--	--
		Pb	BL	--	--
		Hg	BL	--	--
		Cr(VI)	BL	--	--
		PBBs	NA	--	--
		PBDEs	NA	--	--
		DBP	--	NA	--
		BBP	--	NA	--
		DEHP	--	NA	--
		DiBP	--	NA	--
52	52	Cd	BL	--	--
		Pb	BL	--	--
		Hg	BL	--	--
		Cr(VI)	IN	--	Negative
		PBBs	NA	--	--
		PBDEs	NA	--	--
		DBP	--	NA	--
		BBP	--	NA	--
		DEHP	--	NA	--
		DiBP	--	NA	--
53	53	Cd	BL	--	--
		Pb	BL	--	--
		Hg	BL	--	--
		Cr(VI)	IN	--	Negative
		PBBs	NA	--	--
		PBDEs	NA	--	--
		DBP	--	NA	--
		BBP	--	NA	--
		DEHP	--	NA	--
		DiBP	--	NA	--
54	54	Cd	BL	--	--
		Pb	BL	--	--
		Hg	BL	--	--
		Cr(VI)	BL	--	--
		PBBs	BL	--	--
		PBDEs	BL	--	--
		DBP	--	BL	--
		BBP	--	BL	--
		DEHP	--	BL	--
		DiBP	--	BL	--

TO BE CONTINUED

Eurofins Testing Technology (Shenzhen) Co., Ltd.

4/F., Building 3, Building 2, Runheng Electronic Park, Liuxian 2nd Road, Xin'an Street, Bao'an District, Shenzhen, Guangdong, China
Tel.: +86 755 8358 5700 • Fax: +86 755 8358 5701 • Email: Info.HK@cpt.eurofinscn.com • Website: www.eurofins.com / www.pt.eurofins.com

TEST RESULT

Test No.	Material No.	XRF Results (mg/kg) (1)		Screening Results of PHTH (mg/kg) (2)	Wet Chemical Confirmation Result (mg/kg) (3)
55	55	Cd	BL	--	--
		Pb	BL	--	--
		Hg	BL	--	--
		Cr(VI)	BL	--	--
		PBBs	BL	--	--
		PBDEs	BL	--	--
		DBP	--	BL	--
		BBP	--	BL	--
		DEHP	--	BL	--
		DiBP	--	BL	--
56	56	Cd	BL	--	--
		Pb	BL	--	--
		Hg	BL	--	--
		Cr(VI)	BL	--	--
		PBBs	BL	--	--
		PBDEs	BL	--	--
		DBP	--	BL	--
		BBP	--	BL	--
		DEHP	--	BL	--
		DiBP	--	BL	--
57	57	Cd	BL	--	--
		Pb	BL	--	--
		Hg	BL	--	--
		Cr(VI)	IN	--	Negative
		PBBs	NA	--	--
		PBDEs	NA	--	--
		DBP	--	NA	--
		BBP	--	NA	--
		DEHP	--	NA	--
		DiBP	--	NA	--
58	58	Cd	BL	--	--
		Pb	BL	--	--
		Hg	BL	--	--
		Cr(VI)	IN	--	Negative
		PBBs	NA	--	--
		PBDEs	NA	--	--
		DBP	--	NA	--
		BBP	--	NA	--
		DEHP	--	NA	--
		DiBP	--	NA	--

TO BE CONTINUED

Eurofins Testing Technology (Shenzhen) Co., Ltd.

4/F., Building 3, Building 2, Runheng Electronic Park, Liuxian 2nd Road, Xin'an Street, Bao'an District, Shenzhen, Guangdong, China
Tel.: +86 755 8358 5700 • Fax: +86 755 8358 5701 • Email: Info.HK@cpt.eurofinscn.com • Website: www.eurofins.com / www.pt.eurofins.com

TEST RESULT

Test No.	Material No.	XRF Results (mg/kg) (1)		Screening Results of PHTH (mg/kg) (2)	Wet Chemical Confirmation Result (mg/kg) (3)
59	59	Cd	BL	--	--
		Pb	BL	--	--
		Hg	BL	--	--
		Cr(VI)	BL	--	--
		PBBs	BL	--	--
		PBDEs	BL	--	--
		DBP	--	BL	--
		BBP	--	BL	--
		DEHP	--	BL	--
		DiBP	--	BL	--
60	60	Cd	BL	--	--
		Pb	BL	--	--
		Hg	BL	--	--
		Cr(VI)	BL	--	--
		PBBs	BL	--	--
		PBDEs	BL	--	--
		DBP	--	BL	--
		BBP	--	BL	--
		DEHP	--	BL	--
		DiBP	--	BL	--
61	61	Cd	BL	--	--
		Pb	BL	--	--
		Hg	BL	--	--
		Cr(VI)	BL	--	--
		PBBs	NA	--	--
		PBDEs	NA	--	--
		DBP	--	NA	--
		BBP	--	NA	--
		DEHP	--	NA	--
		DiBP	--	NA	--
62	62	Cd	BL	--	--
		Pb	BL	--	--
		Hg	BL	--	--
		Cr(VI)	BL	--	--
		PBBs	NA	--	--
		PBDEs	NA	--	--
		DBP	--	NA	--
		BBP	--	NA	--
		DEHP	--	NA	--
		DiBP	--	NA	--

TO BE CONTINUED

Eurofins Testing Technology (Shenzhen) Co., Ltd.

4/F., Building 3, Building 2, Runheng Electronic Park, Liuxian 2nd Road, Xin'an Street, Bao'an District, Shenzhen, Guangdong, China
Tel.: +86 755 8358 5700 • Fax: +86 755 8358 5701 • Email: Info.HK@cpt.eurofinscn.com • Website: www.eurofins.com / www.pt.eurofins.com

TEST RESULT

Test No.	Material No.	XRF Results (mg/kg) (1)		Screening Results of PHTH (mg/kg) (2)	Wet Chemical Confirmation Result (mg/kg) (3)
63	63	Cd	BL	--	--
		Pb	BL	--	--
		Hg	BL	--	--
		Cr(VI)	BL	--	--
		PBBs	NA	--	--
		PBDEs	NA	--	--
		DBP	--	NA	--
		BBP	--	NA	--
		DEHP	--	NA	--
		DiBP	--	NA	--
64	64	Cd	BL	--	--
		Pb	BL	--	--
		Hg	BL	--	--
		Cr(VI)	BL	--	--
		PBBs	NA	--	--
		PBDEs	NA	--	--
		DBP	--	NA	--
		BBP	--	NA	--
		DEHP	--	NA	--
		DiBP	--	NA	--
65	65	Cd	BL	--	--
		Pb	BL	--	--
		Hg	BL	--	--
		Cr(VI)	BL	--	--
		PBBs	NA	--	--
		PBDEs	NA	--	--
		DBP	--	NA	--
		BBP	--	NA	--
		DEHP	--	NA	--
		DiBP	--	BL	--
66	66	Cd	BL	--	--
		Pb	BL	--	--
		Hg	BL	--	--
		Cr(VI)	BL	--	--
		PBBs	BL	--	--
		PBDEs	BL	--	--
		DBP	--	BL	--
		BBP	--	BL	--
		DEHP	--	BL	--
		DiBP	--	BL	--

TO BE CONTINUED

Eurofins Testing Technology (Shenzhen) Co., Ltd.

4/F., Building 3, Building 2, Runheng Electronic Park, Liuxian 2nd Road, Xin'an Street, Bao'an District, Shenzhen, Guangdong, China
Tel.: +86 755 8358 5700 • Fax: +86 755 8358 5701 • Email: Info.HK@cpt.eurofinscn.com • Website: www.eurofins.com / www.pt.eurofins.com

TEST RESULT

Test No.	Material No.	XRF Results (mg/kg) (1)		Screening Results of PHTH (mg/kg) (2)	Wet Chemical Confirmation Result (mg/kg) (3)
67	67	Cd	BL	--	--
		Pb	BL	--	--
		Hg	BL	--	--
		Cr(VI)	IN	--	Negative
		PBBs	NA	--	--
		PBDEs	NA	--	--
		DBP	--	NA	--
		BBP	--	NA	--
		DEHP	--	NA	--
		DiBP	--	NA	--
68	68	Cd	BL	--	--
		Pb	BL	--	--
		Hg	BL	--	--
		Cr(VI)	BL	--	--
		PBBs	NA	--	--
		PBDEs	NA	--	--
		DBP	--	NA	--
		BBP	--	NA	--
		DEHP	--	NA	--
		DiBP	--	NA	--
69	69	Cd	BL	--	--
		Pb	BL	--	--
		Hg	BL	--	--
		Cr(VI)	BL	--	--
		PBBs	NA	--	--
		PBDEs	NA	--	--
		DBP	--	NA	--
		BBP	--	NA	--
		DEHP	--	NA	--
		DiBP	--	NA	--
70	70	Cd	BL	--	--
		Pb	BL	--	--
		Hg	BL	--	--
		Cr(VI)	BL	--	--
		PBBs	BL	--	--
		PBDEs	BL	--	--
		DBP	--	NA	--
		BBP	--	NA	--
		DEHP	--	NA	--
		DiBP	--	NA	--

TO BE CONTINUED

Eurofins Testing Technology (Shenzhen) Co., Ltd.

4/F., Building 3, Building 2, Runheng Electronic Park, Liuxian 2nd Road, Xin'an Street, Bao'an District, Shenzhen, Guangdong, China
Tel.: +86 755 8358 5700 • Fax: +86 755 8358 5701 • Email: Info.HK@cpt.eurofinscn.com • Website: www.eurofins.com / www.pt.eurofins.com

TEST RESULT

Test No.	Material No.	XRF Results (mg/kg) (1)		Screening Results of PHTH (mg/kg) (2)	Wet Chemical Confirmation Result (mg/kg) (3)
71	71	Cd	BL	--	--
		Pb	BL	--	--
		Hg	BL	--	--
		Cr(VI)	IN	--	Negative
		PBBs	NA	--	--
		PBDEs	NA	--	--
		DBP	--	NA	--
		BBP	--	NA	--
		DEHP	--	NA	--
		DiBP	--	NA	--
72	72	Cd	BL	--	--
		Pb	BL	--	--
		Hg	BL	--	--
		Cr(VI)	BL	--	--
		PBBs	NA	--	--
		PBDEs	NA	--	--
		DBP	--	NA	--
		BBP	--	NA	--
		DEHP	--	NA	--
		DiBP	--	NA	--
73	73	Cd	BL	--	--
		Pb	BL	--	--
		Hg	BL	--	--
		Cr(VI)	BL	--	--
		PBBs	BL	--	--
		PBDEs	BL	--	--
		DBP	--	BL	--
		BBP	--	BL	--
		DEHP	--	BL	--
		DiBP	--	BL	--
74	74	Cd	BL	--	--
		Pb	BL	--	--
		Hg	BL	--	--
		Cr(VI)	BL	--	--
		PBBs	BL	--	--
		PBDEs	BL	--	--
		DBP	--	BL	--
		BBP	--	BL	--
		DEHP	--	BL	--
		DiBP	--	BL	--

TO BE CONTINUED

Eurofins Testing Technology (Shenzhen) Co., Ltd.

4/F., Building 3, Building 2, Runheng Electronic Park, Liuxian 2nd Road, Xin'an Street, Bao'an District, Shenzhen, Guangdong, China
Tel.: +86 755 8358 5700 • Fax: +86 755 8358 5701 • Email: Info.HK@cpt.eurofinscn.com • Website: www.eurofins.com / www.pt.eurofins.com

TEST RESULT

Test No.	Material No.	XRF Results (mg/kg) (1)		Screening Results of PHTH (mg/kg) (2)	Wet Chemical Confirmation Result (mg/kg) (3)
75	75	Cd	BL	--	--
		Pb	BL	--	--
		Hg	BL	--	--
		Cr(VI)	IN	--	N.D.
		PBBs	BL	--	--
		PBDEs	BL	--	--
		DBP	--	BL	--
		BBP	--	BL	--
		DEHP	--	BL	--
		DiBP	--	BL	--
76	76	Cd	BL	--	--
		Pb	BL	--	--
		Hg	BL	--	--
		Cr(VI)	BL	--	--
		PBBs	IN	--	N.D.
		PBDEs	IN	--	N.D.
		DBP	--	BL	--
		BBP	--	BL	--
		DEHP	--	BL	--
		DiBP	--	BL	--
77	77	Cd	BL	--	--
		Pb	BL	--	--
		Hg	BL	--	--
		Cr(VI)	BL	--	--
		PBBs	NA	--	--
		PBDEs	NA	--	--
		DBP	--	NA	--
		BBP	--	NA	--
		DEHP	--	NA	--
		DiBP	--	NA	--
78	78	Cd	BL	--	--
		Pb	BL	--	--
		Hg	BL	--	--
		Cr(VI)	BL	--	--
		PBBs	BL	--	--
		PBDEs	BL	--	--
		DBP	--	BL	--
		BBP	--	BL	--
		DEHP	--	BL	--
		DiBP	--	BL	--

TO BE CONTINUED

Eurofins Testing Technology (Shenzhen) Co., Ltd.

4/F., Building 3, Building 2, Runheng Electronic Park, Liuxian 2nd Road, Xin'an Street, Bao'an District, Shenzhen, Guangdong, China
Tel.: +86 755 8358 5700 • Fax: +86 755 8358 5701 • Email: Info.HK@cpt.eurofinscn.com • Website: www.eurofins.com / www.pt.eurofins.com

TEST RESULT

Test No.	Material No.	XRF Results (mg/kg) (1)		Screening Results of PHTH (mg/kg) (2)	Wet Chemical Confirmation Result (mg/kg) (3)
79	79	Cd	BL	--	--
		Pb	BL	--	--
		Hg	BL	--	--
		Cr(VI)	IN	--	N.D.
		PBBs	BL	--	--
		PBDEs	BL	--	--
		DBP	--	BL	--
		BBP	--	BL	--
		DEHP	--	BL	--
		DiBP	--	BL	--
80	80	Cd	BL	--	--
		Pb	BL	--	--
		Hg	BL	--	--
		Cr(VI)	BL	--	--
		PBBs	NA	--	--
		PBDEs	NA	--	--
		DBP	--	NA	--
		BBP	--	NA	--
		DEHP	--	NA	--
		DiBP	--	NA	--
81	81	Cd	BL	--	--
		Pb	BL	--	--
		Hg	BL	--	--
		Cr(VI)	BL	--	--
		PBBs	BL	--	--
		PBDEs	BL	--	--
		DBP	--	BL	--
		BBP	--	BL	--
		DEHP	--	BL	--
		DiBP	--	BL	--
82	82	Cd	BL	--	--
		Pb	BL	--	--
		Hg	BL	--	--
		Cr(VI)	BL	--	--
		PBBs	NA	--	--
		PBDEs	NA	--	--
		DBP	--	NA	--
		BBP	--	NA	--
		DEHP	--	NA	--
		DiBP	--	NA	--

TO BE CONTINUED

Eurofins Testing Technology (Shenzhen) Co., Ltd.

4/F., Building 3, Building 2, Runheng Electronic Park, Liuxian 2nd Road, Xin'an Street, Bao'an District, Shenzhen, Guangdong, China
Tel.: +86 755 8358 5700 • Fax: +86 755 8358 5701 • Email: Info.HK@cpt.eurofinscn.com • Website: www.eurofins.com / www.pt.eurofins.com

TEST RESULT

Test No.	Material No.	XRF Results (mg/kg) (1)		Screening Results of PHTH (mg/kg) (2)	Wet Chemical Confirmation Result (mg/kg) (3)
83	83	Cd	BL	--	--
		Pb	BL	--	--
		Hg	BL	--	--
		Cr(VI)	IN	--	Negative
		PBBs	NA	--	--
		PBDEs	NA	--	--
		DBP	--	NA	--
		BBP	--	NA	--
		DEHP	--	NA	--
		DiBP	--	NA	--
84	84	Cd	BL	--	--
		Pb	BL	--	--
		Hg	BL	--	--
		Cr(VI)	IN	--	Negative
		PBBs	NA	--	--
		PBDEs	NA	--	--
		DBP	--	NA	--
		BBP	--	NA	--
		DEHP	--	NA	--
		DiBP	--	NA	--
85	85	Cd	BL	--	--
		Pb	BL	--	--
		Hg	BL	--	--
		Cr(VI)	BL	--	--
		PBBs	BL	--	--
		PBDEs	BL	--	--
		DBP	--	BL	--
		BBP	--	BL	--
		DEHP	--	BL	--
		DiBP	--	BL	--
86	86	Cd	BL	--	--
		Pb	BL	--	--
		Hg	BL	--	--
		Cr(VI)	IN	--	Negative
		PBBs	NA	--	--
		PBDEs	NA	--	--
		DBP	--	NA	--
		BBP	--	NA	--
		DEHP	--	NA	--
		DiBP	--	NA	--

TO BE CONTINUED

Eurofins Testing Technology (Shenzhen) Co., Ltd.

4/F., Building 3, Building 2, Runheng Electronic Park, Liuxian 2nd Road, Xin'an Street, Bao'an District, Shenzhen, Guangdong, China
Tel.: +86 755 8358 5700 • Fax: +86 755 8358 5701 • Email: Info.HK@cpt.eurofinscn.com • Website: www.eurofins.com / www.pt.eurofins.com

TEST RESULT

Test No.	Material No.	XRF Results (mg/kg) (1)		Screening Results of PHTH (mg/kg) (2)	Wet Chemical Confirmation Result (mg/kg) (3)
87	87	Cd	BL	--	--
		Pb	BL	--	--
		Hg	BL	--	--
		Cr(VI)	BL	--	--
		PBBs	IN	--	N.D.
		PBDEs	IN	--	N.D.
		DBP	--	BL	--
		BBP	--	BL	--
		DEHP	--	BL	--
		DiBP	--	BL	--
88	88	Cd	BL	--	--
		Pb	BL	--	--
		Hg	BL	--	--
		Cr(VI)	BL	--	--
		PBBs	BL	--	--
		PBDEs	BL	--	--
		DBP	--	BL	--
		BBP	--	BL	--
		DEHP	--	BL	--
		DiBP	--	BL	--
89	89	Cd	BL	--	--
		Pb	BL	--	--
		Hg	BL	--	--
		Cr(VI)	BL	--	--
		PBBs	BL	--	--
		PBDEs	BL	--	--
		DBP	--	BL	--
		BBP	--	BL	--
		DEHP	--	BL	--
		DiBP	--	BL	--
90	90	Cd	BL	--	--
		Pb	BL	--	--
		Hg	BL	--	--
		Cr(VI)	BL	--	--
		PBBs	NA	--	--
		PBDEs	NA	--	--
		DBP	--	NA	--
		BBP	--	NA	--
		DEHP	--	NA	--
		DiBP	--	NA	--

TO BE CONTINUED

Eurofins Testing Technology (Shenzhen) Co., Ltd.

4/F., Building 3, Building 2, Runheng Electronic Park, Liuxian 2nd Road, Xin'an Street, Bao'an District, Shenzhen, Guangdong, China
Tel.: +86 755 8358 5700 • Fax: +86 755 8358 5701 • Email: Info.HK@cpt.eurofinscn.com • Website: www.eurofins.com / www.pt.eurofins.com

TEST RESULT

Test No.	Material No.	XRF Results (mg/kg) (1)		Screening Results of PHTH (mg/kg) (2)	Wet Chemical Confirmation Result (mg/kg) (3)
91	91	Cd	BL	--	--
		Pb	BL	--	--
		Hg	BL	--	--
		Cr(VI)	BL	--	--
		PBBs	BL	--	--
		PBDEs	BL	--	--
		DBP	--	BL	--
		BBP	--	BL	--
		DEHP	--	BL	--
		DiBP	--	BL	--
92	92	Cd	BL	--	--
		Pb	BL	--	--
		Hg	BL	--	--
		Cr(VI)	BL	--	--
		PBBs	BL	--	--
		PBDEs	BL	--	--
		DBP	--	BL	--
		BBP	--	BL	--
		DEHP	--	BL	--
		DiBP	--	BL	--
93	93	Cd	BL	--	--
		Pb	BL	--	--
		Hg	BL	--	--
		Cr(VI)	BL	--	--
		PBBs	BL	--	--
		PBDEs	BL	--	--
		DBP	--	BL	--
		BBP	--	BL	--
		DEHP	--	BL	--
		DiBP	--	BL	--
94	94	Cd	BL	--	--
		Pb	BL	--	--
		Hg	BL	--	--
		Cr(VI)	BL	--	--
		PBBs	IN	--	N.D.
		PBDEs	IN	--	N.D.
		DBP	--	BL	--
		BBP	--	BL	--
		DEHP	--	BL	--
		DiBP	--	BL	--

TO BE CONTINUED

Eurofins Testing Technology (Shenzhen) Co., Ltd.

4/F., Building 3, Building 2, Runheng Electronic Park, Liuxian 2nd Road, Xin'an Street, Bao'an District, Shenzhen, Guangdong, China
Tel.: +86 755 8358 5700 • Fax: +86 755 8358 5701 • Email: Info.HK@cpt.eurofinscn.com • Website: www.eurofins.com / www.pt.eurofins.com

TEST RESULT

Remark:

(1) (a) It is the result on total Br while test item on restricted substances is PBBs/PBDEs. It is the result on total Cr while test item on restricted substances is Cr(VI).

(b) Results are obtained by EDXRF for primary screening, and further chemical testing by ICP (for Cd, Pb, Hg), UV-VIS (for Cr(VI)) and GC/MS (for PBBs, PBDEs) is recommended to be performed, if the concentration exceeds the below warning value according to IEC62321.

XRF Screening Limits in mg/kg for Regulated Elements in Various Matrices:

Element	Polymer Materials	Metallic Materials	Composite Materials
Cd	$BL \leq (70-3\sigma) < X < (130+3\sigma) \leq OL$	$BL \leq (70-3\sigma) < X < (130+3\sigma) \leq OL$	$LOD < X < (150+3\sigma) \leq OL$
Pb	$BL \leq (700-3\sigma) < X < (1300+3\sigma) \leq OL$	$BL \leq (700-3\sigma) < X < (1300+3\sigma) \leq OL$	$BL \leq (500-3\sigma) < X < (1500+3\sigma) \leq OL$
Hg	$BL \leq (700-3\sigma) < X < (1300+3\sigma) \leq OL$	$BL \leq (700-3\sigma) < X < (1300+3\sigma) \leq OL$	$BL \leq (500-3\sigma) < X < (1500+3\sigma) \leq OL$
Cr	$BL \leq (700-3\sigma) < X$	$BL \leq (700-3\sigma) < X$	$BL \leq (500-3\sigma) < X$
Br	$BL \leq (300-3\sigma) < X$	-	$BL \leq (250-3\sigma) < X$

(c) The XRF screening test for ROHS elements – The reading may be different to the actual content in the sample be of non-uniformity composition.

Note: BL= Below Limit

OL= Over Limit

IN = Inconclusive

LOD = Limit of Detection

N.D. = Not Detected (<MDL)

NA = Not Applicable

- = Not Regulated

-- = Not Conducted

mg/kg = milligram per kilogram = ppm = 0.0001%

(2) Screening results of PHTH are for primary screening, and further chemical testing by GC-MS (for DBP, BBP, DEHP and DIBP) are recommended to be performed if the concentration exceeds the below warning value (unit: mg/kg)

Compound	Polymer Materials
DBP	$BL \leq 600 < X$
BBP	$BL \leq 600 < X$
DEHP	$BL \leq 600 < X$
DiBP	$BL \leq 600 < X$

(3) (a) Unit and Method Detected Limit (MDL) in wet chemical test.

Testing Item	Detection Limit
Cadmium, Lead & Mercury	10 mg/kg
Chromium (VI)	10 mg/kg
Polybrominated Biphenyls (PBBs) & Polybrominated Diphenyl Ethers (PBDEs)	10 [^] mg/kg
Dibutylphthalate (DBP)	50 mg/kg
Benzylbutylphthalate (BBP)	50 mg/kg
Diethylhexylphthalate (DEHP)	50 mg/kg
Diisobutyl phthalate (DiBP)	50 mg/kg

^ The MDL for single compound of PBBs and PBDEs.

TO BE CONTINUED

Eurofins Testing Technology (Shenzhen) Co., Ltd.

4/F., Building 3, Building 2, Runheng Electronic Park, Liuxian 2nd Road, Xin'an Street, Bao'an District, Shenzhen, Guangdong, China
Tel.: +86 755 8358 5700 • Fax: +86 755 8358 5701 • Email: Info.HK@cpt.eurofinscn.com • Website: www.eurofins.com / www.pt.eurofins.com

TEST RESULT

(b) According to IEC 62321, result on Cr(VI) for metal sample is shown as Positive/Negative.

Negative = Absence of Cr(VI) coating.

Positive = Presence of Cr(VI) coating.

(4) RoHS Requirement:

Restricted Substances	Limits [^]
Cadmium (Cd)	0.01% (100 mg/kg)
Lead (Pb)	0.1% (1000 mg/kg)
Mercury (Hg)	0.1% (1000 mg/kg)
Chromium (VI) (Cr VI)	0.1% (1000 mg/kg)
Polybrominated Biphenyls (PBBs)	0.1% (1000 mg/kg)
Polybrominated Diphenyl Ethers (PBDEs)	0.1% (1000 mg/kg)
Dibutylphthalate (DBP)	0.1% (1000 mg/kg)
Benzylbutylphthalate (BBP)	0.1% (1000 mg/kg)
Diethylhexylphthalate (DEHP)	0.1% (1000 mg/kg)
Diisobutyl phthalate (DiBP)	0.1% (1000 mg/kg)

[^]The above limits were quoted from 2011/65/EU and its amendment Directive (EU) 2015/863 for homogeneous material.

Other Information / Remark:

N/A

END OF THE REPORT

Eurofins Testing Technology (Shenzhen) Co., Ltd.

4/F., Building 3, Building 2, Runheng Electronic Park, Liuxian 2nd Road, Xin'an Street, Bao'an District, Shenzhen, Guangdong, China
Tel.: +86 755 8358 5700 • Fax: +86 755 8358 5701 • Email: Info.HK@cpt.eurofinscn.com • Website: www.eurofins.com / www.pt.eurofins.com