Public House Creative

Sample Project – Lot 12

Saturday, September 12, 2026

Prepared For Sample Builder Co.

123 Example Street, Sampleville, AZ 00000


5 Issues Identified


4 Issues Incomplete

Kitchen

PLUMBING Raised by: RW 9/10


Supply line for the sink is 2 in. left of the cabinet cutout. Needs to be moved before the base cabinets are set.





ELECTRICAL Raised by: RW 9/10


No outlet rough-in on the island wall. Outlet required by plan.




FRAMING Raised by: RW 9/10

Wall bowed about 3/4 in. at the pantry. Shim or re-frame so the tall cabinet sits plumb.








Primary Bath

WINDOWS Raised by: RW 9/10

Window sill is lower than the tub deck. Confirm height with the builder before the surround is ordered.





Laundry

DRYWALL Raised by: RW 9/10

Hole in the wall behind the washer box.