



Metadata:
 Físico: fis
 Unidade: CT
 Data: 19_07_2024

- CBCT/CT 503 QA Test -
 - CTP 404 Results -
 HU Linearity tolerance: 40
 HU Linearity ROIs:
 Air: 84.0, PMP: 691.0, LDPE: 754.0, Poly: 794.0,
 Acrylic: 922.0, Delrin: 1081.0, Teflon: 1560.0
 HU Passed?: False
 Low contrast visibility: 2.06
 Geometric Line Average (mm): 50.18
 Geometry Passed?: True
 Measured Slice Thickness (mm): 1.028
 Slice Thickness Passed? True



Metadata:

Físico: fis

Unidade: CT

Data: 19_07_2024



- CTP528 Results -

MTF 80% (lp/mm): 0.14

MTF 50% (lp/mm): 0.21

MTF 30% (lp/mm): 0.26

Spatial Resolution



Metadata:

Físico: fis

Unidade: CT

Data: 19_07_2024

- CTP486 Results -

Uniformity tolerance: 40

Uniformity ROIs: Top: 831.0, Right: 829.0, Bottom: 821.0, Left: 822.5, Center: 849.0

Uniformity index: -1.514


Integral non-uniformity: 0.0076

Uniformity Passed?: False


Max Noise Power frequency: 0.0666666

Average Noise Power: 0.209804780657

HU Uniformity




Uniformity Profiles



Metadata:
Físico: fis
Unidade: CT
Data: 19_07_2024

Side View



Metadata:

Físico: fis

Unidade: CT

Data: 19_07_2024