



Metadata:
 Físico: Victor
 Unidade: True Beam
 Data: 25_10_2024

- CBCT/CT 504 QA Test -
 - CTP 404 Results -
 HU Linearity tolerance: 40
 HU Linearity ROIs:
 Air: -1000.0, PMP: -207.0, LDPE: -111.0, Poly:
 -54.0, Acrylic: 118.0, Delrin: 363.0, Teflon:
 1005.5
 HU Passed?: True
 Low contrast visibility: 14.88
 Geometric Line Average (mm): 49.77
 Geometry Passed?: True
 Measured Slice Thickness (mm): 1.427
 Slice Thickness Passed? False



Metadata:

Físico: Victor

Unidade: True Beam

Data: 25_10_2024



- CTP528 Results -

MTF 80% (lp/mm): 0.17

MTF 50% (lp/mm): 0.26

MTF 30% (lp/mm): 0.33

Spatial Resolution



Metadata:

Físico: Victor

Unidade: True Beam

Data: 25_10_2024

- CTP486 Results -

Uniformity tolerance: 40

Uniformity ROIs: Top: 0.0, Right: -2.0, Bottom: -4.0, Left: -3.0, Center: -2.0

Uniformity index: 0.200


Integral non-uniformity: 0.0020

Uniformity Passed?: True


Max Noise Power frequency: 0.0625

Average Noise Power: 0.1326405887739

HU Uniformity



Uniformity Profiles



Metadata:

Físico: Victor

Unidade: True Beam


Data: 25_10_2024

- CTP515 Results -

CNR threshold: 15


Low contrast ROIs "seen": 5

Low Contrast



Metadata:
Físico: Victor
Unidade: True Beam
Data: 25_10_2024

Side View



Metadata:

Físico: Victor

Unidade: True Beam

Data: 25_10_2024