

Metadata:

Físico: í

Unidade: Versa

Data: 11_11_2025

- CBCT/CT 503 QA Test -

- CTP 404 Results -

HU Linearity tolerance: 40

HU Linearity ROIs:

Air: -930.0, PMP: -305.5, LDPE: -242.0, Poly:

-218.0, Acrylic: -99.0, Delrin: 78.0, Teflon:

533.0

HU Passed?: False

Low contrast visibility: 2.43


Geometric Line Average (mm): 49.66

Geometry Passed?: True


Measured Slice Thickness (mm): 2.175

Slice Thickness Passed? False

HU Linearity



HU linearity



Metadata:

Físico: í

Unidade: Versa

Data: 11_11_2025



- CTP528 Results -

MTF 80% (lp/mm): 0.15

MTF 50% (lp/mm): 0.22

MTF 30% (lp/mm): 0.27

Spatial Resolution



Metadata:

Físico: í

Unidade: Versa

Data: 11_11_2025

- CTP486 Results -

Uniformity tolerance: 40

Uniformity ROIs: Top: -163.0, Right: -169.0, Bottom: -180.0, Left: -169.0, Center: -155.0

Uniformity index: -2.959


Integral non-uniformity: 0.0150

Uniformity Passed?: False


Max Noise Power frequency: 0.0666666

Average Noise Power: 0.135342365943

HU Uniformity



Uniformity Profiles



Metadata:
Físico: í
Unidade: Versa
Data: 11_11_2025

Side View



Metadata:

Físico: í

Unidade: Versa

Data: 11_11_2025