





16HO: 125 days old: dry land: roughly 2.5 weeks out, check again after this rain passes





TIF NV HO: 154 days: Irrigated: 5-7 days.



This field ended up dropping a lot of pods when dug. Did not match the board.





12Y: Dryland: 146 days old: ready to dig




12Y: Dryland: 144 days old: sandier soil than previous sample: ready to dig





12Y: Dry land: 140 days: dig these after the other two fields, but ready to go based on kernels





Dynagrow 913: 138 days: irrigated: 1.5 weeks out





16HO replanted into Arnie: Arnie's 145 days, 16HO 131 days: Irrigated: Roughly 2.5 weeks out, bring another sample next week



TIF NV HG: 138 days: irrigated: 2 weeks out



ARNIE: 138 days: irrigated: 2-2.5 weeks out



06G: 139 days: 1.5-2 weeks out