# ECO-SENTINEL Vegetation Loss Alert Report

| | |
|---|---|
| **Alert ID** | ALERT-IN-a6c394f62857 |
| **Alert Generated At** | 2026-10-09T17:44:26.764137+00:00 |
| **Satellite Acquisition Date** | 2026-09-27T05:35:40.240000+00:00 |
| **Comparison Period** | 2025 vs 2026-09-27 |
| **Satellite Image ID** | …PERNICUS/S2_SR_HARMONIZED/20260927T051651_20260927T053403_T43PDP |
| **Cloud Cover (image metadata)** | 1.987582 |
| **Latitude** | 12.630142 |
| **Longitude** | 75.010593 |
| **Area Lost (ha)** | 0.1454 |
| **Severity Level** | Mild |
| **Region / Division** | Kasaragod |
| **Polygon ID** | LOSS-28d58ef50c51 |
| **ML Confidence** | Not available |
| **Detection Method** | vegetation_loss |
| **Legality Status** | legal_status_unknown |
| **Final Category** | legal_status_unknown |
| **Cloud Masking** | Sentinel-2 SCL classes excluded: 0, 1, 3, 8, 9, 10 |

## Satellite Snapshot of Affected Area