

Electrical Work Request Form

Request Number	1WRELAM575	Date required	2025-08-06
Location	Lot 3 B1		
Requestor	Ben Maher	Assigned Worker	Adam Murray
Description Of Task Requested			
Relocate sumo, LG 83, ELV panel and ELV lights			

Electrical supervisors' comments

Mount ELV lights to the underside of cable tray and one above the goods lift door, to the brackets above. Remove 240v light above goods lift. Relocate sumo, LG83 and ELV panel as per attached pics. Remove all cables going through the wall, to the callpoint etc and refeed through the doorway. Ensure no cabling is left on the scaffold outside goods lift, so it can be stripped

Electrical Design Required?	No	COC Required?	Yes	Test Document Number	TS 845
Design Comments (consider cable sizing, circuit loading, Voltage drop fault, loop impedance, lighting level design, requirement to update drawings etc)					

Additional Photos

Electrical Worker Completed the Work	B. Johnson
Electrical Workers Signature	
	



Electrical Work Request Form

Request Number	1WRELAM565	Date required	2025-08-06
Location	Lot 1 L0		
Requestor	Ben Maher	Assigned Worker	Ben Maher
Description Of Task Requested			
Remove floodlight circuit from scaffold and re run			
Electrical supervisors' comments			
N.A			
Electrical Design Required?	Yes	COC Required?	Yes
		Test Document Number	
		TS 844	
Design Comments (consider cable sizing, circuit loading, Voltage drop fault, loop impedance, lighting level design, requirement to update drawings etc)			
N.A			
Additional Photos			
Electrical Worker Completed the Work	 ben Maher		
		Electrical Workers Signature	 ben Maher



Electrical Work Request Form

Request Number	1WRELAM566	Date required	2025-08-06
Location	Lot 1		
Requestor	Ben maher	Assigned Worker	Ben Maher
Description Of Task Requested			
Remove ELV from scaffold and re feed			
Electrical supervisors' comments			
N.A			

Electrical Design Required?	Yes	COC Required?	Yes	Test Document Number
TS 843				

Design Comments (consider cable sizing, circuit loading, Voltage drop fault, loop impedance, lighting level design, requirement to update drawings etc)				
N.A				

Additional Photos				

Electrical Worker Completed the Work		Electrical Workers Signature	
--------------------------------------	--	------------------------------	--



Electrical Work Request Form

Request Number	1WRELAM567	Date required	2025-08-06
Location	Lot 1 L6		
Requestor	Ben maher	Assigned Worker	Ben Maher
Description Of Task Requested Install 4 x floodlights			
Electrical supervisors' comments N.A			
Electrical Design Required?	Yes	COC Required?	Yes
Test Document Number TS842			
Design Comments (consider cable sizing, circuit loading, Voltage drop fault, loop impedance, lighting level design, requirement to update drawings etc) N.A			
Additional Photos 			
Electrical Worker Completed the Work	Ben Maher		
	Electrical Workers Signature 		



Electrical Work Request Form

Request Number	1WRELAM564	Date required	2025-08-06
Location	Lot 1 L0 north		
Requestor	Ben Maher	Assigned Worker	Trent Minton
Description Of Task Requested			
Install isolator for gantry crane			

Electrical supervisors' comments			
N.A			

Electrical Design Required?	Yes	COC Required?	Yes	Test Document Number
15841				

Design Comments (consider cable sizing, circuit loading, Voltage drop fault, loop impedance, lighting level design, requirement to update drawings etc)			
Feed with 500mm cable. feed from KSS-001. set O/L protection at 100 amps			

Additional Photos			
Electrical Worker Completed the Work	Trent Minton		Electrical Workers Signature



Electrical Work Request Form

Request Number	1WRELAM597	Date required	2025-08-13
Location	Lot 2 B6 south		
Requestor	Ben Maher	Assigned Worker	Trent Minton
Description Of Task Requested Extend and re test SPER room fan isolator			
Electrical supervisors' comments N.A			
Electrical Design Required?	Yes	COC Required?	Yes
		Test Document Number	
Design Comments (consider cable sizing, circuit loading, Voltage drop fault, loop impedance, lighting level design, requirement to update drawings etc) N.A			
Additional Photos			
Electrical Worker Completed the Work			
		Electrical Workers Signature	



Electrical Work Request Form

Request Number	1WRELAM598	Date required	2025-08-12
Location	Lot 2 B6 south		
Requestor	Ben Maher	Assigned Worker	Trent Minton
Description Of Task Requested	Extend and re route feeds to CER room isolators		
Electrical supervisors' comments N.A			
Electrical Design Required?	Yes	COC Required?	Yes
Test Document Number	TS 848		
Design Comments (consider cable sizing, circuit loading, Voltage drop fault, loop impedance, lighting level design, requirement to update drawings etc) N.A			
Additional Photos			
Electrical Worker Completed the Work	 		
Electrical Workers Signature			



Electrical Work Request Form

Request Number	1WRELAM596	Date required	2025-08-12
Location	Lot 2 south		
Requestor	Ben Maher	Assigned Worker	Trent Minton
Description Of Task Requested			
relocate RIS south DB into lot 2 B8 south hammer head			

Electrical supervisors' comments

N.A

Electrical Design Required?	Yes	COC Required?	Yes	Test Document Number	TS847
-----------------------------	-----	---------------	-----	----------------------	-------

Design Comments

(consider cable sizing, circuit loading, Voltage drop fault, loop impedance, lighting level design, requirement to update drawings etc)

N.A

Additional Photos


--	--

Electrical Worker
Completed the Work

Electrical Workers
Signature



Electrical Work Request Form

Request Number	1WRELAM580	Date required	2025-08-14
Location	Lot 2 B4 North		
Requestor	Ben Maher	Assigned Worker	Brendan Johnson
Description Of Task Requested			
Re feed lot 2 b4 goods lift. Relocate isolator			
Electrical supervisors' comments			
Lower cable to below roof height. Relocate isolator to lift. Remove all redundant cabling			
Electrical Design Required?	No	COC Required?	Yes
		Test Document Number	TS 846
Design Comments (consider cable sizing, circuit loading, Voltage drop fault, loop impedance, lighting level design, requirement to update drawings etc)			
Additional Photos			
			
Electrical Worker Completed the Work	b.Johnson	Electrical Workers Signature	






Electrical Work Request Form

Request Number

1WRELAM580

Date required

2025-08-14



Electrical Work Request Form

Request Number	1WRELAM580	Date required	2025-08-14
----------------	------------	---------------	------------



Electrical Work Request Form

Request Number	1WRELAM580	Date required	2025-08-14
			



Electrical Work Request Form

Request Number

1WRELAM580

Date required

2025-08-14



Electrical Work Request Form

Request Number	1WRELAM588	Date required	2025-08-15
Location	Lot 2 B8 south		
Requestor	Ben Maher	Assigned Worker	Trent Minton
Description Of Task Requested Install a light above ris south DB			
Electrical supervisors' comments N.A			
Electrical Design Required?	Yes	COC Required?	Yes
			Test Document Number <i>TS 855</i>
Design Comments (consider cable sizing, circuit loading, Voltage drop fault, loop impedance, lighting level design, requirement to update drawings etc) N.A			
Additional Photos 			
Electrical Worker Completed the Work	<i>Paul Gallacher</i>	Electrical Workers Signature	<i>P. Gallacher</i>



Electrical Work Request Form

Request Number	1WRELAM523	Date required	2025-07-28
Location	Lot 1 L0		
Requestor	Ben Maher	Assigned Worker	Jamie Dowling
Description Of Task Requested			
Refeed ELV DB from lot 1 L2 north DB			
Electrical supervisors' comments			
N.A			
Electrical Design Required?	Yes	COC Required?	Yes
Test Document Number			
TS 824.			
Design Comments (consider cable sizing, circuit loading, Voltage drop fault, loop impedance, lighting level design, requirement to update drawings etc)			
N.A			
Additional Photos			
Electrical Worker Completed the Work	Jamie Dowling		Electrical Workers Signature
		J. Dowling	



Electrical Work Request Form

Request Number	1WRELAM595	Date required	2025-08-12
Location	Lot 2 B4 north		
Requestor	Ben Maher	Assigned Worker	Ben Maher
Description Of Task Requested Re route feed to EDBAM04351			
Electrical supervisors' comments N.A			
Electrical Design Required?	No	COC Required?	Yes
Design Comments (consider cable sizing, circuit loading, Voltage drop fault, loop impedance, lighting level design, requirement to update drawings etc)			
Additional Photos			
Electrical Worker Completed the Work			
		Electrical Workers Signature	



Electrical Work Request Form

Request Number	1WRELAM594	Date required	2025-08-12
Location	Lot 2 B4 north		
Requestor	Ben maher	Assigned Worker	Ben Maher
Description Of Task Requested	Re route feed to NDBAM04351		
Electrical supervisors' comments N.A			
Electrical Design Required?	Yes	COC Required?	Yes
Design Comments (consider cable sizing, circuit loading, Voltage drop fault, loop impedance, lighting level design, requirement to update drawings etc)	N.A		
Additional Photos 			
Electrical Worker Completed the Work	Ben Maher		
	Electrical Workers Signature Ben Maher		



Electrical Work Request Form

Request Number	1WRELAM593	Date required	2025-08-12
Location	Lot 2 B4 north		
Requestor	Ben maher	Assigned Worker	Ben Maher
Description Of Task Requested			
Re route feed to EDBAM04352			
Electrical supervisors' comments			
N.A			
Electrical Design Required?	Yes	COC Required?	Yes
			Test Document Number TS 852
Design Comments (consider cable sizing, circuit loading, Voltage drop fault, loop impedance, lighting level design, requirement to update drawings etc)			
N.A			
Additional Photos			
Electrical Worker Completed the Work	Ben Maher		Electrical Workers Signature Ben Maher



Electrical Work Request Form

Request Number	1WRELAM592	Date required	2025-08-12
Location	Lot 2 B4 north		
Requestor	Ben Maher	Assigned Worker	Ben Maher
Description Of Task Requested			
Re route feed to NDBAM04352			
Electrical supervisors' comments			
N.A			
Electrical Design Required?	Yes	COC Required?	Yes
		Test Document Number	
		TS851	
Design Comments (consider cable sizing, circuit loading, Voltage drop fault, loop impedance, lighting level design, requirement to update drawings etc)			
N.A			
Additional Photos			
Electrical Worker Completed the Work	Ben Maher		Electrical Workers Signature
		Ben Maher	



P2

Electrical Work Request Form

Request Number	1WRELAM552	Date required	2025-08-01
Location	Lot 1 B7		
Requestor	Ben Maher	Assigned Worker	Brendan Johnson
Description Of Task Requested			
Remove floodlight cable from pено and refeed through round pено below			
Electrical supervisors' comments			
N.A			
Electrical Design Required?	No	COC Required?	Yes
		Test Document Number	
		TS 840	
Design Comments (consider cable sizing, circuit loading, Voltage drop fault, loop impedance, lighting level design, requirement to update drawings etc)			
Additional Photos			
Electrical Worker Completed the Work	B. Johnson	Electrical Workers Signature	






Electrical Work Request Form

Request Number

1WRELAM552

Date required

2025-08-01



Electrical Work Request Form

Request Number

1WRELAM552

Date required

2025-08-01



Electrical Work Request Form

Request Number	1WRELAM550	Date required	2025-08-01
Location	Lot 2 B6 north		
Requestor	Ben maher	Assigned Worker	Brendan Johnson
Description Of Task Requested Refeed light outside lift. Light can no longer run through wall due to cladding starting			


Electrical supervisors' comments

Refeed light from BOH light string and remove conduit etc going through wall

Electrical Design Required?	Yes	COC Required?	Yes	Test Document Number	TS839
-----------------------------	-----	---------------	-----	----------------------	-------

Design Comments

(consider cable sizing, circuit loading, Voltage drop fault, loop impedance, lighting level design, requirement to update drawings etc)
N.A

Additional Photos


Electrical Worker Completed the Work

B. Johnson

Electrical Workers Signature

Bd





Electrical Work Request Form

Request Number

1WRELAM550

Date required

2025-08-01



Electrical Work Request Form

