





Built-Up Area Estimation Results

Building-1




Depth : 3.22 m
Actual Width length: 3.455 m
Predicted Width length : 3.450 m
Width Error : 0.144 %




Depth : 4.16 m
Actual Width length: 5.80 m
Predicted Width length : 5.812 m
Width Error : 0.207 %

Actual Area: 20.039 m² , Predicted Area : 20.051 m²,
Built-Up Area Error : 0.06 %

Building-2




Depth : 7 m
Actual Width length: 7.7 m
Predicted Width length : 7.691 m
Width Error : 0.116 %




Depth : 4.03 m
Actual Width length: 5.0 m
Predicted Width length : 4.845 m
Width Error : 3.1 %

Actual Area: 38.5 m² , Predicted Area : 37.262 m²,
Built-Up Area Error : 3.215 %

Building-3




Depth : 4.89 m
Actual Width length: 4.12 m
Predicted Width length : 4.114 m
Width Error : 0.145 %



Depth : 3.7 m
Actual Width length: 3.54 m
Predicted Width length : 3.438 m
Width Error : 2.881 %

Actual Area: 14.584 m² , Predicted Area : 14.143 m²,
Built-Up Area Error : 3.023 %

Building-4




Depth : 9.80 m
Actual Width length: 9.95 m
Predicted Width length : 9.580 m
Width Error : 3.718 %



Depth : 3.45 m
Actual Width length: 5.00 m
Predicted Width length : 4.836 m
Width Error : 3.280 %

Actual Area: 49.75 m² , Predicted Area : 46.328 m²,
Built-Up Area Error : 6.876 %

Building-5



Depth : 11.50 m
Actual Width length : 19.60 m
Predicted Width length : 20.680 m
Width Error : 5.51 %




Depth : 4.45 m
Actual Width length : 6.45 m
Predicted Width length : 6.524 m
Width Error : 1.147 %

Actual Area: 126.42 m² , Predicted Area : 134.916 m²,
Built-Up Area Error : 6.72 %

Building-6



Depth : 9.15 m
Actual Width length : 11.64 m
Predicted Width length : 11.644 m
Width Error : 0.034 %



Depth : 6.05 m
Actual Width length : 5 m
Predicted Width length : 4.993 m
Width Error : 0.14 %

Actual Area: 58.2 m² , Predicted Area : 58.138 m²,
Built-Up Area Error : 0.106 %

Building-7



Depth : 9.30 m
Actual Width length : 12.50 m
Predicted Width length : 12.489 m
Width Error : 0.088 %




Depth = 4.70 m
Actual Width length = 6.80 m
Predicted Width length = 6.850 m
Width Error = 0.735 %

Actual Area: 85 m² , Predicted Area : 85.549 m²,
Built-Up Area Error : 0.645 %

Building-8




Depth : 11.1 m
Actual Width length : 17.50 m
Predicted Width length : 16.915 m
Width Error : 3.342 %




Depth : 4.50 m
Actual Width length : 6.90 m
Predicted Width length : 7.054 m
Width Error : 2.231 %

Actual Area: 120.75 m² , Predicted Area : 119.318 m²,
Built-Up Area Error : 1.185 %

Building-9




Depth : 8.70 m
Actual Width length : 14.25 m
Predicted width : 14.570 m
Width Error : 2.245 %




Depth : 4.5 m
Actual Width length : 7.35 m
Predicted width : 7.133 m
Width Error : 2.952 %

Actual Area: 104.737 m² , Predicted Area : 103.927 m²,
Built-Up Area Error : 0.773 %

Building-10




Depth : 14.80 m
Actual Width length : 17.00 m
Predicted Width length : 16.335 m
Width Error : 3.911 %




Depth : 9.0 m
Actual Width length = 9 m
Predicted Width length = 8.671 m
Width Error = 3.655 %

Actual Area: 153 m² , Predicted Area : 141.640 m²,
Built-Up Area Error : 7.424 %

Building-11




Depth : 5.10 m
Actual Width length : 6.90 m
Predicted Width length : 6.977 m
Width Error : 1.115 %




Depth = 15.50 m
Actual Width length = 26.65 m
Predicted Width length = 27.562 m
Width Error = 3.422 %

Actual Area: 183.885 m² , Predicted Area : 192.30 m²,
Built-Up Area Error : 4.576 %

Building-12




Depth : 18 m
Actual Width length : 27.50 m
Predicted Width length : 26.335 m
Width Error : 4.236 %




Depth : 5 m
Actual Width length : 7.90 m
Predicted Width length : 7.971 m
Width Error : 0.898 %

Actual Area: 217.25 m² , Predicted Area : 209.916 m²,
Built-Up Area Error : 3.375 %

Building-13




Depth : 5.85 m
Actual Width length: 9.20 m
Predicted Width length : 9.459 m
Width Error : 2.815 %



Depth : 2.50 m
Actual Width length: 3.56 m
Predicted Width length : 3.530 m
Width Error : 0.842 %

Actual Area: 32.752 m² , Predicted Area : 33.39 m²,
Built-Up Area Error : 1.948 %

Building-14




Depth : 3 m
Actual Width length: 3.4 m
Predicted Width length : 3.504 m
Width Error : 3.05 %



Depth : 2.50 m
Actual Width length: 3.4 m
Predicted Width length : 3.371 m
Width Error : 0.852 %

Actual Area: 11.56 m² , Predicted Area : 11.811 m²,
Built-Up Area Error : 2.171 %

Building-15




Depth : 5.16 m
Actual Width length: 3.58 m
Predicted Width length : 3.499 m
Width Error : 2.262 %




Depth : 4.93 m
Actual Width length: 4.81 m
Predicted Width length : 4.641 m
Width Error : 3.513 %

Actual Area: 17.219 m² , Predicted Area : 16.238 m²,
Built-Up Area Error : 5.697 %

Building-16




Depth : 4.95 m
Actual Width length: 7.53 m
Predicted Width length : 7.613 m
Width Error : 1.102 %




Depth : 5.20 m
Actual Width length: 2.8 m
Predicted Width length : 2.723 m
Width Error : 2.75 %

Actual Area: 21.084 m² , Predicted Area : 20.730 m²,
Built-Up Area Error : 1.678 %

Building-17




Depth : 3.6 m
Actual Width length: 3.74 m
Predicted Width length : 3.671 m
Width Error : 1.844 %




Depth : 3.85 m
Actual Width length: 2.88 m
Predicted Width length : 2.831 m
Width Error : 1.70 %

Actual Area: 10.771 m² , Predicted Area : 10.392 m²,
Built-Up Area Error : 3.518 %

Building-18



Depth : 4.06 m
Actual Width length: 6.7 m
Predicted Width length : 6.564 m
Width Error : 2.029 %




Depth : 4.42 m
Actual Width length: 6.66 m
Predicted Width length : 6.345 m
Width Error : 4.729 %

Actual Area: 44.622 m² , Predicted Area : 41.648 m²,
Built-Up Area Error : 6.663 %

Building-19



Depth : 11.80 m
Actual Width length : 17.00 m
Predicted Width length : 18.106 m
Width Error : 6.506 %




Depth : 9.0 m
Actual Width length = 9 m
Predicted Width length = 8.671 m
Width Error = 3.655 %

Actual Area: 153 m² , Predicted Area : 156.997 m²,
Built-Up Area Error : 2.612 %

Building-20




Depth : 5.61 m
Actual Width length: 10.00 m
Predicted Width length : 9.496 m
Width Error : 5.04 %




Depth : 3.41 m
Actual Width length: 4.580 m
Predicted Width length : 4.511 m
Width Error : 1.506 %

Actual Area: 45.80 m² , Predicted Area : 42.836 m²,
Built-Up Area Error : 6.470 %

Building-21



Depth : 3.45 m
Actual Width length: 4.09 m
Predicted Width length : 3.959 m
Width Error : 3.202 %




Depth : 3.58 m
Actual Width length: 2.86 m
Predicted Width length : 2.818 m
Width Error : 1.468 %

Actual Area: 11.697 m² , Predicted Area : 11.156 m²,
Built-Up Area Error : 4.621 %

Building-22



Depth : 5.40 m
Actual Width length: 6.20 m
Predicted Width length : 6.147 m
Width Error : 0.854 %



Depth : 4.80 m
Actual Width length: 4.02 m
Predicted Width length : 3.935 m
Width Error : 2.114 %

Actual Area: 24.924 m² , Predicted Area : 24.188 m²,
Built-Up Area Error : 2.951 %

Summary of Built-Up Area Estimation Results

Error Metric	Estimated Width Error (%)	Estimated Built-Up Area Error (%)
Mean error	2.298	3.469
Standard deviation error	1.610	2.354
Maximum error	6.506	7.424