

WEB VAPT EVIDENCE FILE DOCUMENTATION

06-gobuster-directory-results.png

Field	Details
Project	Enterprise Security Assessment Lab
Module	Sub-Project 1 - Web Application VAPT
Evidence Row	06 - Gobuster enumeration
Evidence File	06-gobuster-directory-results.png
Result Type	Directory discovery
Prepared For	GitHub portfolio documentation

Document Purpose

This PDF documents one specific evidence file from the Web VAPT evidence table. It embeds the actual screenshot, explains what the screenshot proves, maps it to the methodology, and records professional interpretation, risk, remediation, and redaction guidance for GitHub publication.

1. Embedded Evidence Screenshot




Figure 1 - Actual screenshot evidence: 06-gobuster-directory-results.png

What this screenshot proves

The screenshot shows Gobuster discovering paths such as docs, external, config, vulnerabilities, and server-status style responses.

2. Evidence Context

Area	Value
Testing Phase	Directory and File Enumeration
Tool / Component	Gobuster
Objective	Discover hidden directories and files on the local DVWA target.
Result Type	Directory discovery

3. Command / Workflow Used

```
gobuster dir -u http://localhost -w /usr/share/wordlists/dirbuster/directory-list-2.3-medium.txt -o gobuster_results.txt
```

The commands or workflow above represent the evidence-producing action. Placeholders such as , , or should be used in public documentation instead of live secrets or private infrastructure details.

4. Professional Interpretation

The screenshot shows Gobuster discovering paths such as docs, external, config, vulnerabilities, and server-status style responses.

This evidence should be treated as a supporting artifact, not as a standalone finding by itself. In a professional report, the screenshot supports a specific testing phase, validates an observation, and strengthens reproducibility when paired with methodology and remediation guidance.

5. Security Risk / Why It Matters

Exposed directories can reveal sensitive functions, configuration files, setup pages, and administrative surfaces.

For this portfolio project, the risk is described in a real-world context while clearly noting that the target was an authorized DVWA/local lab environment. This avoids exaggerating lab results as production impact.

6. Recommended Remediation / Defensive Control

Remove unused paths, restrict sensitive directories, disable directory listing, and protect admin/setup areas with authentication.

7. GitHub Redaction Requirements

Internal URLs, sensitive discovered paths, server names, and any accidental non-lab domain information.

Before pushing to GitHub, confirm that screenshots do not expose cookies, session IDs, credentials, hashes, cracked passwords, private IPs, internal file paths, or any secret values. If the screenshot already contains sensitive information, blur or crop it before upload.

8. GitHub README Link Snippet

```
[Open Evidence PDF](./reports/evidence-file-documentation-with-screenshots/06_06-gobuster-  
directory-results_evidence_documentation.pdf)
```

Legal and Ethical Note

This evidence documents authorized testing against an intentionally vulnerable local lab target. The techniques described must not be used against public or third-party systems without explicit permission.