



a STEP/B-rep preflight (all 528 models)



FreeCAD/OCCT 7.8.1 cross-check: 528/528.


No healing/sewing; same kernel family.

b End-to-end Dual Contouring



4 misses reappear at resolution 32 or 48.

c Oracle-diagnostic QEF coverage



Pooled: 22.73%

Measured mesh errors; not deployable certificates.