


Dealer Quality Assessment - Detailed Report

Dealer name	Location
BR FRANCE COLORADO	ST SHTQ Trecho 01 Avenida Comercial, Loja 11 - SN 71551-010 Brasilia Brazil
Dealer code	RRG
07601038	NO
NV Renault Sales / year	NV Dacia Sales / Year
200	0
Workshop Customers / Day	Principal Audited Brand
8	RENAULT
Auditor	Audit Date
MENEZES-DAVID CRISTIANE	14/06/2024




NEW VEHICLES ACTIVITY - 95%



100% - CUSTOMER JOURNEY



88% - PRODUCT PRESENTATION



90% - PREPARATION / DELIVERY



100% - ORDER MANAGEMENT



100% - MANAGEMENT

AFTERSALES ACTIVITY - 99%



100% - APPOINTMENT BOOKING / PREPARATION



100% - RECEPTION



100% - PRODUCTION



86% - RESTITUTION



100% - MANAGEMENT

ZOOM



100% - Basics Sales Methods



93% - BRAND STORE RENAULT



100% - Basics Aftersales Methods



100% - FLASH ARES MAINTENANCE

Strengths (Sales & After Sales only)	Weaknesses (Sales & After Sales only)
Vendas Área interna do showroom atende aos padrões da marca em termos de limpeza, organização e imagem visual Todos os dossiês de VNs vendidos e entregues estão completos Avaliações individuais de desempenho e sessões de aconselhamento com os membros da equipe ocorrem de acordo com o preconizado Pós Vendas Dados dos clientes e informações do veículo são registrados e confirmados na recepção Serviço de revisão foi executado conforme os padrões estabelecidos Na devolução do veículo, relatório da avaliação eletrônica e checklist de manutenção foram explicados e entregues ao cliente	Vendas 1 dos totens de preços do showroom estava com as informações invertidas (na frente constavam os acessórios, no verso, a ficha técnica do veículo, preço e emissões) A entregadora técnica não soube dizer prontamente que também consulta os guias de entrega para atualizar-se sobre os produtos Pós Vendas 1 dos dossiês de serviço realizado (revisão) não continha o relatório da avaliação eletrônica com a Clip

DIGITAL

DIGITAL RENAULT - 43%



45% - JOURNEY
EXPERIENCE



39% - Website conformity

Digital Score

43%

dealership's digital website main items to improve

Link do GMB direciona o cliente para o site do grupo

O ícone da Renault na URL não atende aos padrões e o nome Renault não é visível no link

Cores utilizadas no site não correspondem às cores-padrão estabelecidas

GUIs não são as preconizadas

Logotipos não estão corretamente posicionados

[CONFIDENTIALITY & PERSONAL DATA PROCESSING] Given the nature of this document and the included personal data, the use of this document is strictly restricted to professional use for which it is intended and to authorized individuals only : Renault group employees, Renault group partners, and Renault group service providers. As the recipient of this document, it is your responsibility to maintain its confidentiality and to restrict redistribution only to authorized individuals.

95 %

NEW VEHICLES ACTIVITY

100 %

CUSTOMER JOURNEY

10 - The dealership exterior is in impeccable condition, is clean and is well maintained



Parte externa atende aos padrões em termos de limpeza e conservação



OK - The exterior appearance of the dealership is in impeccable condition

10b - The exterior area respects the visual charter of the Renault brand




Fachada encontra-se em conformidade com os padrões de identidade visual da marca



OK - The exterior area respects the visual charter of the Renault brand

11 - The Renault Showroom Interior is in perfect condition




OK - The interior appearance of the dealership is in perfect condition

11b - The Showroom respects the visual charter of the Renault brand



OK - The showroom respects the visual charter of the Renault brand

12 - The Renault showroom furniture is clean and well maintained



OK - The showroom furniture is in good condition and properly maintained

13 - The Renault sales desks are correctly positioned (away from the windows) and in perfect condition



OK - The sales desk are correctly positioned and in perfect condition

14 - Washrooms / Toilets are available for customer use. They are identified, clean, well lit and usable



OK - The customer toilets are accessible and in a compliant state

15 - The customer waiting area is suitable for waiting & up to standard



OK - The furniture in the customer area is clean and compliant as a waiting area

17 - Sales staff wear appropriate and identifiable business attire



OK - Sales staff are identifiable

49b - There is a 24/7 accessible charging station for electric vehicles




Não se aplica ao Brasil

88 %

PRODUCT PRESENTATION

22 - New vehicles are presented according to the Renault brand's standards




OK - New vehicles are displayed according to the brand's standards

23 - The Renault price-product display stands are compliant



1 dos totens estava com as informações invertidas (na frente os acessórios, no verso, ficha técnica, preço e emissões)



KO - The Renault price displays are not compliant or do not contain the current mandatory information

25 - The new vehicles exhibited in the Renault Showroom are in perfect condition



OK - The vehicles on display are in perfect condition

26 - The vehicles on display all have a charged battery



OK - The vehicles on display are all charged

28 - The demonstrator fleet adheres to the model / engine recommendations




Concessionária segue as orientações da marca para a frota do test drive



OK - There is a demonstrator vehicle fleet compliant with the recommendations of the subsidiary

29 - Demonstrator vehicles are present in the Test Drive area and ready to be driven



OK - The vehicles of the demonstrator fleet are present in the dedicated area, ready to be driven according to the manufacturer's standards

29a - The Demonstrator vehicles are clean, inside and out




OK - Demonstrator fleet vehicles are clean and ready for use

29b - Qualitative demonstration/Test drive reports are completed following vehicle demonstration drives



Fichas são preenchidas e utilizadas para conversão de vendas




OK - The qualitative reports following the vehicle tests are all carried out and are in conformity

90 %

PREPARATION / DELIVERY

46 - The personnel in charge of preparing the vehicle are aware of the latest technical information



OK - The person in charge of technical preparation knows the latest information

48 - The dealership has recommended chargers in sufficient number



Concessionária dispõe de 1 carregador Ateq BC512




OK - The dealership has the regulatory battery charger and it is fully functional

49 - There is an electric vehicle charging station for new vehicle preparation



Concessionária não homologada para VE

51 - The preparation area meets the manufacturer's standards



OK - The preparation area complies with the recommendations and is clean and tidy

52 - The preparation staff have been warned of the electrical risks



Concessionária não homologada para VE

53 - The handover area meets the manufacturer's standards



OK - The handover area complies with manufacturer standards

54 - The Renault vehicles to be delivered are presented to the customer according to the recommendations, with the appropriate delivery covers




OK - covers are present in good number (4 different sizes) and are in good condition

55 - The staff that perform handovers are aware of the latest product innovations and respect manufacturer's recommendations



Entregadora técnica demonstrou as 5 de acordo com os padrões estabelecidos, entretanto não soube dizer prontamente que consulta os guias de entrega para conhecer os produtos e se atualizar. Citou e mostrou que usa as plataformas da Renault, como o R-Learning.



KO - The person in charge of the handover doesn't know the 5-step method, and/or doesn't know the latest product innovations

100 %

ORDER MANAGEMENT

35 - The customer is informed of the late delivery of their vehicle



Não houve ocorrências de atrasos na entrega de VNs

36 - Customers receive an order confirmation within three days



Mensagem de boas-vindas é enviada ao cliente de acordo com o preconizado

OK - The validated order is confirmed to customers

37 - Product update operations are closely monitored



Para os 5 dossiês verificados, as OTSs foram verificadas conforme o preconizado

OK - The presence of OTS is systematically checked in ICM and there is a trace of the consultation

40 - Customer files are complete




Todos os arquivos checados estão completos

OK - The customer files checked were complete and contained all the standard documents expected

41 - The customer is contacted the day before delivery



Mensagem de confirmação é enviada ao cliente 24 horas antes da entrega do VN



OK - Customers are systematically contacted 24 hours before delivery as a reminder

41b - The delivery date is planned taking into account the preparation process of the vehicle (assembly of accessories)




Acessórios foram instalados antes da entrega do VN para os dossiês verificados

OK - The delivery date was planned taking into account the process of fitting the accessories

43 - The customer is systematically contacted within five working days following the handover



Mensagem é enviada ao cliente em tempo hábil




OK - Customers systematically receive a post-delivery call and this is followed up by the Sales Manager

57 - There is an internal or company procedure for dealing with customer issues or complaints



Reclamações são registradas no CRM, que envia os eventos ao gestor e à gerente de qualidade e acompanha as tratativas.




OK - There is an up-to-date customer complaints log

58 - The Sales Manager organizes individual reviews regularly & specific coaching sessions to improve the skills of the team



Avaliações individuais de desempenho e reuniões de feedback são realizadas mensalmente, bem como sessões de aconselhamento ocorrem regularmente



OK - There is a planned and formalized coaching approach for sales staff

60 - There is a monthly meeting to review the latest quality data on NV activity & gives rise to the necessary measures to improve the situation



Reuniões de qualidade ocorrem uma vez ao mês e geram planos de ação




OK - A formalized quality meeting is carried out every month & give rise to measurable action plans

63 - There are brief daily meetings to drive sales and quality



Reuniões diárias são conduzidas sistematicamente



OK - The Sales Manager leads a short daily meeting in front of a tracking board or digital support

99 %

AFTERSALES ACTIVITY

100 %

APPOINTMENT BOOKING / PREPARATION

101 - Provisions have been made in order to receive telephone appointments




Agendamentos realizados pelo CRM da central do grupo, em Taguatinga

OK - Appointments are made by dedicated staff

102 - When making an appointment, all customer details & all vehicle information are documented and alternative mobility solutions are proposed



Dados do cliente e informações do veículo são registrados e confirmados, assim como soluções de mobilidade são oferecidas e confirmadas na recepção



OK - When making the appointment, all customer data/vehicle information is are documented and alternative mobility solutions are offered

104 - As soon as an appointment is made, recall operations are checked



OK - For each appointment ICM is consulted

107 - All files are complete & are prepared the day before



3 agendamentos no dia (2 na parte da manhã, 1 à tarde) 3 arquivos preparados em D-1 Todos completos

OK - all prepared files are ready the day before, and all files are complete

109 - Spare parts are prepared in advance & are made available to the workshop in a compliant manner



Peças são separadas no dia anterior e estão disponibilizadas corretamente




OK - Spare parts are always prepared in advance and are made available to the workshop in labelled boxes or lockers

111 - The customer receives confirmation of their appointment by SMS or email



Mensagem de confirmação do agendamento é enviada sistematicamente ao cliente




OK - The customer systematically receives an appointment confirmation

112 - The customer is contacted the day before as a reminder of their appointment



Lembrete do agendamento é enviado em D-1




OK - The customer is systematically contacted the day before the appointment and there is a trace of the confirmation

113 - Access to the after-sales services is identifiable upon arrival at the dealership



Acesso de fácil identificação




OK - Access to the after-sales services is identifiable upon arrival at the dealership

114 - The reception area complies with the brand's recommendations and is in impeccable condition



OK - The reception area complies with the standards and is perfectly maintained

115 - Front-office staff wear appropriate business attire to allow customers to identify them




OK - All front-office staff wear standard badges and uniforms

116 - The presence of recall operations is checked at reception



OTS consultada na recepção na presença do cliente




OK - The Service Advisor consults the OTS screen in ICM

117 - At the reception, incident resolution requests are properly documented (MCS codes)



OK - MCS codes are systematically present on all checked files

118 - The vehicle inspection area is present and complies with the recommendations




OK - The vehicle inspection area is in perfect condition and complies with the recommendations

119 - During the reception, a vehicle inspection done according to the standard is systematically carried out




OK - The vehicle inspection is systematically carried out respecting the manufacturer standards

120 - Customer vehicles are properly protected and disinfected



OK - All the driving seat position protections are fitted correctly

122 - The Service Advisor checks all points outside the vehicle




OK - All of the vehicle's exterior points are checked as per the standards

124 - For each intervention there is a price commitment to the customer



Preço total e detalhado presente em todas as OSs checadas




OK - Overall price and detailed prices are correctly noted in checked files and Repair Orders are signed by customers

125 - In the files, estimated collection times are noted and personalized



Horários previstos para retirada são personalizados



OK - In the files, the estimated collection times are noted and personalized to the customer


100 %

PRODUCTION

127 - The customer is contacted to notify him/her of additional work



Mensagem é enviada ao cliente quando há serviço adicional






OK -The customer is systematically contacted to inform them of additional work

128 - In case of additional work, a quote is systematically done and transmitted to the customer




Orçamento é enviado ao cliente e aprovação ou reprovação são registrados







OK - An additional estimate is systematically sent to the customer

129 - The technician has the equipment and tools at their disposal to carry out vehicle maintenance



OK - All the equipment and tooling is available to the technician

130 - The technician has all the documents at their disposal to carry out vehicle maintenance






OK - The technician has the documents necessary to carry out the service and refers to them

131 - The electrical functions of the vehicle are checked



OK - All the vehicle's electrical functions have been checked

133 - An electronic assessment of the vehicle is carried out (only for RENAULT cars)



OK - The assessment of the vehicle's electronic control units (ECU) was carried out during the observed service

134 - In the event of a stored fault, the technician performs a diagnostic



Técnico mecânico explica que, quando trata falha memorizada e a avaria se confirma, procura o Cotech para as providências, que podem ser substituição de peças ou até abertura de chamado técnico na montadora

OK - Stored faults are correctly processed by the technician

136 - Fluid replacement and top up is carried out according to the manufacturer's recommendations



OK - The oil filter is changed in accordance with the manufacturer's recommendations

138 - The wheels of the vehicle are checked



OK - The 5 checkpoints have been carried out on all the wheels

139 - The front brakes of the vehicle are checked




OK - The brakes check complies with that of the repair methods

140 - The oil used conforms to the manufacturer's recommendations




Técnico mecânico demonstra utilizar o programa de manutenção do ICM para verificar o óleo a ser utilizado (no serviço presente: 10W40)





OK - The standard of oil used is in accordance with the ICM sheet

141 - Checking the oil level complies with the manufacturer's recommendations



OK - The oil level on the dipstick is correct

142 - The workshop is clean and tidy




OK - The workshop is clean and tidy

143 - Measures exist to ensure workshop cleanliness



Concessionária utiliza metodologia 5S para o controle da limpeza e organização da oficina




OK - There are procedures in place to ensure long-term workshop cleanliness

144 - There is a dedicated High Voltage Zone workstation for the maintenance of electric vehicles



Concessionária não homologada para VE

145 - The quality of the work carried out is checked



OK - A quality control of the work carried out is performed regularly using the standard document

86 %

RESTITUTION

146 - The file is finalized before the vehicle restitution to the customer




Arquivo do serviço finalizado está completo

OK – The files are checked and finalized before the customer arrives to collect their vehicle

147 - Customer files are complete before archiving



1 dossiê de serviço executado não continha o relatório da avaliação eletrônica com a Clip (revisão 50.000KM)






PA - One of the files checked was incomplete

148 - A message is sent to inform the customer of the availability of their vehicle



Cliente é contatado quando veículo está pronto para retirada



OK - The call or text message to the customer to let them know that their vehicle is ready for collection is evidenced in the file

148b - The Restitution starts with the explanation of the Price and the invoice



Devolução tem início com a explicação do serviço realizado (protocolo Brasil)

148c - On collection, the CLIP Electronic Computer Check Report is explained and given to the customer



Relatório da avaliação eletrônica com a Clip foi explicado e entregue ao cliente

OK - Service Advisor explained the CLIP Electronic Computer Check Report and gave it to the customer

148d - On collection, the Control Certificate was explained and given to the customer



Checklist de manutenção foi explicado e entregue ao cliente

OK - The Service Advisor explained the Control Certificate and gave it to the customer

148e - On collection, the vehicle's protections were removed in front of the customer



OK - The protections of the vehicle were removed in front of the customer



100 %

MANAGEMENT

149 - A daily after-sales briefing takes place



Reuniões diárias são conduzidas sistematicamente





OK - A daily briefing is carried out

150 - The Aftersales Manager organizes observations in order to improve the skills of the team



Gestor realiza bimestralmente avaliações individuais de desempenho, utiliza também como base comportamento observado no período



OK - Coaching sessions are organised regularly

151 - A formalized AFS quality meeting is carried out every month & actions to improve quality have been put in place



Reuniões de qualidade ocorrem 1 vez ao mês e geram planos de ação



OK - Quality meetings are organised every month with measurable actions

155 - All technical staff have been warned of the electrical risks




Concessionária não homologada para VE

156 - There is a follow-up of returns and alterations for non-compliance of work



Retornos e retrabalhos são registrados e acompanhados no sistema VCR



OK - The returns log/booklet is compliant and up to date

93 %

BRAND STORE RENAULT

10 - The dealership exterior is in impeccable condition, is clean and is well maintained



Parte externa atende aos padrões em termos de limpeza e conservação



OK - The exterior appearance of the dealership is in impeccable condition

10b - The exterior area respects the visual charter of the Renault brand




Fachada encontra-se em conformidade com os padrões de identidade visual da marca



OK - The exterior area respects the visual charter of the Renault brand

11 - The Renault Showroom Interior is in perfect condition




OK - The interior appearance of the dealership is in perfect condition

11b - The Showroom respects the visual charter of the Renault brand



OK - The showroom respects the visual charter of the Renault brand

12 - The Renault showroom furniture is clean and well maintained



OK - The showroom furniture is in good condition and properly maintained

13 - The Renault sales desks are correctly positioned (away from the windows) and in perfect condition



OK - The sales desk are correctly positioned and in perfect condition

15 - The customer waiting area is suitable for waiting & up to standard



OK - The furniture in the customer area is clean and compliant as a waiting area

17 - Sales staff wear appropriate and identifiable business attire



OK - Sales staff are identifiable

22 - New vehicles are presented according to the Renault brand's standards




OK - New vehicles are displayed according to the brand's standards

23 - The Renault price-product display stands are compliant



1 dos totens estava com as informações invertidas (na frente os acessórios, no verso, ficha técnica, preço e emissões)



KO - The Renault price displays are not compliant or do not contain the current mandatory information

25 - The new vehicles exhibited in the Renault Showroom are in perfect condition



OK - The vehicles on display are in perfect condition

53 - The handover area meets the manufacturer's standards



OK - The handover area complies with manufacturer standards

54 - The Renault vehicles to be delivered are presented to the customer according to the recommendations, with the appropriate delivery covers



OK - covers are present in good number (4 different sizes) and are in good condition

113 - Access to the after-sales services is identifiable upon arrival at the dealership




Acesso de fácil identificação




OK - Access to the after-sales services is identifiable upon arrival at the dealership

114 - The reception area complies with the brand's recommendations and is in impeccable condition



OK - The reception area complies with the standards and is perfectly maintained

115 - Front-office staff wear appropriate business attire to allow customers to identify them




OK - All front-office staff wear standard badges and uniforms

118 - The vehicle inspection area is present and complies with the recommendations







OK - The vehicle inspection area is in perfect condition and complies with the recommendations

129 - The technician has the equipment and tools at their disposal to carry out vehicle maintenance



OK - All the equipment and tooling is available to the technician

130 - The technician has all the documents at their disposal to carry out vehicle maintenance






OK - The technician has the documents necessary to carry out the service and refers to them

131 - The electrical functions of the vehicle are checked



OK - All the vehicle's electrical functions have been checked

133 - An electronic assessment of the vehicle is carried out (only for RENAULT cars)



OK - The assessment of the vehicle's electronic control units (ECU) was carried out during the observed service

134 - In the event of a stored fault, the technician performs a diagnostic



Técnico mecânico explica que, quando trata falha memorizada e a avaria se confirma, procura o Cotech para as providências, que podem ser substituição de peças ou até abertura de chamado técnico na montadora

OK - Stored faults are correctly processed by the technician

136 - Fluid replacement and top up is carried out according to the manufacturer's recommendations



OK - The oil filter is changed in accordance with the manufacturer's recommendations

138 - The wheels of the vehicle are checked



OK - The 5 checkpoints have been carried out on all the wheels

139 - The front brakes of the vehicle are checked




OK - The brakes check complies with that of the repair methods

140 - The oil used conforms to the manufacturer's recommendations




Técnico mecânico demonstra utilizar o programa de manutenção do ICM para verificar o óleo a ser utilizado (no serviço presente: 10W40)



OK - The standard of oil used is in accordance with the ICM sheet

141 - Checking the oil level complies with the manufacturer's recommendations



OK - The oil level on the dipstick is correct

43 %

DIGITAL



43 %

DIGITAL RENAULT

45 %

JOURNEY EXPERIENCE

201 - The dealer is correctly represented by Google via his GMB profile





OK - GMB (Google My Business) is correctly used

202 - The link in the GMB section redirects to the correct dealer website (ONLY Renault + group + city)



Link do GMB direciona o cliente para o site do grupo




KO - The GMB link does not redirect (directly) to the good dealer Renault website

211 - The Sales and After Sales Manager ensures all customer-submitted Google RENAULT Reviews are responded on time and answers are qualitative



Avaliações são 100% respondidas, porém as respostas parecem não ser personalizadas




KO - review(s) do(es)n't have a response on time or the answer(s) is/are not qualitative

212 - Renault Internet customer requests are processed according to the standard



Leads são atendidos em tempo hábil e de acordo com os padrões



OK - Internet requests are processed on time and personalized


39 %

Website conformity

203 - The dealer's website is properly viewable on a tablet or mobile device and images/elements are adjusting and adapting to the specific sizes



Site não apresenta alterações quando acessado de outros dispositivos. Avaliação feita no site do grupo.




OK - The dealer website works smoothly either on a pc screen, mobile screen, or tablet screen

204 - The URL specify RENAULT with the correct RENAULT favicon



Ícone da Renault na URL não corresponde ao padrão; nome Renault não é visível. Avaliação feita no site do grupo.




KO - favicon & 'Renault' in the URL don't appear

205 - The website uses the official Renault colors and logotypes



Logotipos estão corretos, mas as cores do site não atendem aos padrões. Avaliação feita no site do grupo.




KO - as soon as either a color or/and logotype used is/are not the correct one(s)

206 - The website has only the official Renault fonts and graphical user interface (GUIs)



Fontes utilizadas e GUIs não estão em conformidade com os padrões da marca. Avaliação feita no site do grupo.





KO - Either the font or/and GUIs are not the right ones

207 - New car visuals respects the standards



Angulação dos veículos não corresponde à preconizada (3/4); ordem de apresentação dos veículos não é a correta, além de não estarem separados por tipo de veículo (passeio, comercial, e-tech). Avaliação feita no site do grupo.




KO - new vehicles visuals don't respect the standards

208 - The elements (navigation, hero, etc) on the homepage are in the recommended position



Logotipos não estão corretamente posicionados; nome da cidade/bairro não vem descrito. Avaliação feita no site do grupo.




KO - The dealer website doesn't respects the recommendations in the guides and all criterias are not met

209 - On the range presentation page only the Renault brand is present, and all prices are displayed without any discount labels or strike lines



Avaliação feita no site do grupo.




OK - brand exclusivity and price display policy are respected

210 - The website has an organized dedicated offers & services page/area



O horário do serviço oferecido não está presente Avaliação feita no site do grupo.



PA - all offers & services are presented, but there is some missing information