

Fleet

Cat 793C

Cat 793D


03/06/2025

03/06/2025

10


12

Equipment	Excellent	Good	Poor	Terrible	Count of Payload	Ratio	Poor & Terrible	Rt R Susp Cyl	Lt R Susp Cyl
TK342		7	8	75	34	0.92	83	4,262.27	4,313.25
Total	2	89	63	1243	430	0.93	1306	4,986.54	4,807.68




SensorName

Multiple selections




Latitude	Longitude	Equipment	BlastName	Destino	Turno	Datetime	Crew	FullNameShovelOperator	FullNameTruckOperator	Average Break Temp
-29.3967430277	-69.9657108282	TK342	ORE-BIN-D	CELDA-F7-4278-84-CC	A	03/06/2025 11:36:00 a.m.	4.00		Omar Marinero	33.00
-29.3962795053	-69.9681410610	TK342	ORE-BIN-D	CELDA-F7-4278-84-CC	A	03/06/2025 10:56:00 a.m.	4.00		Omar Marinero	35.75
-29.3961880830	-69.9644576424	TK342	ORE-BIN-D	CELDA-F7-4278-84-CC	A	03/06/2025 10:54:00 a.m.	4.00		Omar Marinero	34.50
-29.3959427062	-69.9645651771	TK342	ORE-BIN-D	CELDA-F7-4278-84-CC	A	03/06/2025 11:02:00 a.m.	4.00		Omar Marinero	72.00
-29.3952482607	-69.9628824067	TK342	ORE-BIN-D	CELDA-F7-4278-84-CC	A	03/06/2025 11:34:00 a.m.	4.00		Omar Marinero	70.50
Total										53,754.25

Front Side Compliance by Datetime



Rear Side Compliance by Datetime



Equipment

All

▼

21/03/2025



01/05/2025



Fleet

Cat 793C


Cat 793D

CAT 793 Fleet – Correlation Signature Map (ordered by risk)


Granularity: 1 minute | Sensors kept: 13




Blue = weaker/broken link (e.g., cooling can't cool) | Red = stronger link (e.g., retarder dumps heat) | Left strip Risk: Green < 3 | Amber 3-5 | Red ≥ 5 | Grey = no data
Risk is unit-less composite (sum of key |z| values).




Rt R Brk Temp (73) vs Eng Cool Flow (4348)



Eng Load (41) vs Brk/Air Pres (742)




Brake Temp vs Retarder Command (mA) k-means clusters



- Risk level
- Group / Risk
- (1,Normal)
 - (3,Normal)
 - High-Risk

der Command (mA) — k-means clusters



- Risk level
- Normal
 - High-Risk
- Group / Risk
- High-Risk
 - 1
 - 3