


	QUALITY REPORT - FINAL INSPECTION QUALITY CONTROL DEPARTMENT	CODIGO/CODE	CORP-CAL-CF-001
		VERSION/VERSION	2
		FECHA / DATE	21/07/2026
		HOJA/SHEET	1

CERTIFICATE NUMBER :	716108		
SUPPLIER:	AGP COLOMBIA	SUPPLIER ADDRESS:	Cl. 15 ##35-59, Bogotá, Colombia
CLIENT:	BENTELER DE MEXICO SA DE CV	PRODUCTION ORDER:	000011316133
		COLOR:	GREEN LIGHT
VEHICLE:	BMW X5 4D UTILITY	COMPOSITION:	L31-1
AQL:	NOT APPLICABLE	SAMPLE SIZE:	100%
		THICKNESS(mm):	35.100
		PRODUCTION LOT:	0626203068



Dimensional Results

CHARACTERISTICS	1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19	20
Resistance right	0.8																			
Resistencia left	0.9																			
Isolation between electrical systems	0																			
Terminals	6																			
Camara fabric resistance	9.7																			
BLACK BAND EXTERNAL	49																			
BLACK BAND EXTERNAL	162																			
BLACK BAND EXTERNAL	49																			
BLACK BAND EXTERNAL	84																			
BLACK BAND INTERNAL	96																			
BLACK BAND INTERNAL	27																			
BLACK BAND INTERNAL	254																			
Thickness	33.69	33.72	33.65	33.57																
Zona A (Mdop)	69.85	63.23																		
TNT FLEX MEASUREMET	146.3																			
TNT FLEX MEASUREMET	58.55																			
TNT FLEX MEASUREMET	146.9																			
TNT FLEX MEASUREMET	58.88																			
TNT FLEX MEASUREMET	57.86																			
BLACK BAND INTERNAL	27																			
TNT FLEX MEASUREMET	56.99																			
Zona B (Mdop)	78.99	85.63																		

Appearance Results

Black band external	OK	Black band internal	OK
Mirror bracket	OK	Terminals insulation	OK
Logo (art)		Logo (location)	

jacpera


Lina Tovar

Elena Bejarano

INSPECTED
INSPECTOR

CHECKED
QUALITY ENGINEER

AUTHORIZED
QUALITY MANAGER



ITEM	ZONE	DEFECT	SIZE
1	B	Slight contamination	0.00
2	A	Impurity	0.60
3	A	Impurity	0.80
4	B	Contamination	0.00

appearance 1



appearance 2



jcapera

INSPECTED
INSPECTOR

Lina Tovar

CHECKED
QUALITY ENGINEER

Elena Bejarano

AUTHORIZED
QUALITY MANAGER

appearance 3




TNT FLEX



TNT FLEX



TNT FLEX



jcapera

INSPECTED
INSPECTOR

Lina Tovar

CHECKED
QUALITY ENGINEER

Elena Bejarano

AUTHORIZED
QUALITY MANAGER



QUALITY REPORT - FINAL INSPECTION
QUALITY CONTROL DEPARTMENT

CODIGO/CODE	CORP-CAL-CF-001
VERSION/VERSION	2
FECHA / DATE	21/07/2026
HOJA/SHEET	4


TNT FLEX



STEELS



STEELS



STEELS



jcapera

INSPECTED
INSPECTOR

Lina Tovar

CHECKED
QUALITY ENGINEER

Elena Bejarano

AUTHORIZED
QUALITY MANAGER



QUALITY REPORT - FINAL INSPECTION
QUALITY CONTROL DEPARTMENT

CODIGO/CODE	CORP-CAL-CF-001
VERSION/VERSION	2
FECHA / DATE	21/07/2026
HOJA/SHEET	5


Image 1




Image 2



Right Thermograph



Left Thermograph



jcapera

INSPECTED
INSPECTOR

Lina Tovar

CHECKED
QUALITY ENGINEER

Elena Bejarano


AUTHORIZED
QUALITY MANAGER



QUALITY REPORT - FINAL INSPECTION
QUALITY CONTROL DEPARTMENT

CODIGO/CODE	CORP-CAL-CF-001
VERSION/VERSION	2
FECHA / DATE	21/07/2026
HOJA/SHEET	6

Distortion with zebra 0 grades



Distortion with zebra 45 grades



Distortion without zebra



PERIMETRAL DISTORTION



jcapera

INSPECTED
INSPECTOR

Lina Tovar

CHECKED
QUALITY ENGINEER

Elena Bejarano

AUTHORIZED
QUALITY MANAGER

Logo - Traceability




test of torque



Torker test 2



Reflection 1



jcapera

INSPECTED
INSPECTOR

Lina Tovar

CHECKED
QUALITY ENGINEER

Elena Bejarano

AUTHORIZED
QUALITY MANAGER



QUALITY REPORT - FINAL INSPECTION
QUALITY CONTROL DEPARTMENT

CODIGO/CODE	CORP-CAL-CF-001
VERSION/VERSION	2
FECHA / DATE	21/07/2026
HOJA/SHEET	8

Reflection 2



Image 1



Image 2





Image 3



jcapera

INSPECTED
INSPECTOR


Lina Tovar

CHECKED
QUALITY ENGINEER

Elena Bejarano

AUTHORIZED
QUALITY MANAGER

Image 4




MIRROR BRACKET



camara support



CUSTOM STICKER



jcapera

INSPECTED
INSPECTOR

Lina Tovar

CHECKED
QUALITY ENGINEER

Elena Bejarano

AUTHORIZED
QUALITY MANAGER


Lower right



Lower left



Upper central



cable output (pins)



jcapera

INSPECTED
INSPECTOR

Lina Tovar

CHECKED
QUALITY ENGINEER

Elena Bejarano

AUTHORIZED
QUALITY MANAGER



QUALITY REPORT - FINAL INSPECTION
QUALITY CONTROL DEPARTMENT

CODIGO/CODE	CORP-CAL-CF-001
VERSION/VERSION	2
FECHA / DATE	21/07/2026
HOJA/SHEET	11


Double vision




Photo OP



ISRA



Thermograph 1



jcopera

INSPECTED
INSPECTOR

Lina Tovar

CHECKED
QUALITY ENGINEER

Elena Bejarano

AUTHORIZED
QUALITY MANAGER



QUALITY REPORT - FINAL INSPECTION
QUALITY CONTROL DEPARTMENT

CODIGO/CODE	CORP-CAL-CF-001
VERSION/VERSION	2
FECHA / DATE	21/07/2026
HOJA/SHEET	12

Appareance



jcapera

INSPECTED
INSPECTOR

Lina Tovar

CHECKED
QUALITY ENGINEER

Elena Bejarano

AUTHORIZED
QUALITY MANAGER