	QUALITY REPORT - FINAL INSPECTION QUALITY CONTROL DEPARTMENT	CODIGO/CODE	CORP-CAL-CF-001
		VERSION/VERSION	2
		FECHA / DATE	29/09/2026
		HOJA/SHEET	1


CERTIFICATE NUMBER : **752111**


SUPPLIER: AGP COLOMBIA **SUPPLIER ADDRESS:** Cl. 15 ##35-59, Bogotá, Colombia

CLIENT: AMERICAN GLASS PRODUCTS COMPANY **PRODUCTION ORDER:** 000011318623 **COLOR:** GREEN LIGHT

VEHICLE: CHEVROLET EXPRESS VAN **COMPOSITION:** L39-5 **THICKNESS(mm):** 42.340

AQL: NOT APPLICABLE **SAMPLE SIZE:** 100% **PRODUCTION LOT:** 0626204109





Dimensional Results

CHARACTERISTCS	A	B	C	D	E	F	G	H	I	J	K	L	M	N	O	P	Q	R	S	T
Curvature (PBS)	1.8	0	0.1	0.2	1.6	3.5	3.2	2.2	1.4	2.6	3.2	2.2	0.7	0.1	0.1	2.5	2.4	0.5	1.6	2.4


CHARACTERISTCS	1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19	20
sag	7.6																			
Thickness	40.83	40.92	40.55	40.95																
Internal Offset	1.9	1.4	1.1	0.8	1.9	1.6	1.6	1.3	0.1	0	0.5	0	0	0	0.1	0.5	0	0.2	1.5	1
Perimeter	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
Chamfer	144	144	144																	
External black band	88.20	110.7	179.9	111.9																
Internal black band 1	230	110.6	179.9	109.8																
Length Meshes TNT	244	247	240	244																

Appearance Results

Logo (art)		Logo (location)	
Finishing and cleaning edges	OK	Package edge appeareance	OK
Silkscreen appearance	OK	Mass Defects	OK
Black band design	OK	Haze	0.39

ygoliat	Wilson Rubio	Elena Bejarano
INSPECTED **INSPECTOR**	CHECKED **QUALITY ENGINEER**	AUTHORIZED **QUALITY MANAGER**

	QUALITY REPORT - FINAL INSPECTION QUALITY CONTROL DEPARTMENT	CODIGO/CODE	CORP-CAL-CF-001
		VERSION/VERSION	2
		FECHA / DATE	29/09/2026
		HOJA/SHEET	2



ITEM	ZONE	DEFECT	SIZE
1	B	Intern Scratch	5.00
2	B	Color dot	0.80
3	B	Impurity	0.80
4	B	Not visible stain Day Light	0.00
5	B	Bearing	0.00

Appareance 1




Logo - Traceability




ygoliat	Wilson Rubio	Elena Bejarano
INSPECTED **INSPECTOR**	CHECKED **QUALITY ENGINEER**	AUTHORIZED **QUALITY MANAGER**

	QUALITY REPORT - FINAL INSPECTION QUALITY CONTROL DEPARTMENT	CODIGO/CODE	CORP-CAL-CF-001
		VERSION/VERSION	2
		FECHA / DATE	29/09/2026
		HOJA/SHEET	3

Appareance 2 (inner side)



Appareance 3



Appareance External Face




Distortion without zebra




ygoliat	Wilson Rubio	Elena Bejarano
INSPECTED **INSPECTOR**	CHECKED **QUALITY ENGINEER**	AUTHORIZED **QUALITY MANAGER**

Double Image 1



Distortion with zebra at 0°



Distortion with zebra at 45°



ygoliat	Wilson Rubio	Elena Bejarano
INSPECTED **INSPECTOR**	CHECKED **QUALITY ENGINEER**	AUTHORIZED **QUALITY MANAGER**