

	QUALITY REPORT - FINAL INSPECTION QUALITY CONTROL DEPARTMENT	CODIGO/CODE	CORP-CAL-CF-001
		VERSION/VERSION	2
		FECHA / DATE	06/08/2026
		HOJA/SHEET	1

CERTIFICATE **594614**

NUMBER :

SUPPLIER: AGP COLOMBIA

SUPPLIER ADDRESS: Cl. 15 ##35-59, Bogotá, Colombia

CLIENT: AGP SGLASS EUROPE GMBH

PRODUCTION ORDER: 000011169381

COLOR:

GREEN LIGHT

VEHICLE: LAND ROVER

COMPOSITION: L60-5


THICKNESS(mm): 61.340

SENTINEL 4D UTILITY

AQL: NOT APPLICABLE

SAMPLE SIZE: 100%

PRODUCTION LOT: 0825201721



Dimensional Results

CHARACTERISTICS	1	2	3	4
Nom. & Tol.	34±2	37±2	58±2	34±2
External black band	35.2	36.28	59.32	34.5
Nom. & Tol.	65±2	51±2	-	59±2
Internal black band 1	65.14	50.03	59.32	
Nom. & Tol.	83±2	50±2	68±2	67±2
Internal black band 2	82.17	52.20	69.72	67.18
Nom. & Tol.	61±2	61±2	61±2	61±2
Thickness	60.41	60.25	60.32	60.40

CHARACTERISTICS	1	2
Nom. & Tol.	-	-
Hot resistance, Ohms	NA	NA
Nom. & Tol.	-	-
Cold resistance, Ohms	NA	NA
Nom. & Tol.	<89	<275
Mdp Zone 1	NA	NA
Nom. & Tol.	<89	<275
Mdp Zone 2	NA	NA

Appearance Results

Zebra Reflection		Appareance outer side	
Package edge appareance		Black band design	
Silkscreen appareance	✓	Appareance inner side	
Mass Defect		Finishing and cleaning edges	✓
Distortion with zebra at 45°		Color Ap	
Distortion with zebra at 0°		Logo/Traceability	
Distortion without zebra		ISRA.	

wrubio


Wilson Rubio

Elena Bejarano

INSPECTED
INSPECTOR

CHECKED
QUALITY ENGINEER

AUTHORIZED
QUALITY MANAGER




ITEM	ZONE	DEFECT	SIZE
1	B	Intern Scratch	23.00

Picture of Logo



Distortion with zebra at 45°



wrubio

INSPECTED
INSPECTOR


Wilson Rubio

CHECKED
QUALITY ENGINEER

Elena Bejarano

AUTHORIZED
QUALITY MANAGER


Distortion with zebra at 0°




Distortion without zebra



Double Image 1



Package



wrubio

INSPECTED
INSPECTOR

Wilson Rubio

CHECKED
QUALITY ENGINEER


Elena Bejarano

AUTHORIZED
QUALITY MANAGER

Image Reflection 1



Image reflection 2



Appareance 1



Appareance External Face



wrubio

INSPECTED
INSPECTOR

Wilson Rubio

CHECKED
QUALITY ENGINEER

Elena Bejarano

AUTHORIZED
QUALITY MANAGER

Appareance 2 (inner side)




Appareance 3



Logo - Traceability



Logo logistic



wrubio

INSPECTED
INSPECTOR

Wilson Rubio

CHECKED
QUALITY ENGINEER

Elena Bejarano

AUTHORIZED
QUALITY MANAGER