


	QUALITY REPORT - FINAL INSPECTION QUALITY CONTROL DEPARTMENT	CODIGO/CODE	CORP-CAL-CF-001
		VERSION/VERSION	2
		FECHA / DATE	23/07/2026
		HOJA/SHEET	1

CERTIFICATE NUMBER :	682329				
SUPPLIER:	AGP COLOMBIA	SUPPLIER ADDRESS:	Cl. 15 ##35-59, Bogotá, Colombia		
CLIENT:	AGP SGLASS EUROPE GMBH	PRODUCTION ORDER:	000011247567	COLOR:	GREEN LIGHT
VEHICLE:	LAND ROVER SENTINEL 4D UTILITY	COMPOSITION:	L40-2	THICKNESS(mm):	42.000
AQL:	NOT APPLICABLE	SAMPLE SIZE:	100%	PRODUCTION LOT:	0126204764



Dimensional Results							
CHARACTERISTICS	1	2	3	4	CHARACTERISTICS	1	2
Nom. & Tol.	67±3	33±3	108±3	33±3	Nom. & Tol.	0,67-1,24	0,67-1,24
External black band	67.32	34.21	108.7	33.68	Hot resistance, Ohms	0.9	1
Nom. & Tol.	68	36	134	36	Nom. & Tol.	0,67-1,24	0,67-1,24
Internal black band 1	67.39	35.32	133	35.96	Cold resistance, Ohms	0.9	1.2
Nom. & Tol.	297+3	41+3	186+3	51+3	Nom. & Tol.	<175	<175
Internal black band 2	301	44	190	45	Mdp Zone 1	85.63	80.34
Nom. & Tol.	41±2	41±2	41±2	41±2	Nom. & Tol.	<175	<175
Thickness	41.68	41.79	41.88	41.72	Mdp Zone 2	90.32	91.20


Appearance Results			
Image Reflection	NA	Package edge apparence	✓
Silkscreen apparence	✓	Thermographic imaging	NA
Distortion with Zebra at 45	NA	Distortion with Zebra at 0	NA
Distortion with Zebra	NA	double image	NA
Apparence external face	NA	Black band design	NA
Apparence inner side	NA	Finishing and cleaning edges	✓
Gradient	✓	Mass Defect	✓
Color	✓	Logo (art)	

jcapera	Lina Tovar	Elena Bejarano
INSPECTED INSPECTOR	CHECKED QUALITY ENGINEER	AUTHORIZED QUALITY MANAGER




QUALITY REPORT - FINAL INSPECTION
QUALITY CONTROL DEPARTMENT

CODIGO/CODE	CORP-CAL-CF-001
VERSION/VERSION	2
FECHA / DATE	23/07/2026
HOJA/SHEET	2



ITEM	ZONE	DEFECT	SIZE
1	B	Intern Scratch	20.00
2	B	Internal stain	0.00

Appareance 1



Appareance 2 (inner side)



jcapera

INSPECTED
INSPECTOR

Lina Tovar

CHECKED
QUALITY ENGINEER

Elena Bejarano

AUTHORIZED
QUALITY MANAGER



QUALITY REPORT - FINAL INSPECTION
QUALITY CONTROL DEPARTMENT

CODIGO/CODE	CORP-CAL-CF-001
VERSION/VERSION	2
FECHA / DATE	23/07/2026
HOJA/SHEET	3

Appareance 3



Appareance External Face



Distortion with zebra at 0°



Distortion with zebra at 45°



jcaper

INSPECTED
INSPECTOR

Lina Tovar

CHECKED
QUALITY ENGINEER


Elena Bejarano

AUTHORIZED
QUALITY MANAGER


Distortion without zebra




Double Image 1



Termal Photo 1



Termal Photo 2



jcapera

INSPECTED
INSPECTOR

Lina Tovar

CHECKED
QUALITY ENGINEER

Elena Bejarano

AUTHORIZED
QUALITY MANAGER



QUALITY REPORT - FINAL INSPECTION
QUALITY CONTROL DEPARTMENT

CODIGO/CODE	CORP-CAL-CF-001
VERSION/VERSION	2
FECHA / DATE	23/07/2026
HOJA/SHEET	5

Image Reflection 1




Image reflection 2





Image reflection 3



jcapera

INSPECTED
INSPECTOR

Lina Tovar

CHECKED
QUALITY ENGINEER

Elena Bejarano

AUTHORIZED
QUALITY MANAGER