QUALITY REPORT - FINAL INSPECTION
QUALITY CONTROL DEPARTMENT

CODIGO/CODE	CORP-CAL-CF-001
VERSION/VERSION	2
FECHA / DATE	19/09/2026
HOJA/SHEET	1


CERTIFICATE NUMBER : **720630**


SUPPLIER: AGP COLOMBIA **SUPPLIER ADDRESS:** Cl. 15 ##35-59, Bogotá, Colombia

CLIENT: AGP SGLASS EUROPE GMBH **PRODUCTION ORDER:** 000011338108 **COLOR:** GREEN LIGHT

VEHICLE: LAND ROVER SENTINEL 4D UTILITY **COMPOSITION:** L40-2 **THICKNESS(mm):** 42.000

AQL: NOT APPLICABLE **SAMPLE SIZE:** 100% **PRODUCTION LOT:** 0726201166





Dimensional Results

CHARACTERISTICS	1	2	3	4
Nom. & Tol.	67±3	33±3	108±3	33±3
External black band	79.56	33.69	108.8	33.56
Nom. & Tol.	68	36	134	36
Internal black band 1	80.87	36.89	134.2	37.82
Nom. & Tol.	297+3	41+3	186+3	51+3
Internal black band 2	91.29	45.89	190	45.28
Nom. & Tol.	41±2	41±2	41±2	41±2
Thickness	41.58	41.48	41.23	41.33

CHARACTERISTICS	1	2
Nom. & Tol.	0,67-1,24	0,67-1,24
Hot resistance, Ohms	0.9	0.9
Nom. & Tol.	0,67-1,24	0,67-1,24
Cold resistance, Ohms	1.1	1.1
Nom. & Tol.	<175	<175
Mdp Zone 1	80.69	79.69
Nom. & Tol.	<175	<175
Mdp Zone 2	96.99	80.99

Appearance Results

Zebra Reflection	☑	Appareance outer side	☑
Package edge appareance	☑	Black band design	☑
Silkscreen appareance	☑	Appareance inner side	☑
Thermographic imaging	☑	Finishing and cleaning edges	☑
Distortion with zebra at 45°	☑	Logo/Traceability	☑
Distortion with zebra at 0°	☑	Mass Defect	☑
Distortion without zebra	☑	Color Ap	☑
double image	☑		

Wrubio	Wilson Rubio	Elena Bejarano
INSPECTED	CHECKED	AUTHORIZED
INSPECTOR	**QUALITY ENGINEER**	**QUALITY MANAGER**

	QUALITY REPORT - FINAL INSPECTION QUALITY CONTROL DEPARTMENT	CODIGO/CODE	CORP-CAL-CF-001
		VERSION/VERSION	2
		FECHA / DATE	19/09/2026
		HOJA/SHEET	2

Appareance 1




Appareance 2 (inner side)



Appareance 3



Appareance External Face




Wrubio	Wilson Rubio	Elena Bejarano
INSPECTED **INSPECTOR**	CHECKED **QUALITY ENGINEER**	AUTHORIZED **QUALITY MANAGER**

	QUALITY REPORT - FINAL INSPECTION QUALITY CONTROL DEPARTMENT	CODIGO/CODE	CORP-CAL-CF-001
		VERSION/VERSION	2
		FECHA / DATE	19/09/2026
		HOJA/SHEET	3

Distortion with zebra at 0°




Distortion with zebra at 45°



Distortion without zebra




Double Image 1




Wrubio	Wilson Rubio	Elena Bejarano
INSPECTED **INSPECTOR**	CHECKED **QUALITY ENGINEER**	AUTHORIZED **QUALITY MANAGER**

Termal Photo 1



Termal Photo 2



Wrubio	Wilson Rubio	Elena Bejarano
INSPECTED **INSPECTOR**	CHECKED **QUALITY ENGINEER**	AUTHORIZED **QUALITY MANAGER**