QUALITY REPORT - FINAL INSPECTION
QUALITY CONTROL DEPARTMENT

CODIGO/CODE	CORP-CAL-CF-001
VERSION/VERSION	2
FECHA / DATE	19/09/2026
HOJA/SHEET	1


CERTIFICATE NUMBER : **737828**


SUPPLIER: AGP COLOMBIA **SUPPLIER ADDRESS:** Cl. 15 ##35-59, Bogotá, Colombia

CLIENT: AGP SGLASS EUROPE GMBH **PRODUCTION ORDER:** 000011338126 **COLOR:** GRAY LIGHT AUTOMOTIVE

VEHICLE: LAND ROVER SENTINEL 4D UTILITY **COMPOSITION:** L60-5 **THICKNESS(mm):** 61.480

AQL: NOT APPLICABLE **SAMPLE SIZE:** 100% **PRODUCTION LOT:** 0726201184





Dimensional Results

CHARACTERISTICS	1	2	3	4
Nom. & Tol.	**34±2**	**34±2**	**58±2**	**37±2**
External black band	44.46	43.68	39.54	43.70
Nom. & Tol.	**65±2**	**59±2**	**-**	**51±2**
Internal black band 1	64.26	48.49	0	45.40
Nom. & Tol.	**83±2**	**67±2**	**68±2**	**50±2**
Internal black band 2	81.14	53.16	53.56	56.20
Nom. & Tol.	**61±2**	**61±2**	**61±2**	**61±2**
Thickness	60.98	60.97	61.90	60.85


CHARACTERISTICS	1	2
Nom. & Tol.	**-**	**-**
Hot resistance, Ohms	NA	NA
Nom. & Tol.	**-**	**-**
Cold resistance, Ohms	NA	NA
Nom. & Tol.	**-**	**-**
Mdp Zone 1	NA	NA
Nom. & Tol.	**-**	**-**
Mdp Zone 2	NA	NA

Appearance Results

Zebra Reflection	☑	**Appareance outer side**	☑
Package edge appareance	☑	**Black band design**	☑
Silkscreen appareance	☑	**Appareance inner side**	☑
Mass Defect	☑	**Finishing and cleaning edges**	☑
Distortion with zebra at 45°	☑	**Color Ap**	☑
Distortion with zebra at 0°	☑	**Logo/Traceability**	☑
Distortion without zebra	☑	**ISRA.**	


Wrubio	Wilson Rubio	Elena Bejarano
INSPECTED	CHECKED	AUTHORIZED
INSPECTOR	**QUALITY ENGINEER**	**QUALITY MANAGER**

	QUALITY REPORT - FINAL INSPECTION QUALITY CONTROL DEPARTMENT	CODIGO/CODE	CORP-CAL-CF-001
		VERSION/VERSION	2
		FECHA / DATE	19/09/2026
		HOJA/SHEET	2



ITEM	ZONE	DEFECT	SIZE
1	B	Fluff	10.00

Logo - Traceability



Appareance 1



Wrubio	Wilson Rubio	Elena Bejarano
INSPECTED **INSPECTOR**	CHECKED **QUALITY ENGINEER**	AUTHORIZED **QUALITY MANAGER**

Appareance 2 (inner side)




Appareance 3



Appareance External Face



Image Reflection 1



Wrubio	Wilson Rubio	Elena Bejarano
INSPECTED **INSPECTOR**	CHECKED **QUALITY ENGINEER**	AUTHORIZED **QUALITY MANAGER**

Image reflection 2




Image reflection 3



Distortion without zebra



Wrubio	Wilson Rubio	Elena Bejarano
INSPECTED **INSPECTOR**	CHECKED **QUALITY ENGINEER**	AUTHORIZED **QUALITY MANAGER**