
AGP	**QUALITY REPORT - FINAL INSPECTION** **QUALITY CONTROL DEPARTMENT**	CODIGO/CODE	CORP-CAL-CF-001
		VERSION/VERSION	2
		FECHA / DATE	19/09/2026
		HOJA/SHEET	1

CERTIFICATE NUMBER : **742703**

SUPPLIER:	AGP COLOMBIA	**SUPPLIER ADDRESS:**	Cl. 15 ##35-59, Bogotá, Colombia		
CLIENT:	AGP SGLASS EUROPE GMBH	**PRODUCTION ORDER:**	000011338138	**COLOR:**	GREEN LIGHT
VEHICLE:	LAND ROVER SENTINEL 4D UTILITY	**COMPOSITION:**	L60-5	**THICKNESS(mm):**	61.340
AQL:	NOT APPLICABLE	**SAMPLE SIZE:**	100%	**PRODUCTION LOT:**	0726201196





Dimensional Results

CHARACTERISTICS	1	2	3	4
Nom. & Tol.	**34±2**	**37±2**	**58±2**	**34±2**
External black band	35.21	37.25	57.32	34.23
Nom. & Tol.	**65±2**	**51±2**	**-**	**59±2**
Internal black band 1	65.66	50.55	0	59.74
Nom. & Tol.	**83±2**	**50±2**	**68±2**	**67±2**
Internal black band 2	83.88	50.74	68.41	67.88
Nom. & Tol.	**61±2**	**61±2**	**61±2**	**61±2**
Thickness	60.02	60.86	60.91	61.41

CHARACTERISTICS	1	2
Nom. & Tol.	**-**	**-**
Hot resistance, Ohms	NA	NA
Nom. & Tol.	**-**	**-**
Cold resistance, Ohms	NA	NA
Nom. & Tol.	**<89**	**<275**
Mdp Zone 1	NA	NA
Nom. & Tol.	**<89**	**<275**
Mdp Zone 2	NA	NA

Appearance Results

Zebra Reflection	☑	**Appareance outer side**	☑
Package edge appareance	☑	**Black band design**	☑
Silkscreen appareance	☑	**Appareance inner side**	☑
Mass Defect	☑	**Finishing and cleaning edges**	☑
Distortion with zebra at 45°	☑	**Color Ap**	☑
Distortion with zebra at 0°	☑	**Logo/Traceability**	☑
Distortion without zebra	☑	**ISRA.**	


Wrubio	Wilson Rubio	Elena Bejarano
INSPECTED **INSPECTOR**	CHECKED **QUALITY ENGINEER**	AUTHORIZED **QUALITY MANAGER**

	QUALITY REPORT - FINAL INSPECTION QUALITY CONTROL DEPARTMENT	CODIGO/CODE	CORP-CAL-CF-001
		VERSION/VERSION	2
		FECHA / DATE	19/09/2026
		HOJA/SHEET	2

Logo - Traceability



Appearance 1



Appearance 2 (inner side)




Appearance 3



Wrubio	Wilson Rubio	Elena Bejarano
INSPECTED **INSPECTOR**	CHECKED **QUALITY ENGINEER**	AUTHORIZED **QUALITY MANAGER**

	QUALITY REPORT - FINAL INSPECTION QUALITY CONTROL DEPARTMENT	CODIGO/CODE	CORP-CAL-CF-001
		VERSION/VERSION	2
		FECHA / DATE	19/09/2026
		HOJA/SHEET	3

Appareance External Face



Distortion without zebra



Distortion with zebra at 0°



Distortion with zebra at 45°




Wrubio	Wilson Rubio	Elena Bejarano
INSPECTED **INSPECTOR**	CHECKED **QUALITY ENGINEER**	AUTHORIZED **QUALITY MANAGER**

Double Image 1



Image Reflection 1



ISRA





Image reflection 3



Wrubio	Wilson Rubio	Elena Bejarano
INSPECTED **INSPECTOR**	CHECKED **QUALITY ENGINEER**	AUTHORIZED **QUALITY MANAGER**