

# LAPORAN REPAIR KOMATSU INDONESIA

|                  |                                    |
|------------------|------------------------------------|
| Tanggal Repair   | 18-Apr-24                          |
| Jam Berangkat    | 08.25 WIB                          |
| Jam Repair       | 10.45 s/d 16.50                    |
| Jam Kembali      | 18.50 WIB                          |
| Qty Unit Repair  | 21 pcs                             |
| Assy No          | 14X0625321                         |
| Type Unit        | D 65 E                             |
| Jumlah Man Power | 2 Orang                            |
| Driver           |                                    |
| Methode Repair   | Penambahan circuit dan ganti lampu |

Maker of Harness ☐ BEI ☒ NON BEI



Couse of Defect ☐ BEI ☒ NON BEI

## MATERIAL UNTUK REPAIR :

| PART NAME   | PART NO         | QTY        |
|-------------|-----------------|------------|
| Wire        | AVS 0,85 B      | 3.76 Meter |
| Wire        | AVS 0,85 B-W    | 3.75 Meter |
| Wire        | AVS 0,85 R-W    | 2.47 Meter |
| Wire        | AVS 0,85 Y-B    | 9.13 Meter |
| Wire        | AVS 0,85 Y      | 1.43 Meter |
| Terminal    | 1062-16-0122    | 22 pcs     |
| Terminal    | 7116-2873       | 22 pcs     |
| Terminal    | B-2             | 33 Pcs     |
| Terminal    | 300502-0        | 22 Pcs     |
| Terminal    | 300501-0        | 11 Pcs     |
| Terminal    | 110500-2        | 33 Pcs     |
| Terminal    | 7114-1471       | 11 Pcs     |
| Rubber Seal | 7157-3570       | 22 pcs     |
| Rubber Seal | 7157-7811-80    | 11 Pcs     |
| Sleeve      | 7120-8012       | 11 Pcs     |
| Sleeve      | 7120-1010       | 33 Pcs     |
| Retainer    | W2P             | 11 Pcs     |
| Retainer    | 7157-6720       | 11 Pcs     |
| Connector   | DT04-2P-CE03    | 11 Pcs     |
| Connector   | 7123-6423-30    | 11 Pcs     |
| Sumitube    | SA3-1           | 1,55 Meter |
| SH Tube     | SH TUBE D5      | 0,66 Meter |
| COT         | COT D5          | 15.4 Meter |
| VO          | VO-B 5*6        | 1.21 Meter |
| Lampu       | Lampu LED putih | 10 pcs     |
| Resistor    | R 220 ohm 0.5W  | 10 pcs     |

1. Modif harness GAUGE dari assy 14X0625321 ke assy 14X-06-J4510 sebanyak 11 pcs

2. Melakukan Repair Lampu Bulb diganti ke LED sebanyak 10 pcs



CONFIRM "OK"

| Disetujui       | Diperiksa | Dibuat    |
|-----------------|-----------|-----------|
|                 |           |           |
| Asst Manager QA | Leader QA | Repairman |

# LAPORAN REPAIR KOMATSU INDONESIA

|                  |                                                 |
|------------------|-------------------------------------------------|
| Tanggal Repair   | 18-Apr-24                                       |
| Jam Berangkat    | 08.25 WIB                                       |
| Jam Repair       | 10.50 S/D 15.30                                 |
| Jam Kembali      | 18.50 WIB                                       |
| Qty Unit Repair  | 29 pcs                                          |
| Assy No          | 22150615-00                                     |
| Type Unit        | PC135F-10M0                                     |
| Jumlah Man Power | 1 Orang                                         |
| Driver           | -                                               |
| Methode Repair   | Potong Wire ganti terminal dan pasang connector |

Maker of Harness ☐ BEI ☒ NON BEI




Couse of Defect ☐ BEI ☒ NON BEI

## MATERIAL UNTUK REPAIR :

| PART NAME   | PART NO      | QTY    |
|-------------|--------------|--------|
| Terminal    | 7116-2874    | 29 Pcs |
| Rubber seal | 7157-2571-80 | 29 Pcs |
| Connector   | 7123-6214-40 | 29 Pcs |

1. Modif harness PC135F pada posisi AC03 dari connector DT ke connector 7123-6214-40 sebanyak 29 pcs

Before :



After :

2. Assy No



3. Type Unit



CONFIRM "OK"

| Disetujui       | Diperiksa | Dibuat    |
|-----------------|-----------|-----------|
|                 |           |           |
| Asst Manager QA | Leader QA | Repairman |