


T2 backward-facing step

streamwise velocity profiles downstream of the step



skin friction on the lower wall: the zero crossing is the reattachment point

