v5 Blender models: photos of all 404 (final state after fix round 2)

One 3/4 photo per model, grouped by the LATEST independent verdict (front and back views). Under each photo: verdict, id, triangles, size, reviewer note.

FIXED BY THE LEAD (two passes, 118 models): rebuilt and checked by the lead, waiting for YOUR review

118 models on 10 pages (F_fixed_now_01 to F_fixed_now_10)

DEFECTIVE: REDO (rebuild) first, then MAJOR (must fix)

1 models on 1 pages (A_defective_01 to A_defective_01)

SMALL FLAWS: MINOR (fixing optional)

0 models on 0 pages (B_small_flaws_01 to B_small_flaws_00)

GOOD: OK (reviewers saw no reason to fix)

285 models on 24 pages (C_good_01 to C_good_24)

NOT REVIEWED: rebuilt in fix round 2, no independent verdict on this version


0 models on 0 pages (D_not_reviewed_01 to D_not_reviewed_00)

FIXED	rebuilt in this pass, for your review
UNREVIEWED	rebuilt in round 2, no verdict yet
REDO	rebuild from scratch
MAJOR	clearly wrong, must be fixed
MINOR	small flaw, fixing optional
OK	normal and usable

After the groups: four-angle pages (front, back, close-up, elevation) of the big pieces: first the never-rebuilt ones, then the round-2 ones.

OK models can still carry a small reviewer note. A different reviewer can rate the same model one step differently (see the report).

Grey ground and sky are only the photo studio. Roblox colours the pieces from a palette.



FIXED CP02_01_ring_wall_corner_01
3,600 tris | 24 x 24 x 23 studs (x, y, height)

rear terrace closed and the inner wedge filled, like CP02_02 (was an open hollow box from behind)




FIXED CP02_03_ring_wall_corner_03
3,600 tris | 24 x 21 x 23 studs (x, y, height)

rear terrace closed and the inner wedge filled (was an open hollow box from behind)



FIXED CP07_01_gatehouse_main
4,864 tris | 64 x 44 x 54 studs (x, y, height)

finished top: side parapet and a roof hut; side walls get pilasters and windows



FIXED CP13_01_grand_stair_01
2,980 tris | 30 x 41 x 24 studs (x, y, height)

one continuous stair side wall (the black stripes were overlapping faces)




FIXED CP15_01_order_hq_01
13,116 tris | 88 x 70 x 60 studs (x, y, height)

gold star badge replaced by a bronze ring with a small tower glyph



FIXED CP17_01_plaza_features_01
1,244 tris | 28 x 28 x 34 studs (x, y, height)

gold star finial replaced by a dull bronze urn and orb



FIXED CP18_02_quay_wall_02
904 tris | 30 x 10 x 8 studs (x, y, height)

curved quay as plain ashlar masonry with short bollards (was ship-like)




FIXED LM02_01_world_tree_falls
5,228 tris | 80 x 40 x 110 studs (x, y, height)

bark ribs now sit on the trunk; no hanging roots or loose rubble



FIXED LM05_01_fortress_cliff_tower_01
2,996 tris | 34 x 34 x 88 studs (x, y, height)

warm banded rock base (was near-default grey)




FIXED LM05_02_fortress_cliff_tower_02
3,308 tris | 34 x 34 x 80 studs (x, y, height)

thin flaps and the stray green speck removed




FIXED LM06_01_fortress_tunnel_gate
1,200 tris | 60 x 58 x 51 studs (x, y, height)

solid tiered rock gate with a passable tunnel and timber frame (was stacked slabs)




FIXED LM07_01_carved_stair_switchback_01
3,760 tris | 50 x 62 x 62 studs (x, y, height)

solid banded rock tower, stair wedges bolted to the face (was a hollow box with a black void)



FIXED LM07_02_carved_stair_switchback_02
3,760 tris | 50 x 61 x 62 studs (x, y, height)

mirror variant of 01: solid tower, stair bolted to the face



FIXED LM08_01_mountain_span_bridge
5,532 tris | 90 x 16 x 24 studs (x, y, height)

filler boards close the gaps between the deck planks




FIXED LM10_01_temple_colonnade_buried_01
4,960 tris | 60 x 20 x 40 studs (x, y, height)

black seams on the lintels gone



FIXED LM12_01_temple_stair_down_01
2,320 tris | 31 x 40 x 24 studs (x, y, height)

black bars on the stair mass gone




FIXED LM12_02_temple_stair_down_02
2,440 tris | 31 x 40 x 24 studs (x, y, height)

black bars on the stair mass gone




FIXED LM13_01_guardian_statue_01
1,278 tris | 19 x 20 x 70 studs (x, y, height)

shoulders, arms, fists and a spear; the red patch is muted




FIXED LM14_01_sand_obelisk_01
368 tris | 10 x 10 x 60 studs (x, y, height)

square tapered obelisk with warm bands




FIXED LM14_02_sand_obelisk_02
400 tris | 10 x 10 x 58 studs (x, y, height)

octagonal obelisk with collars and a ball finial (different shape from 01)




FIXED LM16_01_ring_temple_segment_01
5,220 tris | 50 x 25 x 38 studs (x, y, height)

base pieces sit on the plinth; black seams removed




FIXED LM16_02_ring_temple_segment_02
4,656 tris | 50 x 25 x 40 studs (x, y, height)

all columns intact under a full entablature, fewer stripes, drums on the plinth




FIXED LM19_04_crater_rim_rock_04
1,320 tris | 60 x 50 x 40 studs (x, y, height)

lighter, warmer lower rock bands (was near-black)




FIXED LM19_05_crater_rim_rock_05
1,308 tris | 60 x 50 x 40 studs (x, y, height)

lighter, warmer lower rock bands (was near-black)




FIXED LM20_01_crater_arcane_ruin_01
952 tris | 38 x 38 x 43 studs (x, y, height)

nine tall pointed shards of different heights on a dais, rune bands (was flat grey shards)




FIXED LM20_02_crater_arcane_ruin_02
1,312 tris | 39 x 39 x 38 studs (x, y, height)

full-size arcane ruin: stone circle, trilithons, rune altar, tall rune pillars




FIXED LM20_03_crater_arcane_ruin_03
764 tris | 38 x 38 x 40 studs (x, y, height)

one great carved monolith on a three-step dais with corner posts (was a bare slab)




FIXED LM21_04_floating_rock_04
348 tris | 40 x 40 x 30 studs (x, y, height)

solid banded root under a grass cap (was a stack of wafers)




FIXED LM23_01_gorge_wall_01
3,456 tris | 96 x 30 x 79 studs (x, y, height)

chunky stacked rock wall in warm bands (was striped slabs with square patches)




FIXED LM24_01_fall_pool_rock_01
468 tris | 30 x 30 x 17 studs (x, y, height)

warm banded rock (was near-default grey)




FIXED LM24_02_fall_pool_rock_02
852 tris | 31 x 30 x 16 studs (x, y, height)

boulder cluster with a table stone, warm colours (was plain grey boxes)




FIXED LM24_03_fall_pool_rock_03
768 tris | 31 x 33 x 17 studs (x, y, height)

leaning rock spires over a boulder ring, different shape from 02




FIXED LM25_01_ruin_gate_hero
1,616 tris | 82 x 31 x 80 studs (x, y, height)

a rubble buttress now carries the lintel end; loose debris removed




FIXED LM26_02_ruin_arena_segment_02
2,044 tris | 60 x 30 x 33 studs (x, y, height)

loose rubble at the base removed




FIXED LM26_03_ruin_arena_segment_03
3,520 tris | 60 x 30 x 33 studs (x, y, height)

banded warm stone and proud string courses (was a plain tan wall)




FIXED LM28_02_ruin_column_set_02
1,320 tris | 24 x 24 x 38 studs (x, y, height)


columns seated on collars, loose stubs removed




FIXED LM29_01_ruin_tower_stump_01
2,456 tris | 24 x 26 x 36 studs (x, y, height)
windows with sills and heads, banded stone (was a featureless cylinder)



FIXED LM29_02_ruin_tower_stump_02
2,352 tris | 28 x 26 x 36 studs (x, y, height)
windows, a rubble ramp and a warmer stone ramp, different from 01



FIXED WT03_02_wizard_bookshelf_curved_02
5,820 tris | 23 x 6 x 28 studs (x, y, height)
ribbed and banded back instead of one dark slab



FIXED WT03_03_wizard_bookshelf_curved_03
4,372 tris | 24 x 6 x 28 studs (x, y, height)
ribbed and banded back instead of one dark slab




FIXED WT04_01_wizard_bookshelf_straight_01
2,196 tris | 15 x 5 x 26 studs (x, y, height)
framed back panel with ribs and cornice




FIXED WT04_02_wizard_bookshelf_straight_02
3,536 tris | 15 x 5 x 26 studs (x, y, height)
corner pinnacles on top, differs from 01




FIXED WT13_01_plateau_terrace_set_01
2,936 tris | 32 x 30 x 10 studs (x, y, height)
paving joints are a soft stone tone, no longer a dark grate



FIXED WT13_02_plateau_terrace_set_02
2,656 tris | 30 x 30 x 10 studs (x, y, height)
closed ends and a plinth under the coping (no void)




FIXED WT13_03_plateau_terrace_set_03
5,288 tris | 29 x 31 x 10 studs (x, y, height)
riser gaps are stone-coloured, no black slots




FIXED WT13_05_plateau_terrace_set_05
2,980 tris | 32 x 33 x 10 studs (x, y, height)
stepped plateau terrace with a cairn on top (was tiny rubble piles)



FIXED WT13_06_plateau_terrace_set_06
3,696 tris | 29 x 29 x 10 studs (x, y, height)
stone lantern with dark openings, no yellow glow




FIXED HL03_02_glacier_tongue_02
720 tris | 90 x 50 x 24 studs (x, y, height)
solid three-step ice tongue, scattered shards removed




FIXED HM01_03_rope_suspension_bridge_03
11,418 tris | 129 x 11 x 14 studs (x, y, height)

deck gets thick side beams, handrails and posts (was thin and spindly)



FIXED HM02_01_timber_cantilever_bridge_01
1,004 tris | 36 x 9 x 12 studs (x, y, height)

stone abutments in warm banded rock (was plain grey)




FIXED HM02_02_timber_cantilever_bridge_02
1,208 tris | 36 x 9 x 12 studs (x, y, height)

warm abutments and an ochre-red roof, clearly different from 01



FIXED HM03_01_tunnel_portal_01
468 tris | 32 x 20 x 25 studs (x, y, height)

rock mass in warm banded colours (was plain grey)




FIXED HM03_02_tunnel_portal_02
564 tris | 32 x 21 x 26 studs (x, y, height)

warm banded rock, no icicle stripes, thicker snow caps




FIXED HM03_03_tunnel_portal_03
1,000 tris | 32 x 20 x 24 studs (x, y, height)

rock mass in warm banded colours (was plain grey)



FIXED HM04_02_tunnel_lining_02
1,216 tris | 24 x 24 x 21 studs (x, y, height)

black corner panels gone (overlapping faces removed)




FIXED HM06_03_switchback_wall_03
1,576 tris | 31 x 14 x 14 studs (x, y, height)

one continuous coping and path line tie the blocks into a wall



FIXED HM08_01_cairn_shrine_01
584 tris | 14 x 14 x 12 studs (x, y, height)

warm banded stones and a proper flag (was grey with a black flag block)



FIXED HM08_03_cairn_shrine_03
616 tris | 13 x 14 x 12 studs (x, y, height)

roof carried by four posts, tie beams and a hub block (was floating)




FIXED HM09_03_monastery_outpost_03
1,436 tris | 38 x 28 x 30 studs (x, y, height)

back face now has windows, door and roof battlements (was a blank white slab)




FIXED FR02_01_forest_ruin_01
1,128 tris | 40 x 30 x 34 studs (x, y, height)

weathered warm stone on the arch (was default grey)



FIXED FR02_02_forest_ruin_02
1,136 tris | 40 x 30 x 34 studs (x, y, height)

light warm stone on the steps, a different tone from 01 and 03




FIXED FR02_03_forest_ruin_03
876 tris | 41 x 30 x 34 studs (x, y, height)

dark warm stone on the wall blocks, a different tone from 01 and 02




FIXED FR02_04_forest_ruin_04
2,172 tris | 43 x 31 x 34 studs (x, y, height)

shrine ruin: warm stone columns, lintel, stone urn (was grey with a bright gold tip)



FIXED FR03_01_cave_mouth_01
648 tris | 40 x 32 x 30 studs (x, y, height)

much wider and taller dark cave mouth (was small and shallow)



FIXED PL02_01_hay_silo_01
1,200 tris | 14 x 14 x 24 studs (x, y, height)

duller natural straw tones (was bright yellow)



FIXED PL05_01_ruined_watchtower_plains_01
2,456 tris | 20 x 20 x 40 studs (x, y, height)

windows, buttresses and a stronger stone ramp (was a plain pale cylinder)



FIXED PL05_02_ruined_watchtower_plains_02
2,720 tris | 20 x 20 x 40 studs (x, y, height)

windows, buttresses and a stronger stone ramp



FIXED PL05_03_ruined_watchtower_plains_03
2,390 tris | 20 x 22 x 40 studs (x, y, height)

windows, buttresses and a stronger stone ramp, broken roof kept



FIXED DS01_01_adobe_house_01
1,202 tris | 20 x 20 x 18 studs (x, y, height)

blue awning strip and loose bits removed



FIXED DS01_05_adobe_house_05
2,288 tris | 20 x 20 x 18 studs (x, y, height)

corner pilasters, plaster bands, base skirt and shutters (was a plain white slab)




FIXED DS04_01_palm_01
3,816 tris | 14 x 14 x 40 studs (x, y, height)

weeping-crown palm kept as the reference shape




FIXED DS04_02_palm_02
2,952 tris | 14 x 14 x 42 studs (x, y, height)

upright flat-crown palm with a date cluster (different silhouette from 01)



FIXED DS06_02_canyon_wall_02
2,880 tris | 127 x 40 x 93 studs (x, y, height)
chunkier slabs in a red-to-cream strata (was thin boards)




FIXED DS06_03_canyon_wall_03
2,988 tris | 125 x 40 x 94 studs (x, y, height)
gradient cliff with a lean, clearly different from 02




FIXED DS07_03_hoodoo_arch_03
1,584 tris | 40 x 30 x 70 studs (x, y, height)
smooth red-to-cream gradient (no camouflage patches), thicker crown




FIXED DS08_02_underground_entrance_02
884 tris | 30 x 31 x 24 studs (x, y, height)
rear pylons thicker and standing on the body




FIXED CO02_01_sea_stack_01
1,176 tris | 40 x 40 x 93 studs (x, y, height)
bare rock top instead of the grass cap



FIXED CO02_02_sea_stack_02
1,400 tris | 40 x 40 x 95 studs (x, y, height)
twin spires in sandstone tones, bare top



FIXED CO02_03_sea_stack_03
1,608 tris | 40 x 40 x 94 studs (x, y, height)
reddish banded rock with the arch, bare top



FIXED CO04_01_sea_arch_01
1,992 tris | 70 x 30 x 60 studs (x, y, height)
wide natural arch with a clear opening, built at full size



FIXED RD04_02_trading_post_02
4,932 tris | 30 x 24 x 20 studs (x, y, height)
hipped roof, balcony, dormer and a different stall row (was a recolour of the neighbours)



FIXED RD06_05_abandoned_house_05
2,968 tris | 22 x 20 x 20 studs (x, y, height)
ruin with a roof slope resting on the back wall and posts (was jumbled tiles)



FIXED VG02_02_tree_old_oak_02
2,832 tris | 27 x 30 x 42 studs (x, y, height)
dead oak with bare branches (different shape from the broken-crown oak 01)



FIXED VG05_01_tree_cypress_swamp_01
1,724 tris | 22 x 23 x 41 studs (x, y, height)
floating hanging strands removed



FIXED VG07_02_boardwalk_02
1,064 tris | 30 x 6 x 4 studs (x, y, height)

double railing on both sides, so it differs from 01



FIXED TW01_01_town1_hero_statue
2,030 tris | 14 x 14 x 38 studs (x, y, height)

belt, chest medallion, shoulder pieces and hem band sharpen the figure




FIXED TW02_01_street_life_01
864 tris | 12 x 10 x 10 studs (x, y, height)

cart now carries sacks, a barrel and a crate (was a white box)




FIXED TW02_03_street_life_03
948 tris | 12 x 9 x 10 studs (x, y, height)

market stall with awning, crates, barrel and sacks (was plain boxes)




FIXED TW02_04_street_life_04
674 tris | 12 x 10 x 10 studs (x, y, height)

jar tops closed with lids, black slits between crates gone




FIXED TW02_07_street_life_07
368 tris | 12 x 10 x 10 studs (x, y, height)

smith's hanging sign with an anvil emblem in light warm colours (was a dark blob)




FIXED RV01_02_bank_rock_02
496 tris | 31 x 20 x 10 studs (x, y, height)

solid stacked bank rock (was a crumpled slab with shards)




FIXED VC01_03_volcanic_rock_03
1,412 tris | 60 x 50 x 60 studs (x, y, height)

twisted spire cluster, loose shards removed



FIXED VC01_04_volcanic_rock_04
1,640 tris | 60 x 50 x 60 studs (x, y, height)

basalt with colour bands and a rust-coloured base




FIXED VC01_06_volcanic_rock_06
1,784 tris | 60 x 50 x 60 studs (x, y, height)

leaning wide variant in a lighter ash tone with a rust base




FIXED VC04_04_skull_city_building_04
1,184 tris | 30 x 30 x 30 studs (x, y, height)

closed gable roof (was an open frame with rafters)



FIXED VC04_06_skull_city_building_06
1,294 tris | 30 x 30 x 30 studs (x, y, height)

lean-to roof as one solid wedge seated on the walls (was a floating plank)




FIXED FL02_01_floating_island_small_01
462 tris | 40 x 40 x 25 studs (x, y, height)

solid cone-shaped root in warm brown rock (was loose chunks)




FIXED FL02_02_floating_island_small_02
462 tris | 41 x 41 x 25 studs (x, y, height)

bulb-shaped root in cooler rock, clearly different from 01




FIXED FL02_03_floating_island_small_03
498 tris | 40 x 40 x 24 studs (x, y, height)

crooked root with hanging tips in banded rock, different from 01 and 02



FIXED SP01_04_snow_spire_cluster_04
1,908 tris | 60 x 60 x 168 studs (x, y, height)

much stouter spire and base (was needle-thin)




FIXED SP01_06_snow_spire_cluster_06
1,644 tris | 60 x 60 x 164 studs (x, y, height)

much stouter spire and base (was needle-thin)




FIXED SD01_03_red_mesa_cluster_03
1,836 tris | 115 x 102 x 95 studs (x, y, height)

loose chunks at the base removed



FIXED SD02_05_desert_ruin_block_05
2,296 tris | 40 x 40 x 30 studs (x, y, height)

thin flaps around the base removed




FIXED HB01_02_harbour_wall_tower_02
470 tris | 24 x 24 x 43 studs (x, y, height)

stone bands on the shaft and a rail joining the lantern posts



FIXED RW01_01_rework_existing_01
3,288 tris | 76 x 70 x 80 studs (x, y, height)

loose planks and fragments around the base removed



FIXED RW01_02_rework_existing_02
404 tris | 24 x 7 x 20 studs (x, y, height)

banded sandstone gateposts with moss, sign between them (was plain grey boxes)




FIXED RW02_01_rework_world_tree_roots
16,492 tris | 198 x 187 x 32 studs (x, y, height)

a real trunk boss where the roots meet, with ribs and moss (was a starfish)




FIXED NE01_03_village_sign_03
252 tris | 10 x 4 x 18 studs (x, y, height)

painted wood board and a stone footing (was white slabs)




FIXED NE02_03_entry_rock_pair_03
880 tris | 31 x 22 x 15 studs (x, y, height)

warm banded rocks (was flat tan)




FIXED EV02_01_canopy_cluster_01
9,920 tris | 70 x 70 x 40 studs (x, y, height)

solid bridges with rails between the platforms (were thin ropes)




FIXED EV02_02_canopy_cluster_02
12,096 tris | 70 x 63 x 44 studs (x, y, height)

solid bridges, red hut roofs and 4 platforms, clearly different from 01




FIXED EV03_01_elf_path_piece_01
1,132 tris | 20 x 20 x 7 studs (x, y, height)

solid root-and-stone stair, closed underside, light step edges, rails



FIXED EV03_02_elf_path_piece_02
1,052 tris | 20 x 18 x 6 studs (x, y, height)

back of the stair now has pilasters, plinth and coping (was a blank slab)




FIXED EV03_05_elf_path_piece_05
488 tris | 20 x 20 x 6 studs (x, y, height)

warmer deck tones and lighter joints (was a dark flat slab)



FIXED TW03_01_skull_avenue_set_01
736 tris | 14 x 14 x 14 studs (x, y, height)

lighter iron and coals, less near-black



FIXED TW03_02_skull_avenue_set_02
684 tris | 14 x 14 x 14 studs (x, y, height)

brazier filled with coals and ash, dull iron and bronze (was an empty bowl with a gold rim)




FIXED TW03_03_skull_avenue_set_03
332 tris | 14 x 14 x 14 studs (x, y, height)

banner is now pleated cloth tied to the crossbar (was a flat red slab)




FIXED TW03_04_skull_avenue_set_04
364 tris | 14 x 14 x 14 studs (x, y, height)

swallowtail banner as one cloth shape with a plain diamond (was reading as letters)




MAJOR WT02_01_wizard_tower_interior
43,788 tris | 100 x 100 x 288 studs (x, y, height)

walkable floors with spiral stairs and domed top are good; but NO bookshelves on any interior floor; NO circular relief map inside the tower




OK CP01_01_ring_wall_straight_01
1,108 tris | 41 x 11 x 19 studs (x, y, height)

no flaws noted by the reviewer



OK CP01_02_ring_wall_straight_02
3,716 tris | 41 x 11 x 19 studs (x, y, height)

note: clean tiling crenellated block wall, rests on ground




OK CP01_03_ring_wall_straight_03
1,460 tris | 41 x 10 x 19 studs (x, y, height)

no flaws noted by the reviewer




OK CP02_02_ring_wall_corner_02
3,600 tris | 25 x 25 x 23 studs (x, y, height)

no flaws noted by the reviewer




OK CP03_01_ring_wall_stair_end_01
2,596 tris | 20 x 15 x 20 studs (x, y, height)

no flaws noted by the reviewer




OK CP03_02_ring_wall_stair_end_02
2,584 tris | 20 x 15 x 20 studs (x, y, height)

no flaws noted by the reviewer




OK CP04_01_tower_round_cone_01
2,832 tris | 19 x 19 x 43 studs (x, y, height)

no flaws noted by the reviewer




OK CP04_02_tower_round_cone_02
2,952 tris | 25 x 25 x 53 studs (x, y, height)

no flaws noted by the reviewer




OK CP04_03_tower_round_cone_03
2,832 tris | 31 x 31 x 53 studs (x, y, height)

no flaws noted by the reviewer



OK CP04_04_tower_round_cone_04
2,952 tris | 37 x 37 x 59 studs (x, y, height)

no flaws noted by the reviewer



OK CP05_01_turret_crenellated_01
1,800 tris | 14 x 14 x 26 studs (x, y, height)

no flaws noted by the reviewer




OK CP05_02_turret_crenellated_02
2,216 tris | 14 x 14 x 26 studs (x, y, height)

no flaws noted by the reviewer



OK CP06_01_gate_flank_tower_01
3,288 tris | 31 x 31 x 52 studs (x, y, height)

no flaws noted by the reviewer



OK CP06_02_gate_flank_tower_02
3,492 tris | 31 x 31 x 52 studs (x, y, height)

no flaws noted by the reviewer



OK CP08_01_water_gate
5,576 tris | 40 x 30 x 30 studs (x, y, height)

no flaws noted by the reviewer



OK CP09_01_keep_terrace_hero
44,260 tris | 130 x 111 x 116 studs (x, y, height)

no flaws noted by the reviewer



OK CP10_01_keep_wing_01
10,416 tris | 64 x 50 x 70 studs (x, y, height)

no flaws noted by the reviewer



OK CP10_02_keep_wing_02
9,858 tris | 58 x 52 x 70 studs (x, y, height)

no flaws noted by the reviewer




OK CP11_01_great_hall_chapel_01
9,826 tris | 73 x 50 x 60 studs (x, y, height)

no flaws noted by the reviewer




OK CP11_02_great_hall_chapel_02
5,942 tris | 70 x 48 x 61 studs (x, y, height)

no flaws noted by the reviewer




OK CP12_01_terrace_retaining_wall_01
1,084 tris | 41 x 10 x 23 studs (x, y, height)

no flaws noted by the reviewer




OK CP12_02_terrace_retaining_wall_02
1,088 tris | 40 x 10 x 23 studs (x, y, height)

no flaws noted by the reviewer




OK CP13_02_grand_stair_02
6,220 tris | 30 x 41 x 22 studs (x, y, height)

no flaws noted by the reviewer




OK CP14_01_skyline_tower_01
1,402 tris | 30 x 30 x 119 studs (x, y, height)


no flaws noted by the reviewer



OK CP14_02_skyline_tower_02
1,776 tris | 30 x 30 x 102 studs (x, y, height)
no flaws noted by the reviewer




OK CP14_03_skyline_tower_03
2,760 tris | 30 x 30 x 110 studs (x, y, height)
no flaws noted by the reviewer



OK CP14_04_skyline_tower_04
926 tris | 30 x 30 x 110 studs (x, y, height)
no flaws noted by the reviewer




OK CP14_05_skyline_tower_05
1,422 tris | 29 x 29 x 110 studs (x, y, height)
no flaws noted by the reviewer




OK CP15_02_order_hq_02
10,578 tris | 90 x 70 x 53 studs (x, y, height)
no flaws noted by the reviewer



OK CP15_03_order_hq_03
3,362 tris | 90 x 70 x 57 studs (x, y, height)
no flaws noted by the reviewer




OK CP16_01_townhouse_new_01
9,112 tris | 22 x 22 x 28 studs (x, y, height)
no flaws noted by the reviewer




OK CP16_02_townhouse_new_02
5,958 tris | 22 x 22 x 28 studs (x, y, height)
no flaws noted by the reviewer



OK CP16_03_townhouse_new_03
5,958 tris | 22 x 22 x 28 studs (x, y, height)
no flaws noted by the reviewer



OK CP16_04_townhouse_new_04
12,304 tris | 22 x 22 x 28 studs (x, y, height)
no flaws noted by the reviewer



OK CP16_05_townhouse_new_05
12,304 tris | 22 x 22 x 28 studs (x, y, height)
no flaws noted by the reviewer




OK CP16_06_townhouse_new_06
3,980 tris | 22 x 22 x 28 studs (x, y, height)
no flaws noted by the reviewer



OK CP16_07_townhouse_new_07
3,980 tris | 22 x 22 x 28 studs (x, y, height)
no flaws noted by the reviewer




OK CP16_08_townhouse_new_08
5,584 tris | 22 x 22 x 28 studs (x, y, height)
no flaws noted by the reviewer



OK CP16_09_townhouse_new_09
5,614 tris | 22 x 21 x 28 studs (x, y, height)
no flaws noted by the reviewer



OK CP16_10_townhouse_new_10
5,452 tris | 22 x 21 x 28 studs (x, y, height)
no flaws noted by the reviewer




OK CP16_11_townhouse_new_11
1,038 tris | 22 x 23 x 26 studs (x, y, height)
note: open market-stall shelter, mostly roof on posts (intended)




OK CP16_12_townhouse_new_12
9,112 tris | 22 x 22 x 28 studs (x, y, height)
no flaws noted by the reviewer




OK CP17_02_plaza_features_02
776 tris | 30 x 30 x 34 studs (x, y, height)
no flaws noted by the reviewer




OK CP18_01_quay_wall_01
584 tris | 31 x 10 x 8 studs (x, y, height)
no flaws noted by the reviewer




OK CP18_03_quay_wall_03
812 tris | 31 x 10 x 8 studs (x, y, height)
no flaws noted by the reviewer




OK CP18_04_quay_wall_04
736 tris | 31 x 10 x 8 studs (x, y, height)
no flaws noted by the reviewer



OK CP19_01_grand_bridge_01
5,040 tris | 67 x 26 x 28 studs (x, y, height)
no flaws noted by the reviewer




OK CP19_02_grand_bridge_02
4,120 tris | 62 x 23 x 28 studs (x, y, height)
no flaws noted by the reviewer




OK LM01_01_world_tree_trunk_door
2,404 tris | 36 x 36 x 50 studs (x, y, height)

no flaws noted by the reviewer




OK LM03_01_frost_fortress_hero
37,720 tris | 300 x 276 x 220 studs (x, y, height)

no flaws noted by the reviewer



OK LM04_01_fortress_rampart_step_01
5,528 tris | 60 x 20 x 34 studs (x, y, height)

no flaws noted by the reviewer



OK LM04_02_fortress_rampart_step_02
4,140 tris | 60 x 20 x 34 studs (x, y, height)

no flaws noted by the reviewer



OK LM04_03_fortress_rampart_step_03
6,024 tris | 60 x 20 x 34 studs (x, y, height)

no flaws noted by the reviewer




OK LM09_01_temple_buried_hero
5,528 tris | 180 x 160 x 90 studs (x, y, height)

no flaws noted by the reviewer




OK LM10_02_temple_colonnade_buried_02
4,960 tris | 62 x 20 x 40 studs (x, y, height)

no flaws noted by the reviewer



OK LM10_03_temple_colonnade_buried_03
3,664 tris | 60 x 20 x 40 studs (x, y, height)

no flaws noted by the reviewer




OK LM11_01_temple_gate_buried
926 tris | 40 x 20 x 51 studs (x, y, height)

no flaws noted by the reviewer




OK LM13_02_guardian_statue_02
924 tris | 20 x 20 x 70 studs (x, y, height)

no flaws noted by the reviewer




OK LM14_03_sand_obelisk_03
368 tris | 10 x 10 x 60 studs (x, y, height)

no flaws noted by the reviewer




OK LM15_01_ring_temple_hero
10,914 tris | 220 x 220 x 60 studs (x, y, height)

no flaws noted by the reviewer




OK LM17_01_ring_inner_sanctum
3,948 tris | 60 x 60 x 57 studs (x, y, height)

no flaws noted by the reviewer




OK LM18_01_crater_monolith_ring
5,396 tris | 140 x 140 x 50 studs (x, y, height)

no flaws noted by the reviewer




OK LM19_01_crater_rim_rock_01
1,308 tris | 60 x 50 x 40 studs (x, y, height)

no flaws noted by the reviewer




OK LM19_02_crater_rim_rock_02
1,320 tris | 60 x 50 x 40 studs (x, y, height)

no flaws noted by the reviewer




OK LM19_03_crater_rim_rock_03
1,308 tris | 60 x 50 x 40 studs (x, y, height)

no flaws noted by the reviewer




OK LM21_01_floating_rock_01
330 tris | 41 x 43 x 30 studs (x, y, height)

no flaws noted by the reviewer




OK LM21_02_floating_rock_02
276 tris | 40 x 40 x 30 studs (x, y, height)

no flaws noted by the reviewer




OK LM21_03_floating_rock_03
330 tris | 40 x 40 x 30 studs (x, y, height)

no flaws noted by the reviewer




OK LM22_01_colossal_fall_cliff_hero
27,732 tris | 240 x 120 x 265 studs (x, y, height)

no flaws noted by the reviewer




OK LM23_02_gorge_wall_02
3,444 tris | 95 x 30 x 81 studs (x, y, height)

no flaws noted by the reviewer




OK LM23_03_gorge_wall_03
3,720 tris | 95 x 30 x 85 studs (x, y, height)

note: dense stacked-rock face with mossy top reads well, tiles



OK LM26_01_ruin_arena_segment_01
2,460 tris | 60 x 30 x 33 studs (x, y, height)

no flaws noted by the reviewer



OK LM27_01_ruin_aqueduct_arch_01
1,700 tris | 40 x 12 x 50 studs (x, y, height)
no flaws noted by the reviewer



OK LM27_02_ruin_aqueduct_arch_02
1,632 tris | 40 x 12 x 50 studs (x, y, height)
no flaws noted by the reviewer



OK LM28_01_ruin_column_set_01
956 tris | 24 x 24 x 39 studs (x, y, height)
no flaws noted by the reviewer




OK LM28_03_ruin_column_set_03
852 tris | 25 x 24 x 38 studs (x, y, height)
no flaws noted by the reviewer



OK LM30_01_ruined_castle_hero
8,304 tris | 139 x 121 x 70 studs (x, y, height)
no flaws noted by the reviewer




OK LM31_01_ruined_castle_module_01
1,152 tris | 37 x 30 x 41 studs (x, y, height)
no flaws noted by the reviewer




OK LM31_02_ruined_castle_module_02
1,208 tris | 37 x 30 x 43 studs (x, y, height)
no flaws noted by the reviewer




OK LM31_03_ruined_castle_module_03
1,076 tris | 39 x 30 x 40 studs (x, y, height)
no flaws noted by the reviewer




OK WT01_01_wizard_tower_shell
42,636 tris | 119 x 119 x 300 studs (x, y, height)
no flaws noted by the reviewer



OK WT03_01_wizard_bookshelf_curved_01
5,352 tris | 26 x 6 x 28 studs (x, y, height)
no flaws noted by the reviewer



OK WT05_01_wizard_round_map_table
20,314 tris | 48 x 48 x 11 studs (x, y, height)
no flaws noted by the reviewer




OK WT06_01_wizard_floor_medallion
4,844 tris | 80 x 80 x 1 studs (x, y, height)
no flaws noted by the reviewer




OK WT07_01_wizard_lab_set_01
3,192 tris | 18 x 13 x 14 studs (x, y, height)
no flaws noted by the reviewer



OK WT07_02_wizard_lab_set_02
2,620 tris | 17 x 12 x 13 studs (x, y, height)
no flaws noted by the reviewer



OK WT07_03_wizard_lab_set_03
2,564 tris | 16 x 13 x 13 studs (x, y, height)
no flaws noted by the reviewer




OK WT07_04_wizard_lab_set_04
2,212 tris | 19 x 12 x 15 studs (x, y, height)
no flaws noted by the reviewer




OK WT08_01_wizard_study_set_01
2,180 tris | 18 x 13 x 12 studs (x, y, height)
no flaws noted by the reviewer



OK WT08_02_wizard_study_set_02
3,692 tris | 18 x 14 x 12 studs (x, y, height)
no flaws noted by the reviewer



OK WT08_03_wizard_study_set_03
1,560 tris | 17 x 15 x 11 studs (x, y, height)
no flaws noted by the reviewer




OK WT09_01_wizard_chandelier_ring_01
1,756 tris | 20 x 20 x 7 studs (x, y, height)
note: candle flames read as small pale tips (not glowing)




OK WT09_02_wizard_chandelier_ring_02
3,176 tris | 20 x 20 x 8 studs (x, y, height)
note: similar to WT09_01 but two-tier differs enough



OK WT10_01_wizard_observatory_telescope
996 tris | 13 x 14 x 27 studs (x, y, height)
no flaws noted by the reviewer



OK WT11_01_wizard_armillary_crown
3,188 tris | 70 x 70 x 50 studs (x, y, height)
no flaws noted by the reviewer




OK WT12_01_wizard_door_porch
2,488 tris | 41 x 26 x 39 studs (x, y, height)
note: star emblem on signboard (generic, matches game theme)



OK WT13_04_plateau_terrace_set_04
3,204 tris | 28 x 28 x 10 studs (x, y, height)
no flaws noted by the reviewer




OK HL01_01_ice_spire_01
588 tris | 24 x 24 x 71 studs (x, y, height)
no flaws noted by the reviewer




OK HL01_02_ice_spire_02
648 tris | 24 x 24 x 75 studs (x, y, height)
no flaws noted by the reviewer




OK HL01_03_ice_spire_03
708 tris | 24 x 24 x 70 studs (x, y, height)
note: very similar to HL01_02




OK HL01_04_ice_spire_04
552 tris | 24 x 24 x 69 studs (x, y, height)
no flaws noted by the reviewer




OK HL02_01_ice_arch_01
864 tris | 50 x 14 x 40 studs (x, y, height)
no flaws noted by the reviewer



OK HL02_02_ice_arch_02
1,176 tris | 50 x 14 x 40 studs (x, y, height)
no flaws noted by the reviewer



OK HL03_01_glacier_tongue_01
876 tris | 90 x 55 x 24 studs (x, y, height)
no flaws noted by the reviewer



OK HL03_03_glacier_tongue_03
972 tris | 90 x 55 x 24 studs (x, y, height)
no flaws noted by the reviewer



OK HL04_01_ice_cave_mouth_01
788 tris | 40 x 30 x 28 studs (x, y, height)
no flaws noted by the reviewer



OK HL04_02_ice_cave_mouth_02
520 tris | 40 x 30 x 28 studs (x, y, height)
no flaws noted by the reviewer



OK HL05_01_mountain_shrine
816 tris | 24 x 24 x 24 studs (x, y, height)
no flaws noted by the reviewer




OK HL06_01_snow_watchtower
2,654 tris | 20 x 20 x 50 studs (x, y, height)

note: base rubble is plain grey but acceptable at distance




OK HL07_01_mine_entrance_01
860 tris | 31 x 24 x 24 studs (x, y, height)

no flaws noted by the reviewer




OK HL07_02_mine_entrance_02
592 tris | 31 x 24 x 24 studs (x, y, height)

no flaws noted by the reviewer




OK HM01_01_rope_suspension_bridge_01
5,316 tris | 72 x 10 x 14 studs (x, y, height)

no flaws noted by the reviewer




OK HM01_02_rope_suspension_bridge_02
7,552 tris | 103 x 11 x 14 studs (x, y, height)

note: very similar to HM01_01, mainly longer




OK HM04_01_tunnel_lining_01
880 tris | 25 x 26 x 20 studs (x, y, height)

no flaws noted by the reviewer




OK HM05_01_cliff_gallery_01
1,216 tris | 43 x 14 x 23 studs (x, y, height)

no flaws noted by the reviewer




OK HM05_02_cliff_gallery_02
1,192 tris | 40 x 14 x 23 studs (x, y, height)

no flaws noted by the reviewer




OK HM06_01_switchback_wall_01
844 tris | 31 x 14 x 14 studs (x, y, height)

no flaws noted by the reviewer




OK HM06_02_switchback_wall_02
2,752 tris | 31 x 14 x 14 studs (x, y, height)

no flaws noted by the reviewer




OK HM07_01_prayer_flag_string_01
500 tris | 40 x 3 x 12 studs (x, y, height)

no flaws noted by the reviewer




OK HM07_02_prayer_flag_string_02
848 tris | 40 x 2 x 12 studs (x, y, height)

note: similar to HM07_01, more flags




OK HM07_03_prayer_flag_string_03
596 tris | 40 x 2 x 12 studs (x, y, height)

note: similar to HM07_01/02




OK HM07_04_prayer_flag_string_04
500 tris | 40 x 2 x 12 studs (x, y, height)

no flaws noted by the reviewer




OK HM08_02_cairn_shrine_02
1,098 tris | 14 x 14 x 12 studs (x, y, height)

no flaws noted by the reviewer




OK HM08_04_cairn_shrine_04
300 tris | 13 x 12 x 12 studs (x, y, height)

note: gold bell is bright but not glowing




OK HM09_01_monastery_outpost_01
824 tris | 38 x 28 x 29 studs (x, y, height)

no flaws noted by the reviewer



OK HM09_02_monastery_outpost_02
1,466 tris | 34 x 31 x 26 studs (x, y, height)

note: gold roof finial renders bright; verify it is not emissive



OK HM09_04_monastery_outpost_04
1,032 tris | 34 x 30 x 32 studs (x, y, height)

no flaws noted by the reviewer



OK FR01_01_giant_tree_01
5,964 tris | 92 x 93 x 171 studs (x, y, height)

no flaws noted by the reviewer



OK FR01_02_giant_tree_02
4,028 tris | 92 x 91 x 164 studs (x, y, height)

no flaws noted by the reviewer



OK FR01_03_giant_tree_03
4,760 tris | 90 x 90 x 170 studs (x, y, height)

no flaws noted by the reviewer



OK FR01_04_giant_tree_04
3,228 tris | 98 x 92 x 161 studs (x, y, height)

no flaws noted by the reviewer



OK FR02_05_forest_ruin_05
1,052 tris | 40 x 30 x 34 studs (x, y, height)

no flaws noted by the reviewer




OK FR02_06_forest_ruin_06
940 tris | 40 x 30 x 34 studs (x, y, height)

note: banded column plus mossy base reads fine




OK FR03_02_cave_mouth_02
648 tris | 40 x 32 x 30 studs (x, y, height)

no flaws noted by the reviewer



OK FR03_03_cave_mouth_03
672 tris | 40 x 31 x 30 studs (x, y, height)

no flaws noted by the reviewer



OK FR03_04_cave_mouth_04
624 tris | 40 x 32 x 30 studs (x, y, height)

no flaws noted by the reviewer




OK FR03_05_cave_mouth_05
648 tris | 40 x 31 x 30 studs (x, y, height)

no flaws noted by the reviewer




OK FR03_06_cave_mouth_06
672 tris | 40 x 32 x 30 studs (x, y, height)

no flaws noted by the reviewer



OK PL01_01_farmhouse_01
4,186 tris | 30 x 23 x 21 studs (x, y, height)

no flaws noted by the reviewer




OK PL01_02_farmhouse_02
2,906 tris | 28 x 23 x 22 studs (x, y, height)

no flaws noted by the reviewer




OK PL01_03_farmhouse_03
4,390 tris | 26 x 23 x 22 studs (x, y, height)

no flaws noted by the reviewer




OK PL01_04_farmhouse_04
6,620 tris | 28 x 22 x 22 studs (x, y, height)

no flaws noted by the reviewer



OK PL02_02_hay_silo_02
288 tris | 14 x 14 x 24 studs (x, y, height)

note: plain single-colour yellow bales, little relief



OK PL02_03_hay_silo_03
974 tris | 14 x 14 x 23 studs (x, y, height)


no flaws noted by the reviewer




OK PL03_01_farm_cart_01
632 tris | 14 x 8 x 8 studs (x, y, height)
no flaws noted by the reviewer



OK PL03_02_farm_cart_02
820 tris | 14 x 8 x 8 studs (x, y, height)
no flaws noted by the reviewer




OK PL04_01_mill_waterwheel
5,700 tris | 35 x 30 x 30 studs (x, y, height)
no flaws noted by the reviewer



OK PL06_01_rock_arch_natural_01
504 tris | 62 x 22 x 40 studs (x, y, height)
no flaws noted by the reviewer



OK PL06_02_rock_arch_natural_02
504 tris | 63 x 24 x 40 studs (x, y, height)
no flaws noted by the reviewer



OK DS01_02_adobe_house_02
1,798 tris | 20 x 20 x 17 studs (x, y, height)
no flaws noted by the reviewer




OK DS01_03_adobe_house_03
1,804 tris | 20 x 20 x 18 studs (x, y, height)
no flaws noted by the reviewer



OK DS01_04_adobe_house_04
1,804 tris | 20 x 20 x 18 studs (x, y, height)
no flaws noted by the reviewer




OK DS01_06_adobe_house_06
1,468 tris | 20 x 20 x 18 studs (x, y, height)
no flaws noted by the reviewer




OK DS02_01_desert_market_01
1,126 tris | 24 x 18 x 16 studs (x, y, height)
no flaws noted by the reviewer



OK DS02_02_desert_market_02
600 tris | 24 x 18 x 16 studs (x, y, height)
no flaws noted by the reviewer



OK DS02_03_desert_market_03
604 tris | 24 x 18 x 16 studs (x, y, height)
no flaws noted by the reviewer



OK DS03_01_caravan_wagon_01
1,116 tris | 18 x 10 x 12 studs (x, y, height)
no flaws noted by the reviewer




OK DS03_02_caravan_wagon_02
1,168 tris | 18 x 10 x 12 studs (x, y, height)
no flaws noted by the reviewer




OK DS04_03_palm_03
3,816 tris | 14 x 14 x 44 studs (x, y, height)
no flaws noted by the reviewer



OK DS05_01_oasis_rock_ring_01
2,534 tris | 53 x 50 x 11 studs (x, y, height)
no flaws noted by the reviewer



OK DS05_02_oasis_rock_ring_02
1,900 tris | 51 x 53 x 10 studs (x, y, height)
no flaws noted by the reviewer



OK DS06_01_canyon_wall_01
4,584 tris | 127 x 40 x 93 studs (x, y, height)
no flaws noted by the reviewer



OK DS06_04_canyon_wall_04
4,620 tris | 125 x 40 x 92 studs (x, y, height)
no flaws noted by the reviewer




OK DS07_01_hoodoo_arch_01
1,488 tris | 40 x 30 x 70 studs (x, y, height)
no flaws noted by the reviewer




OK DS07_02_hoodoo_arch_02
1,488 tris | 40 x 30 x 70 studs (x, y, height)
no flaws noted by the reviewer




OK DS07_04_hoodoo_arch_04
1,596 tris | 40 x 30 x 70 studs (x, y, height)
no flaws noted by the reviewer




OK DS08_01_underground_entrance_01
864 tris | 30 x 31 x 24 studs (x, y, height)
no flaws noted by the reviewer




OK DS08_03_underground_entrance_03
872 tris | 30 x 31 x 24 studs (x, y, height)
no flaws noted by the reviewer




OK CO01_01_coastal_cliff_01
2,460 tris | 115 x 50 x 70 studs (x, y, height)
no flaws noted by the reviewer




OK CO01_02_coastal_cliff_02
2,268 tris | 120 x 50 x 65 studs (x, y, height)
no flaws noted by the reviewer




OK CO01_03_coastal_cliff_03
2,784 tris | 110 x 50 x 75 studs (x, y, height)
no flaws noted by the reviewer




OK CO01_04_coastal_cliff_04
2,688 tris | 114 x 49 x 70 studs (x, y, height)
no flaws noted by the reviewer




OK CO01_05_coastal_cliff_05
3,912 tris | 110 x 50 x 71 studs (x, y, height)
no flaws noted by the reviewer




OK CO01_06_coastal_cliff_06
2,076 tris | 113 x 50 x 64 studs (x, y, height)
no flaws noted by the reviewer




OK CO03_01_reef_01
2,144 tris | 29 x 28 x 6 studs (x, y, height)
no flaws noted by the reviewer



OK CO03_02_reef_02
2,162 tris | 29 x 28 x 6 studs (x, y, height)
no flaws noted by the reviewer




OK CO03_03_reef_03
2,582 tris | 29 x 28 x 6 studs (x, y, height)
no flaws noted by the reviewer



OK CO03_04_reef_04
2,144 tris | 29 x 28 x 6 studs (x, y, height)
no flaws noted by the reviewer




OK CO03_05_reef_05
2,384 tris | 29 x 28 x 6 studs (x, y, height)
no flaws noted by the reviewer




OK CO03_06_reef_06
2,582 tris | 29 x 28 x 6 studs (x, y, height)
no flaws noted by the reviewer




OK CO04_02_sea_arch_02
1,728 tris | 70 x 28 x 60 studs (x, y, height)
no flaws noted by the reviewer



OK CO05_01_ruin_islet_01
11,544 tris | 60 x 60 x 40 studs (x, y, height)
no flaws noted by the reviewer



OK CO05_02_ruin_islet_02
10,528 tris | 60 x 60 x 40 studs (x, y, height)
no flaws noted by the reviewer



OK CO05_03_ruin_islet_03
10,976 tris | 60 x 60 x 40 studs (x, y, height)
no flaws noted by the reviewer



OK RD01_01_watchtower_01
2,920 tris | 20 x 20 x 50 studs (x, y, height)
no flaws noted by the reviewer




OK RD01_02_watchtower_02
2,356 tris | 20 x 20 x 50 studs (x, y, height)
no flaws noted by the reviewer




OK RD01_03_watchtower_03
2,844 tris | 21 x 20 x 46 studs (x, y, height)
no flaws noted by the reviewer



OK RD01_04_watchtower_04
2,496 tris | 20 x 20 x 47 studs (x, y, height)
no flaws noted by the reviewer



OK RD02_01_camp_set_01
200 tris | 16 x 14 x 10 studs (x, y, height)
no flaws noted by the reviewer



OK RD02_02_camp_set_02
232 tris | 16 x 14 x 9 studs (x, y, height)
no flaws noted by the reviewer



OK RD02_03_camp_set_03
404 tris | 16 x 14 x 10 studs (x, y, height)
no flaws noted by the reviewer



OK RD02_04_camp_set_04
232 tris | 16 x 14 x 10 studs (x, y, height)
no flaws noted by the reviewer



OK RD02_05_camp_set_05
810 tris | 16 x 14 x 10 studs (x, y, height)
no flaws noted by the reviewer



OK RD02_06_camp_set_06
668 tris | 16 x 14 x 10 studs (x, y, height)
no flaws noted by the reviewer



OK RD03_01_waystation_01
2,488 tris | 30 x 24 x 20 studs (x, y, height)
no flaws noted by the reviewer




OK RD03_02_waystation_02
4,960 tris | 30 x 24 x 21 studs (x, y, height)
no flaws noted by the reviewer



OK RD04_01_trading_post_01
4,948 tris | 30 x 24 x 21 studs (x, y, height)
no flaws noted by the reviewer



OK RD05_01_battlefield_prop_01
1,120 tris | 13 x 10 x 10 studs (x, y, height)
no flaws noted by the reviewer




OK RD05_02_battlefield_prop_02
748 tris | 14 x 10 x 10 studs (x, y, height)
no flaws noted by the reviewer




OK RD05_03_battlefield_prop_03
268 tris | 14 x 10 x 10 studs (x, y, height)
no flaws noted by the reviewer



OK RD05_04_battlefield_prop_04
468 tris | 14 x 10 x 10 studs (x, y, height)
no flaws noted by the reviewer




OK RD05_05_battlefield_prop_05
948 tris | 14 x 10 x 10 studs (x, y, height)
no flaws noted by the reviewer



OK RD06_01_abandoned_house_01
1,926 tris | 22 x 20 x 20 studs (x, y, height)
no flaws noted by the reviewer




OK RD06_02_abandoned_house_02
7,176 tris | 22 x 19 x 20 studs (x, y, height)
no flaws noted by the reviewer



OK RD06_03_abandoned_house_03
1,862 tris | 22 x 20 x 20 studs (x, y, height)

no flaws noted by the reviewer



OK RD06_04_abandoned_house_04
3,926 tris | 24 x 21 x 20 studs (x, y, height)

note: collapsed roof debris at side



OK VG01_01_tree_tall_narrow_01
2,084 tris | 14 x 14 x 46 studs (x, y, height)

no flaws noted by the reviewer



OK VG01_02_tree_tall_narrow_02
2,104 tris | 15 x 15 x 45 studs (x, y, height)

no flaws noted by the reviewer



OK VG01_03_tree_tall_narrow_03
2,832 tris | 14 x 15 x 43 studs (x, y, height)

no flaws noted by the reviewer



OK VG02_01_tree_old_oak_01
2,844 tris | 29 x 31 x 45 studs (x, y, height)

no flaws noted by the reviewer



OK VG03_01_tree_flowering_01
3,240 tris | 24 x 23 x 29 studs (x, y, height)

no flaws noted by the reviewer



OK VG03_02_tree_flowering_02
3,464 tris | 23 x 23 x 28 studs (x, y, height)

no flaws noted by the reviewer



OK VG04_01_tree_birch_01
1,818 tris | 14 x 14 x 33 studs (x, y, height)

no flaws noted by the reviewer



OK VG04_02_tree_birch_02
1,818 tris | 14 x 14 x 34 studs (x, y, height)

no flaws noted by the reviewer



OK VG04_03_tree_birch_03
2,088 tris | 14 x 14 x 33 studs (x, y, height)

no flaws noted by the reviewer




OK VG05_02_tree_cypress_swamp_02
1,592 tris | 22 x 22 x 38 studs (x, y, height)


no flaws noted by the reviewer




OK VG05_03_tree_cypress_swamp_03
1,248 tris | 22 x 22 x 38 studs (x, y, height)
no flaws noted by the reviewer




OK VG06_01_marsh_hummock_01
872 tris | 17 x 16 x 6 studs (x, y, height)
no flaws noted by the reviewer




OK VG06_02_marsh_hummock_02
1,028 tris | 17 x 17 x 6 studs (x, y, height)
no flaws noted by the reviewer




OK VG07_01_boardwalk_01
664 tris | 30 x 6 x 4 studs (x, y, height)
no flaws noted by the reviewer



OK TW02_02_street_life_02
628 tris | 12 x 10 x 10 studs (x, y, height)
no flaws noted by the reviewer



OK TW02_05_street_life_05
1,944 tris | 12 x 10 x 10 studs (x, y, height)
note: stacked barrels fairly plain




OK TW02_06_street_life_06
620 tris | 12 x 10 x 10 studs (x, y, height)
no flaws noted by the reviewer




OK TW02_08_street_life_08
212 tris | 12 x 10 x 10 studs (x, y, height)
no flaws noted by the reviewer




OK RV01_01_bank_rock_01
968 tris | 29 x 20 x 10 studs (x, y, height)
no flaws noted by the reviewer




OK RV01_03_bank_rock_03
720 tris | 30 x 19 x 10 studs (x, y, height)
no flaws noted by the reviewer




OK RV01_04_bank_rock_04
968 tris | 28 x 20 x 10 studs (x, y, height)
no flaws noted by the reviewer




OK VC01_01_volcanic_rock_01
2,212 tris | 60 x 50 x 60 studs (x, y, height)
no flaws noted by the reviewer




OK VC01_02_volcanic_rock_02
2,312 tris | 60 x 50 x 60 studs (x, y, height)
no flaws noted by the reviewer



OK VC01_05_volcanic_rock_05
2,212 tris | 60 x 50 x 60 studs (x, y, height)
no flaws noted by the reviewer




OK VC01_07_volcanic_rock_07
1,856 tris | 60 x 50 x 60 studs (x, y, height)
no flaws noted by the reviewer



OK VC01_08_volcanic_rock_08
1,928 tris | 60 x 50 x 60 studs (x, y, height)
no flaws noted by the reviewer



OK VC02_01_skull_cliff_hero_01
5,476 tris | 200 x 120 x 122 studs (x, y, height)
no flaws noted by the reviewer



OK VC02_02_skull_cliff_hero_02
5,148 tris | 200 x 120 x 120 studs (x, y, height)
no flaws noted by the reviewer




OK VC03_01_dark_fort_ruin_01
6,736 tris | 60 x 50 x 50 studs (x, y, height)
no flaws noted by the reviewer



OK VC03_02_dark_fort_ruin_02
6,844 tris | 60 x 50 x 50 studs (x, y, height)
no flaws noted by the reviewer




OK VC03_03_dark_fort_ruin_03
6,736 tris | 60 x 50 x 52 studs (x, y, height)
no flaws noted by the reviewer



OK VC04_01_skull_city_building_01
1,256 tris | 30 x 30 x 30 studs (x, y, height)
no flaws noted by the reviewer




OK VC04_02_skull_city_building_02
1,188 tris | 30 x 30 x 30 studs (x, y, height)
no flaws noted by the reviewer




OK VC04_03_skull_city_building_03
2,558 tris | 30 x 30 x 29 studs (x, y, height)
no flaws noted by the reviewer



OK VC04_05_skull_city_building_05
1,256 tris | 30 x 30 x 30 studs (x, y, height)
no flaws noted by the reviewer




OK FL01_01_floating_island_hero_01
18,064 tris | 86 x 86 x 60 studs (x, y, height)
no flaws noted by the reviewer




OK FL01_02_floating_island_hero_02
13,052 tris | 86 x 86 x 60 studs (x, y, height)
no flaws noted by the reviewer




OK FL01_03_floating_island_hero_03
9,976 tris | 86 x 86 x 63 studs (x, y, height)
no flaws noted by the reviewer




OK SP01_01_snow_spire_cluster_01
1,644 tris | 60 x 60 x 161 studs (x, y, height)
no flaws noted by the reviewer



OK SP01_02_snow_spire_cluster_02
1,776 tris | 60 x 60 x 166 studs (x, y, height)
no flaws noted by the reviewer



OK SP01_03_snow_spire_cluster_03
1,644 tris | 60 x 60 x 163 studs (x, y, height)
no flaws noted by the reviewer




OK SP01_05_snow_spire_cluster_05
1,776 tris | 60 x 60 x 161 studs (x, y, height)
no flaws noted by the reviewer



OK SD01_01_red_mesa_cluster_01
1,284 tris | 120 x 100 x 92 studs (x, y, height)
no flaws noted by the reviewer



OK SD01_02_red_mesa_cluster_02
1,500 tris | 120 x 100 x 92 studs (x, y, height)
no flaws noted by the reviewer



OK SD01_04_red_mesa_cluster_04
1,956 tris | 114 x 101 x 93 studs (x, y, height)
no flaws noted by the reviewer




OK SD01_05_red_mesa_cluster_05
1,956 tris | 118 x 100 x 93 studs (x, y, height)
no flaws noted by the reviewer




OK SD01_06_red_mesa_cluster_06
1,956 tris | 118 x 99 x 89 studs (x, y, height)
no flaws noted by the reviewer




OK SD02_01_desert_ruin_block_01
2,364 tris | 40 x 40 x 30 studs (x, y, height)
no flaws noted by the reviewer



OK SD02_02_desert_ruin_block_02
2,392 tris | 40 x 40 x 30 studs (x, y, height)
no flaws noted by the reviewer




OK SD02_03_desert_ruin_block_03
1,968 tris | 40 x 40 x 30 studs (x, y, height)
no flaws noted by the reviewer




OK SD02_04_desert_ruin_block_04
2,400 tris | 40 x 40 x 30 studs (x, y, height)
no flaws noted by the reviewer



OK SD02_06_desert_ruin_block_06
2,676 tris | 40 x 40 x 30 studs (x, y, height)
no flaws noted by the reviewer



OK BR01_01_viaduct_bridge_01
8,252 tris | 167 x 20 x 40 studs (x, y, height)
no flaws noted by the reviewer



OK BR01_02_viaduct_bridge_02
8,384 tris | 167 x 20 x 40 studs (x, y, height)
no flaws noted by the reviewer



OK HB01_01_harbour_wall_tower_01
2,236 tris | 24 x 24 x 40 studs (x, y, height)
no flaws noted by the reviewer



OK HB01_03_harbour_wall_tower_03
1,646 tris | 24 x 24 x 38 studs (x, y, height)
no flaws noted by the reviewer



OK VL01_01_village_church_spire
1,634 tris | 30 x 40 x 70 studs (x, y, height)
no flaws noted by the reviewer



OK RW01_03_rework_existing_03
10,712 tris | 50 x 49 x 65 studs (x, y, height)
no flaws noted by the reviewer



OK RW01_04_rework_existing_04
10,712 tris | 54 x 54 x 59 studs (x, y, height)

no flaws noted by the reviewer



OK NE01_01_village_sign_01
524 tris | 10 x 4 x 18 studs (x, y, height)

no flaws noted by the reviewer




OK NE01_02_village_sign_02
388 tris | 10 x 5 x 18 studs (x, y, height)

no flaws noted by the reviewer




OK NE01_04_village_sign_04
320 tris | 10 x 4 x 18 studs (x, y, height)

no flaws noted by the reviewer




OK NE01_05_village_sign_05
316 tris | 10 x 3 x 18 studs (x, y, height)

note: anchor emblem on board (maritime, generic)




OK NE01_06_village_sign_06
244 tris | 10 x 3 x 18 studs (x, y, height)

no flaws noted by the reviewer




OK NE02_01_entry_rock_pair_01
976 tris | 31 x 22 x 15 studs (x, y, height)

no flaws noted by the reviewer




OK NE02_02_entry_rock_pair_02
1,000 tris | 31 x 22 x 15 studs (x, y, height)

no flaws noted by the reviewer



OK NE02_04_entry_rock_pair_04
880 tris | 31 x 22 x 15 studs (x, y, height)

no flaws noted by the reviewer



OK EV01_01_elf_house_new_01
4,204 tris | 26 x 26 x 30 studs (x, y, height)

no flaws noted by the reviewer



OK EV01_02_elf_house_new_02
1,648 tris | 28 x 26 x 30 studs (x, y, height)

no flaws noted by the reviewer



OK EV01_03_elf_house_new_03
2,460 tris | 26 x 26 x 30 studs (x, y, height)


no flaws noted by the reviewer




OK EV01_04_elf_house_new_04
2,264 tris | 26 x 26 x 30 studs (x, y, height)
no flaws noted by the reviewer




OK EV01_05_elf_house_new_05
1,552 tris | 26 x 26 x 30 studs (x, y, height)
no flaws noted by the reviewer




OK EV01_06_elf_house_new_06
976 tris | 26 x 26 x 30 studs (x, y, height)
no flaws noted by the reviewer




OK EV01_07_elf_house_new_07
2,324 tris | 26 x 26 x 30 studs (x, y, height)
no flaws noted by the reviewer




OK EV01_08_elf_house_new_08
1,452 tris | 26 x 26 x 30 studs (x, y, height)
no flaws noted by the reviewer



OK EV02_03_canopy_cluster_03
4,596 tris | 65 x 70 x 40 studs (x, y, height)
no flaws noted by the reviewer




OK EV03_03_elf_path_piece_03
1,668 tris | 20 x 20 x 6 studs (x, y, height)
no flaws noted by the reviewer



OK EV03_04_elf_path_piece_04
1,312 tris | 20 x 20 x 6 studs (x, y, height)
no flaws noted by the reviewer




OK EV03_06_elf_path_piece_06
1,626 tris | 20 x 20 x 6 studs (x, y, height)
no flaws noted by the reviewer




CP07_01_gatehouse_main

CP09_01_keep_terrace_hero








CP15_01_order_hq_01

CP15_02_order_hq_02



CP19_01_grand_bridge_01

CP19_02_grand_bridge_02














LM09_01_temple_buried_hero

LM15_01_ring_temple_hero














WT01_01_wizard_tower_shell

WT05_01_wizard_round_map_table









WT12_01_wizard_door_porch

RW02_01_rework_world_tree_roots




VC04_02_skull_city_building_02

LM07_02_carved_stair_switchback_02




SP01_04_snow_spire_cluster_04



RD06_02_abandoned_house_02





VC04_06_skull_city_building_06

WT13_02_plateau_terrace_set_02




LM05_02_fortress_cliff_tower_02

LM07_01_carved_stair_switchback_01




WT13_01_plateau_terrace_set_01

VC04_03_skull_city_building_03














VC04_01_skull_city_building_01

WT13_06_plateau_terrace_set_06


















LM16_01_ring_temple_segment_01

WT13_05_plateau_terrace_set_05




VC04_04_skull_city_building_04

VC04_05_skull_city_building_05


SP01_06_snow_spire_cluster_06

LM08_01_mountain_span_bridge




CP08_01_water_gate



LM22_01_colossal_fall_cliff_hero




WT13_04_plateau_terrace_set_04

LM30_01_ruined_castle_hero




WT03_01_wizard_bookshelf_curved_01

LM12_02_temple_stair_down_02




DS04_01_palm_01





LM02_01_world_tree_falls




DS04_02_palm_02




HL07_01_mine_entrance_01



DS08_03_underground_entrance_03

WT13_03_plateau_terrace_set_03




DS04_03_palm_03

RW01_01_rework_existing_01





LM04_02_fortress_rampart_step_02


HL03_02_glacier_tongue_02





















CP18_02_quay_wall_02






LM25_01_ruin_gate_hero




LM16_02_ring_temple_segment_02

DS08_01_underground_entrance_01



CP01_02_ring_wall_straight_02
LM23_03_gorge_wall_03




DS08_02_underground_entrance_02

LM12_01_temple_stair_down_01



LM13_01_guardian_statue_01