Report Overview

Industrial Zone	Bommasandra
Analysis Type	Vegetation Segmentation
Report Generated	22 Apr 2026, 01:54:10
Violations Found	4
Model Confidence	66.5%
Total Coverage	0.4358 km sq
Status	ACTION REQUIRED

Detected Violations (4 regions)

ID	Severity	Latitude	Longitude	Area km sq	Priority
VIO-002	High	12.816944 N	77.684207 E	0.20761	CRITICAL
VIO-001	High	12.820767 N	77.677207 E	0.08662	CRITICAL
VIO-004	High	12.813076 N	77.680137 E	0.07562	CRITICAL
VIO-003	High	12.814761 N	77.673887 E	0.06599	CRITICAL

Visual Analysis - Heatmap Evidence

Dark = no vegetation loss | Bright = vegetation loss detected



Regulatory Recommendations

1. Issue formal notices to plotholders within flagged GPS coordinates.
2. Schedule ground-truth field inspection within 7 working days.
3. Cross-reference flagged coordinates against approved construction permits.
4. If green belt encroachment confirmed, invoke KIADB enforcement provisions.
5. Re-run EcoWatch AI analysis post-remediation to confirm compliance.

DISCLAIMER: This report is generated by the EcoWatch AI automated satellite analysis system. Results are indicative only and should be verified by a qualified environmental officer before any regulatory action is taken.