



JF123 - Transverse Span, Loadbearing Wall




All wall blocks to be mortar bedded

JF124 - Transverse Stagger / Service Hole, Loadbearing Wall



All wall blocks to be mortar bedded


JF125 - End Bearing 215mm / 100mm Loadbearing Wall



All wall blocks to be mortar bedded


Revision Schedule			
Rev	Date	Description	Drn By
C1	28.11.25	Construction Issue	-

JF126 - End Bearing, min. 215mm Loadbearing Wall




All wall blocks to be mortar bedded

JF128 - Splayed Bearing < 45°, Wide Block




All wall blocks to be mortar bedded


JF130 - Run-out Joint 100mm Sheet




JF132 - Load Supported by Floor



JF54 - Service Pipe Tight to Wall




JF157 - Threshold Edge Detail Parallel




Only use the narrow poly block in this detail
All wall blocks to be mortar bedded

JF158 - Threshold End Detail




All wall blocks to be mortar bedded

JF159 - Vent & Air Brick Detail




All wall blocks to be mortar bedded


JF153 - Staggered Bearing Loadbearing Wall



JF154 - Internal Loadbearing Wall (House / Garage)



JF155 - Internal Loadbearing Wall (House / Garage)



Bellway Homes (Eastern Counties)
Building 2030, Cambourne Business Park,
Cambridgeshire CB23 6DW
Tel: 01480 425 200

Project
Somersham
St Ives Road
Working Drawings

Drawing Title
The Draftsman-Life DML-3B-2S-0
934 ft² | 3b Semi/Mid | All Variants
Beam Details (Sheet 2)

Drawing Created By Group	First Issue Date April '25	Scale(s) 1 : 20
Project No BI01	Drg Status Construction	Revision C1
Drawing No. BI01/934DML/30/0/05		

Do not scale - if in doubt, ask