State Farm Claims
P.O. Box 106170
Atlanta, GA 30348-6170
Fax: 1-844-236-3646
statefarmfireclaims@statefarm.com

Structural Damage Claim Policy

This estimate is priced based on estimated market pricing for the cost of materials, labor, and other factors at the time of the loss.

Adjustments in market pricing and timing of the repairs may impact the final cost of covered repairs. Should you or the contractor you select have questions concerning our estimate, please contact us. If your contractor's estimate is higher than ours, you should contact us prior to beginning repairs. State Farm will work with you and your contractor to determine the actual and necessary cost of covered repairs at the time repairs will be completed, subject to policy terms, conditions and limits.

- We want you to receive quality repair work to restore the damages to your property.
- We will provide you with a detailed estimate of the scope of the damage and costs of repairs. Should the contractor you select have questions concerning our estimate, they should contact your claim representative directly.
- Depending upon the complexity of your repair, our estimate may or may not include an allowance for general contractor's overhead and profit. If you have questions regarding general contractor's overhead and profit and whether general contractor services are appropriate for your loss, please contact your claim representative before proceeding with repairs.
- There may be building codes, ordinances, laws, or regulations that affect the repairs of your property. These items may or may not be covered by your policy. Please contact your claim representative if you have any questions regarding coverage which may be available under your policy.
- State Farm® cannot authorize any contractor to proceed with work on your property. Repairs should proceed only with your authorization.
- State Farm does not guarantee the quality of the workmanship of any contractor or guarantee that the work will be accomplished within any specific time frame.
- It is understood that the contractor is hired by you, our insured, and that they work for you - not State Farm.

If you have any questions or need additional information regarding your claim, please contact your claim representative immediately.

Building Estimate Summary Guide

This summary guide is based on a sample estimate and is provided for reference only. Please refer to the estimate for specifics of your claim.

State Farm Insurance

Insured:	Smith, Joe & Jane	Estimate:	00-0000-000
Property:	1 Main Street	Claim number:	00-0000-000
	Anywhere, IL 00000-0000	Policy Number:	00-00-0000-0
Type of Loss:	Other	Price List:	ILBL8F_MAR 13
Deductible:	$1,000.00		Restoration/Service/ Remodel F = Factored In, D = Do Not Apply

Summary for Dwelling

Line Item Total [1]			5,953.10
Material Sales Tax	@	10.000% x 1,520.00	
Subtotal			6,105.10
General Contractor Overhead [2]	@	10.0% x 6,105.10	610.51
General Contractor Profit	@	10.0% x 6,105.10	
Replacement Cost Value (Including General Contractor Overhead and Profit [3]			7,326.12
Less Depreciation (Including Taxes) [4]			(832.50)
Less General Contractor Overhead & Profit on Recoverable & Non - recoverable Depreciation			(166.50)
Less Deductible [5]			
Net Actual Cash Value Payment [6]			

Maximum Additional Amounts Available If Incurred:

Total Line Item Depreciation (Including Taxes) [4]	832.50	
Less Non - recoverable Depreciation (Including Taxes) [7]		
Subtotal		312.50
General Contractor O&P on Depreciation	166.50	
Less General Contractor O&P on Non - recoverable Depreciation		
Subtotal		
Total Maximum Additional Amounts Available If Incurred [8]		
Total Amount of Claim If Incurred [9]		

Claim Representative

ALL AMOUNTS PAYABLE ARE SUBJECT TO THE TERMS, CONDITIONS AND LIMITS OF YOUR POLICY.

SAMPLE

1. **Line Item Total –** Total value of all line items in the estimate plus possible adjustments for *labor minimums*. *Labor Minimum* is to cover a certain minimum number of hours for drive-time, set up time and applicable administrative costs and repairs.
2. **General Contractor's Overhead and Profit –** General contractor's charge for coordinating your repairs.
3. **Replacement Cost Value (RCV) –** Estimated cost to repair or replace damaged property.
4. **Depreciation –** The decrease in the value of property over a period of time due to wear, tear, condition, and obsolescence. A portion or all of this amount may be eligible for replacement cost benefits.
5. **Deductible –** The insurer will pay for losses, up to the policy limits, in excess of your applicable deductible.
6. **Net Actual Cash Value Payment (ACV) –** The repair or replacement cost of the damaged part of the property less *depreciation* and *deductible.*
7. **Non Recoverable Depreciation –** *Depreciation* applied to items that are not eligible for replacement cost benefits.
8. **Total Maximum Additional Amount if Incurred –** Total amount of recoverable depreciation after actual repair or replacement of the property.
9. **Total Amount of Claim if Incurred –** Total amount of the claim, including *net actual cash value payment and total maximum additional amount available if incurred.*

Insured:	POPE, MARY	Estimate:	35-95Z3-96MR
Property:	13901 SOUTHVIEW AVE CLEVELAND, OH 44120-4655	Claim Number:	3595Z396M
		Policy Number:	70EM31717
Home:	216-991-0645	Price List:	OHCL28_NOV25 Restoration/Service/Remodel
Type of Loss:	Wind		
Deductible:	$500.00		
Date of Loss:	11/20/2025		
Date Inspected:	2/10/2026		

Summary for Coverage A - Dwelling - 35 Windstorm and Hail

Line Item Total	9,826.66
Material Sales Tax	217.17
Replacement Cost Value	10,043.83
Less Deductible	(500.00)
Net Payment	$9,543.83


Sams, Kenneth
866-787-8676

ALL AMOUNTS PAYABLE ARE SUBJECT TO THE TERMS, CONDITIONS AND LIMITS OF YOUR POLICY.

Any person who, with intent to defraud or knowing that he is facilitating a fraud against an insurer, submits an application or files a claim containing a false or deceptive statement is guilty of insurance fraud.

Source - EagleView Roof

Source - EagleView Roof



ROOF1

1,525.16	Surface Area	15.25	Number of Squares
212.92	Total Perimeter Length	45.58	Total Ridge Length

DESCRIPTION	QUANTITY	UNIT PRICE	TAX	RCV
1. Tear off, haul and dispose of comp. shingles - 3 tab	15.25 SQ	76.54	0.00	1,167.24
2. 3 tab - 25 yr. - comp. shingle roofing - w/out felt	17.00 SQ	262.29	148.20	4,607.13
Component RFG240 from this line item was priced by ITEL Asphalt Shingle Pricing (ASP) on 16 Feb 2026. Auto Calculate(Not available)				
3. Hip / Ridge cap - Standard profile - composition shingles	45.58 LF	6.98	11.60	329.75
4. Asphalt starter - universal starter course	78.00 LF	2.20	4.06	175.66
5. Ice & water barrier	366.00 SF	2.02	15.81	755.13
6. Roofing felt - 15 lb.	7.99 SQ	41.10	5.27	333.66
7. Drip edge	212.92 LF	3.19	19.08	698.29
8. Roof vent - turtle type - Plastic	3.00 EA	69.18	3.38	210.92
9. Flashing - pipe jack	1.00 EA	60.03	1.50	61.53
10. Remove Additional charge for steep roof - 7/12 to 9/12 slope	9.86 SQ	17.73	0.00	174.82
11. Additional charge for steep roof - 7/12 to 9/12 slope	10.85 SQ	53.80	0.00	583.73
12. Remove Additional charge for steep roof - 10/12 - 12/12 slope	2.76 SQ	27.86	0.00	76.89
13. Additional charge for steep roof - 10/12 - 12/12 slope	3.04 SQ	84.59	0.00	257.15
14. Remove Additional charge for high roof (2 stories or greater)	2.76 SQ	7.21	0.00	19.90

CONTINUED - ROOF1

DESCRIPTION	QUANTITY	UNIT PRICE	TAX	RCV
15. Additional charge for high roof (2 stories or greater)	3.04 SQ	25.56	0.00	77.70
17. Gutter / downspout - aluminum - up to 5"	12.92 LF	10.57	4.66	141.22
19. Gutter / downspout - aluminum - up to 5"	10.00 LF	10.57	3.61	109.31
Totals: ROOF1			**217.17**	**9,780.03**

Area Totals: Source - EagleView Roof

2,173.13 Exterior Wall Area
1,525.16 Surface Area
15.25 Number of Squares
212.92 Total Perimeter Length
45.58 Total Ridge Length

Total: Source - EagleView Roof		**217.17**	**9,780.03**

Area Totals: Source - EagleView Roof

2,173.13 Exterior Wall Area
1,525.16 Surface Area
15.25 Number of Squares
212.92 Total Perimeter Length
45.58 Total Ridge Length

Total: Source - EagleView Roof		**217.17**	**9,780.03**

Labor Minimums Applied

DESCRIPTION	QUANTITY	UNIT PRICE	TAX	RCV
18. Gutter labor minimum	1.00 EA	263.80	0.00	263.80
Totals: Labor Minimums Applied			**0.00**	**263.80**
Line Item Totals: 35-95Z3-96MR			**217.17**	**10,043.83**

Grand Total Areas:

2,173.13 Exterior Wall Area

1,525.16 Surface Area
15.25 Number of Squares
212.92 Total Perimeter Length
45.58 Total Ridge Length

Trade Summary

Includes all applicable Tax, General Contractor O&P, and Labor Minimums

DESCRIPTION	LINE ITEM QTY	REPL. COST TOTAL	ACV	NON-REC. DEPREC.	MAX ADDL. AMT AVAIL.
RFG ROOFING					
3 tab - 25 yr. - comp. shingle roofing - w/out felt	17.00 SQ	$4,607.13	$4,607.13	$0.00	$0.00
Tear off, haul and dispose of comp. shingles - 3 tab	15.25 SQ	$1,167.24	$1,167.24	$0.00	$0.00
Asphalt starter - universal starter course	78.00 LF	$175.66	$175.66	$0.00	$0.00
Drip edge	212.92 LF	$698.29	$698.29	$0.00	$0.00
Roofing felt - 15 lb.	7.99 SQ	$333.66	$333.66	$0.00	$0.00
Flashing - pipe jack	1.00 EA	$61.53	$61.53	$0.00	$0.00
Additional charge for high roof (2 stories or greater)	3.04 SQ	$77.70	$77.70	$0.00	$0.00
Remove Additional charge for high roof (2 stories or greater)	2.76 SQ	$19.90	$19.90	$0.00	$0.00
Ice & water barrier	366.00 SF	$755.13	$755.13	$0.00	$0.00
Hip / Ridge cap - Standard profile - composition shingles	45.58 LF	$329.75	$329.75	$0.00	$0.00
Additional charge for steep roof - 7/12 to 9/12 slope	10.85 SQ	$583.73	$583.73	$0.00	$0.00
Remove Additional charge for steep roof - 7/12 to 9/12 slope	9.86 SQ	$174.82	$174.82	$0.00	$0.00
Additional charge for steep roof - 10/12 - 12/12 slope	3.04 SQ	$257.15	$257.15	$0.00	$0.00
Remove Additional charge for steep roof - 10/12 - 12/12 slope	2.76 SQ	$76.89	$76.89	$0.00	$0.00
Roof vent - turtle type - Plastic	3.00 EA	$210.92	$210.92	$0.00	$0.00
TOTAL ROOFING		**$9,529.50**	**$9,529.50**	**$0.00**	**$0.00**
SFG SOFFIT, FASCIA, & GUTTER					
Gutter / downspout - aluminum - up to 5"	22.92 LF	$250.53	$250.53	$0.00	$0.00
Gutter labor minimum	1.00 EA	$263.80	$263.80	$0.00	$0.00
TOTAL SOFFIT, FASCIA, & GUTTER		**$514.33**	**$514.33**	**$0.00**	**$0.00**
TOTALS		**$10,043.83**	**$10,043.83**	**$0.00**	**$0.00**


Note: Slight variances may be found within report sections due to rounding

Time & Material Breakdown

Items	Quantity	Unit Price	Total Cost
ROOFING			
Material -			
1 1/4" roofing nails, (based on 50 lb box)	37.03 LB	2.546	94.27*
1 1/2" roofing nails, (based on 50 lb box)	2.40 LB	3.100	7.45*
Ridge cap, standard profile ridge cap for comp shingles	50.68 LF	2.713	137.50*
Asphalt starter - universal starter course shingles	82.14 LF	0.593	48.71
Ice or water barrier (w/ modified bitumen base)	389.06 SF	0.508	197.64
15 lb ASTM roofing felt - 432 SF roll	2.00 RL	25.674	51.27*
Simplex roofing felt cap nails - (based on 50 lb box)	5.71 LB	2.552	14.56*
Drip edge - painted aluminum, 10' lengths	23.72 EA	9.813	232.75*
Roof vent - turtle type - plastic	3.00 EA	14.080	42.24
Roofing cement - per tube	0.15 EA	7.193	1.09*
Flashing - pipe jack - galvanized or plastic - up to 4"	1.00 EA	17.611	17.60*
Composition shingles - 25 year - 3 tab	17.00 SQ	103.880	1,765.93*
		Material:	**2,611.01**
Contractor Labor -			
Roofer	28.29 HR	162.910	4,608.16*
Demolition Laborer	20.03 HR	61.790	1,237.78*
Roofer	0.74 HR	163.940	120.90*
Roofer	3.29 HR	164.470	541.68*
Demolition Laborer	0.32 HR	61.880	19.90*
		Labor:	**6,528.42**
Equipment -			
Landfill charge - per ton	1.91 TN	95.000	181.17*
		Equipment:	**181.17**
		ROOFING Subtotal:	**9,320.60**
SOFFIT, FASCIA, & GUTTER			
Material -			
Silicone caulk - 10 oz tube	0.24 TB	12.480	3.03*
Gutter/downspout - aluminum	25.46 LF	3.612	91.97*
Gutter hanging bracket - aluminum	3.82 EA	2.190	8.37
		Material:	**103.37**
Contractor Labor -			
Siding Installer	0.95 HR	146.000	138.89*
Labor for Gutter labor minimum	1.00 EA	263.800	263.80
		Labor:	**402.69**
		SOFFIT, FASCIA, & GUTTER Subtotal:	**506.06**
Material			**2,714.38**
Labor			**6,931.11**
Equipment			**181.17**
Subtotal			**9,826.66**

POPE, MARY		35-95Z3-96MR
	Material Sales Tax	217.17
Total		**10,043.83**

Back slope (R1) of the house showing wind and deterioration.



Front slope (R3&R4) of the house shows wind and deterioration. (Includes F2, F3, F4, & F5)

N

Source - EagleView Roof