Your Insurance Claims Network
675 Alpha Dr. Suite E&K, Highland Heights, OH 44143
216 331 8323
5/12/2026 2:33 PM

Insured:	FLOYD BREAZEALE	Estimate:	FLOYD BREAZE2
Property:	13720 BANGOR AVE GARFIELD HTS, OH 44125-6003	Claim Number:	3598C944L
		Policy Number:	35GJR1404
Home:	216-319-0275	Price List:	OHCL28_MAR26 Restoration/Service/Remodel
Type of Loss:	Wind		
Deductible:	$0.00		
Date of Loss:	3/12/2026		
Date Inspected:	3/30/2026		

Summary for Dwelling


Line Item Total	16,127.98
Material Sales Tax	383.56
Replacement Cost Value	16,511.54
Less Deductible	(0.00)
Net Payment	$16,511.54

Kevin Stone
216-331-8323

ALL AMOUNTS PAYABLE ARE SUBJECT TO THE TERMS, CONDITIONS AND LIMITS OF YOUR POLICY.

Source - EagleView Roof

Source - EagleView Roof




ROOF1

1,695.24	Surface Area	16.95	Number of Squares
164.45	Total Perimeter Length	24.20	Total Ridge Length
84.16	Total Hip Length		

DESCRIPTION	QUANTITY	UNIT PRICE	TAX	RCV
SHINGLES				
1. Tear off, haul and dispose of comp. shingles - 3 tab	16.95 SQ	76.65	0.00	1,299.22
2. 3 tab - 25 yr. - comp. shingle roofing - w/out felt	18.67 SQ	264.42	165.88	5,102.60
Component RFG240 from this line item was priced by ITEL Asphalt Shingle Pricing (ASP) on 20 Mar 2026. Included 10% wastage				
3. R&R Hip / Ridge cap - cut from 3 tab - composition shingles	108.36 LF	8.86	11.62	971.69
Component RFG240 from this line item was priced by ITEL Asphalt Shingle Pricing (ASP) on 20 Mar 2026.				
4. Asphalt starter - universal starter course	164.45 LF	2.21	8.55	371.98
5. Drip edge	164.45 LF	3.18	14.73	537.68
6. Valley metal	14.44 LF	7.14	2.92	106.02
UNDERLAYMENTS				
7. Roofing felt - 15 lb.	12.24 SQ	41.10	8.07	511.13
8. Ice & water barrier	471.00 SF	2.02	20.35	971.77
VENTS AND FLASHINGS				
9. Flashing - pipe jack	2.00 EA	60.02	2.99	123.03
10. Roof vent - turtle type - Metal	2.00 EA	79.49	3.90	162.88
11. Chimney flashing - small (24" x 24")	1.00 EA	407.46	5.13	412.59
GUTTER				

CONTINUED - ROOF1

DESCRIPTION	QUANTITY	UNIT PRICE	TAX	RCV
12. Detach & Reset Gutter / downspout - aluminum - up to 5"	143.20 LF	6.51	0.00	932.23
To install the roof properly, the gutter pipe needs to be detached and reset properly.				
Totals: ROOF1			**244.14**	**11,502.82**



ROOF2

624.90	Surface Area	6.25	Number of Squares
96.15	Total Perimeter Length	2.24	Total Ridge Length
67.58	Total Hip Length		

DESCRIPTION	QUANTITY	UNIT PRICE	TAX	RCV
SHINGLES				
13. Tear off, haul and dispose of comp. shingles - 3 tab	6.25 SQ	76.65	0.00	479.06
14. 3 tab - 25 yr. - comp. shingle roofing - w/out felt	7.00 SQ	264.42	62.19	1,913.13
Component RFG240 from this line item was priced by ITEL Asphalt Shingle Pricing (ASP) on 20 Mar 2026. Included 10% wastage				
15. R&R Hip / Ridge cap - cut from 3 tab - composition shingles	69.82 LF	8.86	7.48	626.08
Component RFG240 from this line item was priced by ITEL Asphalt Shingle Pricing (ASP) on 20 Mar 2026.				
16. Drip edge	96.15 LF	3.18	8.62	314.38
17. Asphalt starter - universal starter course	96.15 LF	2.21	5.00	217.49
UNDERLAYMENTS				
18. Roofing felt - 15 lb.	6.25 SQ	41.10	4.12	261.00

CONTINUED - ROOF2

DESCRIPTION	QUANTITY	UNIT PRICE	TAX	RCV
GUTTER & DOWNSPOUT				
* 19. R&R Gutter - aluminum - up to 5"	96.15 LF	11.27	34.69	1,118.30
* 20. R&R Downspout - aluminum - up to 5"	48.00 LF	11.27	17.32	558.28
Totals: ROOF2			**139.42**	**5,487.72**

Area Totals: Source - EagleView Roof

403.23 Exterior Wall Area			
2,320.14 Surface Area	23.20 Number of Squares	260.60 Total Perimeter Length	
26.44 Total Ridge Length	151.74 Total Hip Length		

Total: Source - EagleView Roof	**383.56**	**16,990.54**

Area Totals: Source - EagleView Roof

403.23 Exterior Wall Area			
2,320.14 Surface Area	23.20 Number of Squares	260.60 Total Perimeter Length	
26.44 Total Ridge Length	151.74 Total Hip Length		

Total: Source - EagleView Roof	**383.56**	**16,990.54**

Debris Removal

0.00 SF Walls	0.00 SF Ceiling	0.00 SF Walls & Ceiling
0.00 SF Floor	0.00 SF Short Wall	0.00 LF Floor Perimeter
0.00 SF Long Wall		0.00 LF Ceil. Perimeter

DESCRIPTION	QUANTITY	UNIT PRICE	TAX	RCV
21. Dumpster load - Approx. 12 yards, 1-3 tons of debris	1.00 EA	-479.00	0.00	-479.00
Totals: Debris Removal			**0.00**	**-479.00**
Line Item Totals: FLOYD BREAZE2			**383.56**	**16,511.54**

Grand Total Areas:

403.23	Exterior Wall Area				
2,320.14	Surface Area	23.20	Number of Squares	260.60	Total Perimeter Length
26.44	Total Ridge Length	151.74	Total Hip Length		



1 35-Front Elevation



2 34-Front Elevation



3 53-Right Elevation



4 52-Right Elevation



5 39-Left Elevation



6 25-All Photos



7 26-All Photos




8 27-All Photos




9 28-All Photos



10 29-All Photos



11 30-All Photos



12 31-Back Slope



13 32-Back Slope



14 33-Back Slope



15 36-Front Slope



16 37-Front Slope



17 38-Front Slope



18 40-Left Slope



19 41-Left Slope



20 42-Other Photos



21 43-Other Photos



22 44-Other Photos



23 45-Other Photos



24 46-Other Photos



25 47-Other Photos



26 48-Other Photos



27 49-Other Photos



28 50-Other Photos




29 51-Right Elevation




30 54-Right Slope



31 55-Right Slope



32 56-Right Slope



All Slopes of both main and garage roof need replacement.
The roof shingle is 3 Tab shingles - no longer available

