



MIPS_16 PowerPlan Assignment

1- GUI Screenshots:


- M6 : M9 (rings and straps):



- M1 (rails):




- VIAs:




2- Reports

- Missing vias report:




- PG connectivity report:



The screenshot shows a text editor window titled "pg-connectivity.rpt" with the following content:

```
powerplan.tcl      missing_via.rpt      pg-connectivity.rpt      pg-drc.rpt
Loading cell instances...
Number of Standard Cells: 13831
Number of Macro Cells: 0
Number of IO Pad Cells: 0
Number of Blocks: 0
Loading P/G wires and vias...
Number of VDD Wires: 421
Number of VDD Vias: 28281
Number of VDD Terminals: 196
Number of VSS Wires: 3905
Number of VSS Vias: 35581
Number of VSS Terminals: 186
*****Verify net VDD connectivity*****
Number of floating wires: 0
Number of floating vias: 0
Number of floating std cells: 13831
Number of floating hard macros: 0
Number of floating I/O pads: 0
Number of floating terminals: 0
Number of floating hierarchical blocks: 0
*****Verify net VSS connectivity*****
Number of floating wires: 0
Number of floating vias: 0
Number of floating std cells: 13831
Number of floating hard macros: 0
Number of floating I/O pads: 0
Number of floating terminals: 0
Number of floating hierarchical blocks: 0
*****
Overall runtime: 0 seconds.
```

- PG DRC report:



The screenshot shows a text editor window titled "pg-drc.rpt" with the following content:

```
powerplan.tcl      missing_via.rpt      pg-connectivity.rpt      pg-drc.rpt
Command check_pg_drc started at Tue Aug 25 05:05:42 2026
Command check_pg_drc finished at Tue Aug 25 05:05:43 2026
CPU usage for check_pg_drc: 0.99 seconds ( 0.00 hours)
Elapsed time for check_pg_drc: 0.89 seconds ( 0.00 hours)
No errors found.
```