




542_z06



543_z2



682_z29



interior lacuna (in per-cell means)
 lacuna touching the frame (not in per-cell means)
 default cut
 inside a flagged canal region, may be vascular

Dim out-of-plane cells are not detected and are not drawn. Fixed display window for all panels. Pre-validation, pixel units.