




FOOTING PLAN 1:100




TYPICAL PERIMETER CONDITION




TYPICAL INTERNAL CONDITION

TYPICAL STEP



TYPICAL FOOTING BM. 'FB'
1:20



VIEW A-A 1:50

BOA DETAILS

LEGEND:


SEWER MAIN AND DIRECTION OF FLOW	POTABLE WATER MAIN	VC	VITRIFIED CLAY
SYDNEY WATER SEWER MAN HOLE	HYDRANT	S.O.	SQUARE OFF
MAINTENANCE SHAFT	STOP VALVE	PEG	PEG IN GOUND
RODDING POINT	DICL DUCTILE IRON CEMENT LINED	NAIL	NAIL IN GROUND OR ON WALL
VENTSHAFT (INDUCT OR EDUCT)	EW EARTHENWARE	BDY	BOUNDARY
VERTICAL RISER	RC REINFORCED CONCRETE	EX.	EXISTING
P.C.P. OR JUNCTION	SGW SALT GLAZED WARE	DN / Ø	DIAMETER / PEG

NTS

ELECTRONIC DETECTION USED TO LOCATE SEWER MAIN ON SITE.

NOTES:

1. CONTRACTOR TO CONFIRM LINE, LEVEL AND SIZE OF ALL THE EXISTING SERVICES (AS PER NOTE ON PLAN) WITHIN THE VICINITY OF ANY NEW WORKS AND REPORT ANY CONFLICT TO SITE SUPERINTENDENT PRIOR TO ANY CONSTRUCTION COMMENCING
2. Ausflow PTY LTD (ABN: 86 097 766 428)
 Ph: (02) 9555 7979
 Level 1, 323a Darling Street, Balmain NSW 2041
 Email: info@ausflowsydney.com.au
 Web: www.ausflowsydney.com.au
 ACCREDITED AS SERVICE PROTECTION REPORTER BY SYDNEY WATER
3. THE LOCATION OF THE ASSETS SPECIFIED ON THIS REPORT HAVE BEEN TAKEN FROM EXISTING FENCE LINES AND/OR SURVEYORS MARKINGS OR PEGS. FENCE LINES MAY NOT BE TRUE BOUNDARY LINES AND MAY NEED TO BE CONFIRMED BY SURVEYOR.
4. THIS PLAN IS NOT TO SCALE. DO NOT SCALE FROM THIS PLAN REFER DIMENSIONS SHOWN



PLAN TO BE READ IN CONJUNCTION WITH CURRENT SURVEY PLAN

PRIOR TO COMMENCEMENT OF EXCAVATION FOR PROPOSED AND/OR EXISTING SERVICES CONTACT:

CALL BEFORE YOU DIG	Ph	1100
ELECTRICITY	ALIDRO	Ph 4951 4555
GAS	AGILITY	Ph 132 909
TELECOM	TELSTRA	Ph 9204 0880

GIVE AT LEAST 48 HOURS NOTICE

UTILITIES LOCATED

SERVICE	DATE	SIZE (mm)	TYPE
EXISTING SEWER:	17/10/22	225	VC
STORMWATER: SW	-	-	-
POTABLE WATER:	-	-	-

SITE STRATA (CIRCLE APPLICABLE)

CLAY | ROCK | ROCK TRENCH | SAND | SHALE | TUNNEL | RUBBISH FILL | OTHER (SPECIFY) -

I Gabriel Austin of Ausflow Pty Ltd, being accredited to carry out a Service Protection Report, certify that the information shown on the report is accurate and has been prepared in accordance with the relevant instructions

LOCATOR Gabriel Austin
LOCATOR SIGNATURE

PEG-OUT / SERVICE PROTECTION REPORT
AT SITE SHEET

AUSFLOW

BUILDING PLAN APPPROVED:

INSPECTIONS REQUIRED

- [X] CONCRETE ENCASEMENT
- [X] PIER FOUNDATION
- [] SIDE LINE / JUNCTION
- [] GENERAL SITE

BOOK YOUR INSPECTION 48hrs PRIOR TO WORKS COMMENCING Call (02) 9555 7979

Accredited Supplier to SYDNEY WATER

BUILDING PLAN APPROVED SUBJECT TO REQUIREMENTS

Ref No: 1650950 Date: 18/5/23

CORDOR Pty. Limited T/A
ALDRED WU & ASSOCIATES
CONSULTING ENGINEERS
STRUCTURAL - CIVIL

PO BOX 133
KILLARA, NSW 2071
M: 0411139 899

e: aldredwu@gmail.com

No	DESCRIPTION	DATE

PROPOSED DWELLING

83 BRIXTON ROAD, BERALA

FOOTINGS PLAN AND BOA DETAILS

Project number	2021 08	Dwg. number	2
Date	03.02. 23		
Drawn by	DC		
Checked by	AW	Scale	1:50 UNO