# Tribological characterization of polyvinyl alcohol hydrogel as substitute of articular cartilage

#### **OBJETIVE**

Demonstrate that under tribological loading mimicking in vivo conditions, PVA hydrogel presents friction and wear characteristics compatible with articular cartilage making it suitable for replacement.

#### SAMPLE PREPARATION

Samples were evaluated in hydrated state without any additional process o dehydration.

### **DATA ACQUISITION**

500nm

UNWORN

500 nm


UNWORN

All the AFM examinations were carried out in the same room kept at 24 °C and approximately 50% relative humidity. Observations were conducted in an aqueous environment (distilled water). AFM scans were performed in contact-mode using Si3N4 tips and considering the central area of the wear track. RMS values were obtained over an area of  $10x10~\mu m^2$  from roughness analysis.

## CONCLUSION

The frictional response and surface preservation of PVA hydrogel for the different test conditions, as proved by AFM analysis, demonstrates that this hydrogel has high potential to be used as substitute of articular cartilage.

### REPRESENTATIVE FIGURE AND RESULT



Root Mean Square (RMS) was the was the surface roughness parameter. Unworn surfaces of PVA and natural bovine articular cartilage where compare, having the PVA hydrogel a lower value for RMS. The peaks are a probable cause of failures in polymerization.

In case of PVA worn surface due to sliding movement against articular cartilage in PBS medium, RMS values decrease for low contact pressure. The PVA surface preserved in

terms of wear.

RMS = 35 nm

RMS = 79 nm

PVA-5.0 MPa

## REFERENCE

Sardinha, V.M. et al, "Tribological characterization of polyvinyl alcohol hydrogel as substitute of articular cartilage", *Wear*, vol. 301, pp. 218 – 225, 2013.

