


RoadSense AI

Road Inspection Report

Road Name	Wit collage	Timestamp	2026-02-26 13:17:42
GPS	17.668755, 75.923294	Source	Citizen
Severity	10.0/10	Level	Emergency
Action	Immediately — Today	Economic Risk	■ 22,500,000

Annotated Detection Image



Defect Breakdown

#	Type	Confidence	Score	Size
1	Pothole	92%	10.0	93x44px
2	Pothole	91%	10.0	95x79px
3	Pothole	60%	6.3	53x13px