

UAF Light Detection and Ranging (LiDAR) and Ortho-Imagery Data Project Report Revilla Corridor

Tetra Tech was contracted by the University of Alaska Fairbanks (UAF) to provide LiDAR and orthoimagery data for the Road to Resources in Alaska Program. Tetra Tech collected LIDAR data and aerial imagery during the fall of 2013 and the spring/summer of 2014. Included within this document are the various reports required by the contract.

Collection Report

LiDAR data for the Revilla corridor project area was acquired with a Cessna 401 aircraft. The tail number of this aircraft is N34MM.

LiDAR Sensor:

Optech Orion H300

Imagery for the Revilla corridor project area was acquired with a Piper Aztec PA-23-250 Turbo twin aircraft. The tail number of this aircraft is C-FKSK.


Imagery Camera:

Intergraph DMC01 Digital Mapping Camera

Survey Report

Each polygon area contains calibration points as well as independent check points. Check points have been withheld from Tetra Tech. The coordinates with field notes for each area will be provided to GINA directly by the surveyor, McClintock Land Associates.

The Revilla area contains 3 calibration points and 10 independent check points as shown in the diagram below.





Certification from Surveyor

Revilla

QUALITY CONTROL REVIEW SUMMARY

Max. High Elev. Deviation:1.00feetMax. Low Elev. Deviation:-0.38feetElevation Deviation Range:1.38feetElevation Deviation Mean:0.17feetElevation Deviation RMSE0.43feet

(RMSE = Root Mean Square Error)

CHECK POINTS				SURVEYED			LiDAR	Daviation
Point Number	Northing (Fee	t) Easting	(Feet)	Elevation (Feet)	CATEGORY	TIN File Name	Elevation (Feet)	Deviation (Feet)
403	1492240.76	1492240.76 314828		1090.30	Open	L31475_14900	1090.42	0.12
404	1474233.49	31373	344.83	293.64	Open	L31350_14725	294.64	1.00
405	1460478.58	3164′	14.69	356.31	Open	L31625_14600	356.33	-0.02
407	1446180.33	31596	93.52	2593.03	Open	L31575_14450	2593.40	-0.38
408	1422557.17	31658	373.95	652.00	Open	L31650_14225	652.10	-0.10
409	1402643.85	31636	650.03	38.88	Open	L31625_14025	38.54	0.34
410	1415487.58	31656	612.00	416.77	Forest	L31650_14150	416.90	-0.13
411	1439838.53 3		942.35	603.08	Forest	L31600_14375	602.49	0.59
412	1471102.95 3149636.12		376.09	Forest	L31475_14700	376.02	0.06	

Page 1 of 1 Printed: 12/10/2014

TIN CERTIFICATION

Date Prepared: 12/10/2014

Roads to Resources – REVILLA – TIN Surface Model

Prepared by: McClintock Land Associates, Inc.

Prepared for: Tetra Tech, Inc.

I hereby certify that an independent ground survey was performed under my supervision to obtain sampling data to be used to test the reliability of the electronic Triangular Irregular Network (TIN) surface model for Revilla, Alaska. This TIN is based on the Model Key Points Method. For ease of manipulation the surface model was divided into 183 cells as defined by the .dwg files shown on the attached listing.

These files were produced by Tetra Tech, Inc. from a LiDAR survey. The LiDAR data was acquired and calibrated by Aerial Surveys International flown on June 18, 26, 27, July 1, 10, and 11, 2014 and processed by Tetra Tech, Inc. between October 31 and December 8, 2014.

The independent ground survey was performed by McClintock Land Associates, Inc. October 17, 2013 and May 1, 2014 using Static and RTK GPS methods as well as conventional optical methods. Topcon Data Collectors, along with Topcon HiPer GA and GR-3 GNSS receivers were used as well as a Topcon GPT-3005LW Reflectorless Electronic Total Station. Topcon Magnet Field v2.0.1 data collection software was used for the field data collection and Topcon Magnet Office Tools v2.0.1 office software was used for post-processing and adjustments.

The survey data was collected in Alaska State Plane Coordinates, Zone 1 (NAD83) in US Survey Feet. The vertical datum is NAVD88 in feet and elevations were determined as approximate orthometric heights using Geoid Model 2012A. Ties to the NSRS were made using the NGS OPUS Utility. A more detailed description of the methods and control will be contained in the Survey Report for this project.

This TIN was checked using independent QC check points which had been withheld from the TIN producer. The RMS error standard for ASPRS Class 2 Maps for Vertical Accuracy for a 2 foot contour interval map is 2/3 of the contour interval or 1.33 feet. The RMS error between the elevations returned from the TIN and the actual check points was 0.43 feet. This map meets and exceeds that standard.



Professional Land Surveyor
McClintock Land Associates, Inc.

12-10-2014

Date

12/04/2014 L31350 14700-Surface.dwg 12/04/2014 L31350 14725-Surface.dwg 12/04/2014 L31350_14750-Surface.dwg 12/04/2014 L31350_14775-Surface.dwg 12/04/2014 L31350_14800-Surface.dwg 12/04/2014 L31475_14875-Surface.dwg 12/04/2014 L31475_14850-Surface.dwg 12/04/2014 L31475 14825-Surface.dwg 12/04/2014 L31475_14900-Surface.dwg 12/05/2014 L31375_14800-Surface.dwg 12/05/2014 L31375_14825-Surface.dwg 12/05/2014 L31400 14700-Surface.dwg 12/05/2014 L31400 14725-Surface.dwg 12/05/2014 L31400 14750-Surface.dwg 12/05/2014 L31400_14775-Surface.dwg 12/05/2014 L31400 14800-Surface.dwg 12/05/2014 L31400 14825-Surface.dwg 12/05/2014 L31400_14850-Surface.dwg 12/05/2014 L31700 14475-Surface.dwg 12/05/2014 L31425_14725-Surface.dwg 12/05/2014 L31425_14750-Surface.dwg 12/05/2014 L31425_14800-Surface.dwg 12/05/2014 L31425_14825-Surface.dwg 12/05/2014 L31425_14850-Surface.dwg 12/05/2014 L31375 14775-Surface.dwg 12/05/2014 L31425_15000-Surface.dwg 12/05/2014 L31425 15025-Surface.dwg 12/05/2014 L31700_14450-Surface.dwg 12/05/2014 L31450 14725-Surface.dwg 12/05/2014 L31450_14750-Surface.dwg 12/05/2014 L31450 14800-Surface.dwg 12/05/2014 L31450 14825-Surface.dwg 12/05/2014 L31450_14850-Surface.dwg 12/05/2014 L31450_14875-Surface.dwg 12/05/2014 L31450_14900-Surface.dwg 12/05/2014 L31450_14925-Surface.dwg 12/05/2014 L31450 14950-Surface.dwg 12/05/2014 L31450 14975-Surface.dwg 12/05/2014 L31450 15000-Surface.dwg 12/05/2014 L31450_15025-Surface.dwg 12/05/2014 L31475_14675-Surface.dwg 12/05/2014 L31475 14700-Surface.dwg 12/05/2014 L31475 14725-Surface.dwg 12/05/2014 L31475 14750-Surface.dwg 12/05/2014 L31700_14500-Surface.dwg 12/05/2014 L31375 14725-Surface.dwg 12/05/2014 L31375_14700-Surface.dwg 12/05/2014 L31425_14975-Surface.dwg 12/05/2014 L31475_14925-Surface.dwg 12/05/2014 L31475_14950-Surface.dwg 12/05/2014 L31475_14975-Surface.dwg 12/05/2014 L31475_15000-Surface.dwg 12/05/2014 L31475_15025-Surface.dwg 12/05/2014 L31475 15050-Surface.dwg 12/05/2014 L31500 14450-Surface.dwg 12/05/2014 L31500_14475-Surface.dwg 12/05/2014 L31500_14650-Surface.dwg 12/05/2014 L31500 14675-Surface.dwg 12/05/2014 L31500_14700-Surface.dwg 12/05/2014 L31500 14725-Surface.dwg 12/05/2014 L31500_14825-Surface.dwg

12/05/2014 L31500 14850-Surface.dwg 12/05/2014 L31500 14875-Surface.dwg 12/05/2014 L31500_14900-Surface.dwg 12/05/2014 L31500_14925-Surface.dwg 12/05/2014 L31500_14950-Surface.dwg 12/05/2014 L31500_14975-Surface.dwg 12/05/2014 L31500_15025-Surface.dwg 12/05/2014 L31500 15050-Surface.dwg 12/05/2014 L31525_14400-Surface.dwg 12/05/2014 L31525_14425-Surface.dwg 12/05/2014 L31525_14450-Surface.dwg 12/05/2014 L31525_14475-Surface.dwg 12/05/2014 L31525 14500-Surface.dwg 12/05/2014 L31525 14650-Surface.dwg 12/05/2014 L31525 14675-Surface.dwg 12/05/2014 L31525 14700-Surface.dwg 12/05/2014 L31525 15050-Surface.dwg 12/05/2014 L31550_14350-Surface.dwg 12/05/2014 L31550 14375-Surface.dwg 12/05/2014 L31550 14400-Surface.dwg 12/05/2014 L31550_14425-Surface.dwg 12/05/2014 L31550_14450-Surface.dwg 12/05/2014 L31550_14475-Surface.dwg 12/05/2014 L31550_14500-Surface.dwg 12/05/2014 L31550 14625-Surface.dwg 12/05/2014 L31550 14650-Surface.dwg 12/05/2014 L31550 14675-Surface.dwg 12/05/2014 L31575_14325-Surface.dwg 12/05/2014 L31575 14350-Surface.dwg 12/05/2014 L31575_14375-Surface.dwg 12/05/2014 L31575 14400-Surface.dwg 12/05/2014 L31575_14425-Surface.dwg 12/05/2014 L31575_14450-Surface.dwg 12/05/2014 L31575_14475-Surface.dwg 12/05/2014 L31575_14500-Surface.dwg 12/05/2014 L31575_14625-Surface.dwg 12/05/2014 L31575_14650-Surface.dwg 12/05/2014 L31575 14675-Surface.dwg 12/05/2014 L31600 14000-Surface.dwg 12/05/2014 L31600 14025-Surface.dwg 12/05/2014 L31600 14050-Surface.dwg 12/05/2014 L31600_14275-Surface.dwg 12/05/2014 L31600_14300-Surface.dwg 12/05/2014 L31600 14325-Surface.dwg 12/05/2014 L31600_14350-Surface.dwg 12/05/2014 L31600_14375-Surface.dwg 12/05/2014 L31600_14400-Surface.dwg 12/05/2014 L31700 14425-Surface.dwg 12/05/2014 L31675_14575-Surface.dwg 12/05/2014 L31675 14550-Surface.dwg 12/05/2014 L31675_14525-Surface.dwg 12/05/2014 L31675_14500-Surface.dwg 12/05/2014 L31675_14475-Surface.dwg 12/05/2014 L31675_14450-Surface.dwg 12/05/2014 L31675 14425-Surface.dwg 12/05/2014 L31675 14225-Surface.dwg 12/05/2014 L31675 14200-Surface.dwg 12/05/2014 L31675 14175-Surface.dwg 12/05/2014 L31675_14150-Surface.dwg 12/05/2014 L31675_14125-Surface.dwg 12/05/2014 L31650 14650-Surface.dwg

12/05/2014 L31650 14625-Surface.dwg 12/05/2014 L31650 14600-Surface.dwg 12/05/2014 L31650 14575-Surface.dwg 12/05/2014 L31650 14550-Surface.dwg 12/05/2014 L31650 14525-Surface.dwg 12/05/2014 L31650_14500-Surface.dwg 12/05/2014 L31650_14475-Surface.dwg 12/05/2014 L31650_14450-Surface.dwg 12/05/2014 L31650_14425-Surface.dwg 12/05/2014 L31650_14400-Surface.dwg 12/05/2014 L31625_14425-Surface.dwg 12/05/2014 L31625_14450-Surface.dwg 12/05/2014 L31625_14475-Surface.dwg 12/05/2014 L31625 14500-Surface.dwg 12/05/2014 L31625_14550-Surface.dwg 12/05/2014 L31625 14575-Surface.dwg 12/05/2014 L31625_14600-Surface.dwg 12/05/2014 L31625_14625-Surface.dwg 12/05/2014 L31625 14650-Surface.dwg 12/05/2014 L31650 14000-Surface.dwg 12/05/2014 L31650 14025-Surface.dwg 12/05/2014 L31650 14050-Surface.dwg 12/05/2014 L31650_14075-Surface.dwg 12/05/2014 L31650_14100-Surface.dwg 12/05/2014 L31650_14125-Surface.dwg 12/05/2014 L31650_14150-Surface.dwg 12/05/2014 L31650_14175-Surface.dwg 12/05/2014 L31650_14200-Surface.dwg 12/05/2014 L31650_14225-Surface.dwg 12/05/2014 L31650_14250-Surface.dwg 12/05/2014 L31650 14275-Surface.dwg 12/05/2014 L31650 14300-Surface.dwg 12/05/2014 L31650 14325-Surface.dwg 12/05/2014 L31700_14525-Surface.dwg 12/08/2014 L31625_14375-Surface.dwg 12/08/2014 L31625_14350-Surface.dwg 12/08/2014 L31625 14325-Surface.dwg 12/08/2014 L31625_14300-Surface.dwg 12/08/2014 L31625 14275-Surface.dwg 12/08/2014 L31625_14250-Surface.dwg 12/08/2014 L31625_14225-Surface.dwg 12/08/2014 L31625_14200-Surface.dwg 12/08/2014 L31625 14175-Surface.dwg 12/08/2014 L31625_14150-Surface.dwg 12/08/2014 L31625_14125-Surface.dwg 12/08/2014 L31625_14100-Surface.dwg 12/08/2014 L31625_14075-Surface.dwg 12/08/2014 L31625_14050-Surface.dwg 12/08/2014 L31625_14025-Surface.dwg 12/08/2014 L31625_14000-Surface.dwg 12/08/2014 L31600 14650-Surface.dwg 12/08/2014 L31600_14625-Surface.dwg 12/08/2014 L31600_14600-Surface.dwg 12/08/2014 L31600_14500-Surface.dwg 12/08/2014 L31600 14475-Surface.dwg 12/08/2014 L31600_14450-Surface.dwg 12/08/2014 L31600_14425-Surface.dwg 12/08/2014 L31450_14700-Surface.dwg 12/08/2014 L31425 14700-Surface.dwg 12/08/2014 L31375_14750-Surface.dwg 12/08/2014 L31625_14400-Surface.dwg



QA/QC Report

Tetra Tech has performed quality control throughout each step of the acquisition and processing for the Revilla corridor project area. The only difficulty encountered was during the acquisition phase of the project, waiting for suitable weather conditions for collection. Difficult weather conditions were a challenge and caused delays and offsets between LiDAR acquisition, image acquisition and ground survey. Our flight teams remained on-site and acquired LiDAR at a lower altitude that enabled collection below cloud deck. The data was immediately checked for quality to determine if the lower flight altitude would affect the data. There was no adverse effect on the data.

Processing Report

Imagery

The imagery was acquired with a DMC01 digital frame camera on July 12, 2014. The flight took place between 10:20 am and 4:20 pm local time. The camera was equipped with airborne GPS and inertial unit (IMU). The image acquisition was planned in conjunction with survey of ground control points and collection of airborne LiDAR data. An aerotriangulation was performed in the Inpho / Trimble Match-AT version 6.0 software. For orthorectification a digital elevation model with 10ft grid spacing was generated from the LiDAR data. The Orthoimagery was then created in Inpho / Trimble OrthoMaster version 6.0 and mosaicked and color balanced in OrthoVista 6.0. MrSID compressed files were created in Lizardtech Geoexpress 9.

For additional information on the image processing see the AT log file and the camera calibration report and GPS shapefile in the imagery directory. Information regarding the processing is also contained in the xml metadata file accompanying each image (i.e. each individual geotiff tile, the complete MrSID mosaics and the individual unbalanced orthoimages).

Aerotriangulation

The aerotriangulation results are documented in the match-at log file "aat.html". The AT relies much on the airborne GPS and IMU. In addition we used ground control points 401, 402 and 406 mainly for vertical control and datum shift. Selecting photo-identifiable horizontal control was a challenge in this terrain and identification of the photo ID point was not very satisfying. However, the required accuracy of 8' rms will be far exceeded based on airborne GPS alone. An additional visual check was performed by overlaying the orthoimagery e.g. with the intensity imagery.

Orthorectification

The imagery was orthorectified in OrthoMaster using a 10ft spacing DEM generated from the LiDAR data, classes 8 and 9.



4 band unbalanced "raw" orthoimages: the raw aerial images were converted from 16 bit to 8 bit, 4-band imagery without any balancing. The imagery was then orthorectified to the full extent of each image. During the orthorectification process images were clipped to the area of interest (AOI) since no DEM is available outside that area.

3 band True Color RGB and Color Infrared CIR mosaics: 8 bit balanced 4 band images were orthorectified. During the orthorectification process images were clipped to the AOI. Overlap between images was not reduced, i.e. orthoimages were rectified to their full extent. Although the most nadir part of each image is to be preferred this allows for the most options to place seamlines (= cut lines) around features such as water bodies or leaning trees and to reduce visibility of seamlines. One of the concerns in the Revilla corridors was image "smear" in the orthoimagery due to the steep terrain. Image smear occurs in steep terrain, at the edge of the image, on terrain surfaces that are facing away from the image center. This situation leads to few image pixels covering a large area on the ground which then leads to smear in the orthoimage when these pixels are stretched during rectification. To eliminate smear this portion of the mosaic will typically be taken from the neighboring flightline. Images were color balanced across the block in OrthoVista and then written out into two set, 3 band RGB and 3 band CIR geotiff tiles. These tiles were combined to a MrSID mosaic in Lizardtech Geoexpress 9. See Figure 1 for organization of the image data delivery.




Figure 1: Organization of image data

The LiDAR data for the Revilla corridor area was acquired June 18, 26, 27 and on July 1, 10 and 11 of 2014. SBET and shapefile of the trajectory are located with the point cloud data (see Figure 2 for the organization of LiDAR and LiDAR derived data). The data was post processed through PosPac, Waypoint's GPS and IMU (inertial measurement unit) post processing software, and LMS, Optech's LiDAR post processing software. PosPac is used to generate the trajectory file which contains the position (X, Y, Z) from differential GPS observations and the plane's attitude (roll, pitch, heading)



from the IMU. LMS is used to join the discreet point range information to the trajectory information through a common time stamp and to calibrate the data. The calibration is achieved by first identifying common features in the overlap of adjacent flight lines, and then adjustments are applied to the IMU's angular offsets to align the data. Once finished, LMS refines the calibration further through a bundle adjustment to create the final calibrated data set.

Classification of the calibrated LiDAR data set is achieved through the use of TerraScan, the industry standard software from TerraSolid for classifying LiDAR. Individual macros were defined that derive and refine a ground surface, vegetation, and buildings. These macros are also used to eliminate spurious points below the surface and high point artifacts. The Revilla area was then manually checked and edited to eliminate low and high points as well as to ensure that points are classified appropriately.

Breaklines were derived from LiDAR and imagery, which are used in the production of contours and help define water classes in the LiDAR data.




Figure 2: Organization of LiDAR data



DSM

The DSM was created from LiDAR first returns and only-returns. A thinning within 1' cells was applied to select points that contribute to the DSM. This selection occurred in Terrascan. Points were then imported into a geodatabase. A terrain was created in 3D Analyst from the imported points and subsequently a 3' spacing grid was generated, using the NATURAL_NEIGHBORS interpolation method.

The ERDAS imagine mosaic tool was then used to clip and tile the DSM at the same time into individual geotiff tiles.




Figure 3: Result, DSM with 3ft grid spacing, tiled and clipped to AOI

DEM

The DEM was created using ESRI 3DAnalyst. The individual steps included:

- Importing all las files into the geodatabase as multipoint, all returns, classes 8 and 9.
- Importing the breaklines as a feature layer.
- Creating a terrain in 3D Analyst from all mass-points.

TETRA TECH

- Creating a 3' spacing grid, using the NATURAL_NEIGHBORS interpolation method
- The ERDAS Imagine mosaic tool was then used to clip and tile the DEM at the same time into individual geotiff tiles (Figure 4).






Figure 4: DEM as a shaded relief overlaid with the tiling scheme.



Intensity Image

- The intensities were exported from the LAS files in the LP360 software to one ESRI grid with 3ft. spacing.
- The grid was then exported in ESRI to a geotiff with data type float.
- The geotiff was again clipped to the AOI and tiled to the LiDAR tiling scheme in ERDAS Imagine.




Figure 5: Intensity image, 3ft spacing, float values.

TIN

TIN creation based model key points

In producing a TIN from LiDAR data, it is common practice to use model key points and breaklines. Model key points are thinned from the LiDAR ground points to represent the terrain, and allow for an



accurate but less dense data set. Model key points are exported from the las files into csv format, with a 150 ft. over edge beyond the tile boundary. Breaklines are imported directly into the Civil3D file, while the csv is referenced externally to create the TIN. There were a total of 37 million model keypoints in the Revilla polygon in 182 tiles.