
DEMO DISTRICT REGULATORY SURVEILLANCE BRIEF

Brick Kiln Compliance & Environmental Enforcement Directorate | Cycle 2025–26

TOTAL SCANNED	UNIQUE KILNS	CONVERTED ZIGZAG	ILLEGAL FCBKs	1 KM CLUSTERS
120 Tiles	65 Active	33 Compliant	15 Violations	58 Kilns



Official Inventory & Uncertainty Intervals (Adjusted for Val Precision/Recall):

Class	Raw Detections	Val Precision	Val Recall	Est. True Count	Honest 95% CI	Compliance Status
FCBK	**27**	**0.885**	**0.850**	**28**	**[18, 41]**	**ILLEGAL OPERATION**
CFCBK	8	0.900	0.950	8	[3, 13]	SPECIAL REVIEW
Zigzag	30	0.650	0.620	31	[20, 45]	COMPLIANT

Rank	Kiln ID	Type	Conf	Coordinates (°N, °	Score	1km Clust	Field Enforcement Re
#1	KILN-DEMO-025	FCBK	96%	28.5601, 77.1828	80	YES	Non-compliant FCBK design operating
#2	KILN-DEMO-053	FCBK	95%	28.6119, 77.1991	80	YES	Non-compliant FCBK design operating
#3	KILN-DEMO-022	FCBK	94%	28.6229, 77.1717	80	YES	Non-compliant FCBK design operating
#4	KILN-DEMO-056	FCBK	91%	28.6011, 77.1186	80	YES	Non-compliant FCBK design operating
#5	KILN-DEMO-052	FCBK	87%	28.6081, 77.1874	80	YES	Non-compliant FCBK design operating
#6	KILN-DEMO-030	FCBK	90%	28.6114, 77.1323	80	YES	Non-compliant FCBK design operating u
#7	KILN-DEMO-048	FCBK	90%	28.6117, 77.1450	80	YES	Non-compliant FCBK design operating u
#8	KILN-DEMO-032	FCBK	93%	28.6208, 77.1595	80	YES	Non-compliant FCBK design operating u
#9	KILN-DEMO-028	FCBK	87%	28.6377, 77.1247	80	YES	Non-compliant FCBK design operating u
#10	KILN-DEMO-047	FCBK	85%	28.6111, 77.1398	80	YES	Non-compliant FCBK design operating u
#11	KILN-DEMO-042	FCBK	84%	28.6167, 77.1985	80	YES	Non-compliant FCBK design operating u
#12	KILN-DEMO-057	FCBK	81%	28.6029, 77.1236	80	YES	Non-compliant FCBK design operating u
#13	KILN-DEMO-027	FCBK	81%	28.5930, 77.1974	80	YES	Non-compliant FCBK design operating u
#14	KILN-DEMO-023	FCBK	85%	28.6180, 77.1572	80	YES	Non-compliant FCBK design operating u
#15	KILN-DEMO-045	FCBK	76%	28.6090, 77.1176	80	YES	Non-compliant FCBK design operating u
#16	KILN-DEMO-039	FCBK	79%	28.6204, 77.1656	80	YES	Non-compliant FCBK design operating u
#17	KILN-DEMO-021	FCBK	80%	28.6427, 77.1963	80	YES	Non-compliant FCBK design operating u
#18	KILN-DEMO-026	FCBK	77%	28.5629, 77.1948	80	YES	Non-compliant FCBK design operating u
#19	KILN-DEMO-020	FCBK	72%	28.6349, 77.1549	80	YES	Non-compliant FCBK design operating u
#20	KILN-DEMO-059	FCBK	71%	28.5970, 77.1471	80	YES	Non-compliant FCBK design operating u

STANDARDIZED FIELD INSPECTION PROTOCOL:

1. Priority Order: Execute inspections strictly by rank #1-#10 (high-confidence unconverted FCBKs in violation).
2. Route Optimization: Sites flagged 'YES' under 1km Clust must be audited in the same vehicular dispatch.
3. Internal Verification: For low-confidence detections (30-60%), verify whether internal zigzag draft baffles are present.
4. Legal Notice: Issue immediate Section 19 Stop-Work notices to unpermitted FCBKs operating post the 2022 mandate.

Official Regulatory Document - For Authorized Field Officers Only