

Home About Writings Consulting Impressum

15 JAN 2021

INSERTION OF MALICIOUS LINKS FOR EXECUTION IN PROFILE PICTURE - UNVALIDATED USER INPUT IN MS SHAREPOINT 2019 (CVE-2020-1456)

Today I am publishing a Finding discovered by my good friend **user_x73x76x6E** - have fun reading his writeup!

Although this vulnerability was not a typical JavaScript XSS, it was categorized as such by Microsoft. This write up should show that even if no script execution is possible, you can still attack users and infrastructure in other ways.

TL; DR

The SharePoint 2019 server for on-premises with implemented user profile options allowed for authenticated users to upload a profile picture. The path to an uploaded image in the users profile could be changed in the save dialog-request. Here, an arbitrary link could be inserted, allowing the user to attack everyone who visits a page with the user's profile picture embedded. Because of the high occurrence of the profile picture in SharePoint, several attacks scenarios like DoS, user tracking, attack relaying and others are possible. This vulnerability was categorized as cross site scripting (XSS) and assigned the CVE ID CVE-2020-1456.

Setup

Windows Server

- Windows Server 2019 Evaluation
- Version: 1809
- OS build: 17763.379
- Windows Updates till 09/09/2019 12:13PM
- added Active Directory Domain Service
 - promote Server to DC
 - create new Forest

SQL Server

- Install MS SQL Server 2017 Evaluation Edition
- installation type: Basic
- Installer Version: 14.1805.40.72.1
- Database Version: 14.0.1000.169
- Install Microsoft SQL Server Management Studio Release 18.2

SharePoint 2019

- SharePoint Server 2019 (Setup Version 16.0.10337.12109)
- IMG file was saved as ISO with Passmark OSFMount (v3.0.1005.0)
- setup SharePoint as a Single-Server Farm
- add the User Profile Service Application.

Vulnerability Scoring

Vulnerability Class: Improper neutralization of user supplied input CWE-79: Improper Neutralization of Input During Web Page Generation ('Cross-site Scripting')

CVSS 2

- Score 6.5 (Medium)
- Vector AV:N/AC:L/Au:S/C:P/I:P/A:P

CVSS 3.1

- Score: 6.5 (Medium)
- Vector: AV:N/AC:L/PR:L/UI:R/S:C/C:L/I:L/A

Detailed Description - Walkthrough

During a test of a SharePoint application I also partly tested SharePoint itself. In the SharePoint setup with user profiles enabled, each user could upload a profile picture. After uploading the picture, it could be reviewed in the user profile before finally accepting it and permanently save the changes, including all other entries.



Upgrade-Insecure-Requests: 1

current-section=Tbl_Sec_SPS-Section-BasicInfo&MSOWebPartPage_PostbackSource=&MSOT1Pn_Selecte
dWpId=AMSOT1Pn_Lview=0.wMSOT1Pn_ShowSettings=FalsesMSOGallery_SelectedLibrary=aMSOGallery_File
erString=AMSOT1Pn_Button=none&FroileEditorEditAboutMe_inidenRTEField=AMSOSPMebPartManager_DisplayWodeName=BrowsesMSOGSPMebPartManager_ExitingDesignWode=falses_EvEntTARGST=ct100%24Plac
eHolderMsin42ProfileSave_Bottoms_EvENTARGSUMENT=AMSOMPD+ATtPage_Shared=AMSOLADVL_Layoutcha
nges=&MSOLayout_InDesignWode=AMSOSPMebPartManager_OldDisplayWodeName=BrowsesMSOSPMebPartManager_Ges_StartWebPartEditingMame=falses&MSOSPMebPartManager_OldDisplayWodeName=BrowsesMSOSPMebPartManager_StartWebPartEditingMame=falses&MSOSPMebPartManager_DldDisplayWodeName=BrowsesMSOSPMebPartManager_Ges_StartWebPartEditingMame=falses&MSOSPMebPartManager_DldDisplayWodeName=BrowsesMSOSPMebPartManager_Ges_StartWebPartEditingMame=falses&MSOSPMebPartManager_DldDisplayWodeName=BrowsesMSOSPMebPartManager

POST request for saving the uploaded profile picture

This request also contained the parameter <code>ctl00%PlaceHolderMain%ProfileEditorEditPictureURL</code>, which held the path to the uploaded profile picture as shown below in URL encoded form.

tHiwaEcDFV6%2Emrc9TMgXUim3d1Y6x3h6Nd7eHXQ1FyeG3smXpai19esUrnydo5ispeAcXiwin2KgK6TOVoB%2Eo3fb
R636LfHjejkGYP2asKyw2F1%2FLLY8KMTXUyp&28EnMmdKF7hjA2bfLPRRphVOXtq784ji42BMPPHSgmtt4FVD09
MV3BG0j98yA4T7ZtQ38C9T41tfKUXRAFE 1e8GcGT7CeG4cd6yXjmenbeol6cb0tx1EbmBco8ah15sGtCybcybcS0TDEwco
Src1E5i9eAAvrPair2A7jbbB%2FkinPcNZ2q9ckUCveXrHow%2RcSahydgHREA6T15vPg6weLLT%2FUXSTf7ay2T3%2
BSPynAyuvyA6di6F2a0jj2A7HKdRXxAN16fVcei5q0dD6F%2BJLAF7DD19SMASJNOX%3FRGMUHCAHNVGjP9tvevoo
1EVej6puEZcXHbDMj8DokHNy7abac%2BC1NqooDMy1pOW13nRawrisf5Caf98dd7JJvGo3ilmhy%2F86d8b5GTSQ3a8m
R8*%3FRKFTMA16jftkBpTPfk1footaf2PXSBUFRG909Md5SHUAQOG9STmft%2Bg8MBHGceitVD16W2F3DA8B5GTSQ3a8m
R8*%3FRKFTMA16jftkBpTPfk1footaf2PXSBUFRG909Md5SHUAQOG9STmft%2Bg8MBHGceitVD16W2F3DA8B5GTSQ3a8m
R8*%3FRKFTMA16jftkBpT1yTXq4Py956vk09WVC+tXMEC119g6S9Md5SHUAQOG9STmft%2Bg8MBHGceitVD16W2F3DA8B7AYAF1TYG8
R7*SJRX9YTRG7VydbMPMbL3ZBMmgyxx7f0osEmg18FD16W3F3DA8B919869WF7MhXAXWDC1cgkCBFXDXiKZdA2B
ACCpdBa8Cp9ha7Mgfj1YXq4Py956vk09WVC+tXMEC119g6S9Md6JdV3APS8UA545jByT0jdV3APS8UA0MAGWXA2SOV
HaBij4KuYFF73e10ovNF1nORPsttY1JuVrd0pd9HBiL1SUXRBMmgx21SPDtxyXLJ8AjbBFhgYGM4XQhHHef71ofye
1flank1Ea64pXfpykobhOv21cd%2Bpmfmyx7f7UADJ28S2L1RSW00A8A7845jByT0jd5My3ySMCho6Wvsag/MkcApP34nk1
r1B442OXm1ArO1McGPcdLGWADWF7TTCHJ2S82L1RSW00A8A784FSSUy00FxVSKM9Msock4Fxwk3FA8B1Mq2ATU
r1CHFff1UADSTT0p4F9C22MMCMcctAlUF9QAHP11g6A32Ba62a8A64d11ZKF6F8LUFYFYA8A78A8B1Mq2ATU
r1CHFff1UADSTT0p4F9C22MMCMcctAlUF9QAHP11g6A32Ba62a8A64d11ZKF6F8LUFYFYA8A7FA8B1Mq2ATU
r1CHFf1UADSTT0p4F9C22MMCMcctAlUF9QAHP11g6A32BA62A8A644F1KF6F8LUFFYFYA8A7FA8B1Mg2ATU
r1CHFf1UADSTT0p4F9C22MMCMcctAlUF9QAHP11g6A32BA63A8A644F1KF8LUF9CH4F8A7A8A7A6471UD
pd6NN12c3A9bkSSc2Bov9HL81BKC7xwKxwee9sxCH5CKEDxpxs6j1LWH7WcYjHh6Q1rp1aN8C00McD1c8Py5SbmykVcEk
QUANPNNntt1d6Cc44phSLW0d7G0ymgAd73OymgAd7NAFP8D1ExBD10ABA7AFFBCA1D08A74F1UADSA7A97A64771UD
pd6NN12c3A9bkSSc2Bov9HL81BKC7xwKxwee9sxCH5CKEDxpxs6j1LWH7WcYjHh6Q1rp1aN8C00McD1c8Py5SbmykVcEk
QUANPNNttt1G6Cc44phSLW0d7G0ymgAd73OymgAd7K15bc1DxG0A7AF1UBJANAF8AF061DeXAFP1AA8A7A67D1D8A7AF1UBJANAF8AF061DeXAFP1AA8A7A67D11BCA1D08A7A

Parameter in POST request for saving the uploaded profile picture

URL encoded Parameter and value

```
ct100%24PlaceHolderMain%24ProfileEditorEditPictureURL=http%3A%2F
%2F192.168.0.151%3A80%2FUser%2520Photos%2FProfilbilder%2Fpoint_shareuser_Mthumb.jpg
```


Plain text parameter and value

```
ct100$PlaceHolderMain$ProfileEditorEditPictureURL=
http://192.168.0.151:80/User%20Photos/Profilbilder/point_shareuser_Mthumb.jpg
```

This POST request could be intercepted and the value of the parameter, changed to http://123.itsec.de/random.png. Because the server accepted the user provided input, the URL was embedded instead of the original URL to the locally stored picture.


Changed Parameter Value

The inserted URL was embedded instead of the profile picture. In this case, a 1GB "image file" was provided behind the link. As seen below, the "image file" was requested by the browser.



Manipulated Parameter in POST request for saving the uploaded profile picture

The embedded link could also be identified in the source code of the web page by analyzing the src parameter of the HTML img tag.



Verification in Browser

Conclusion

Every user who visits a site, where the corresponding user image is embedded, opens the link in the background. This allows for the user to be tracked, produce a lot of traffic in the network, being tricked to carry out prepared attacks and being flagged by internal and/or external systems because of suspicious or malicious behavior (trying to access blocked sites or similar).

Potential Damage and Attack Scenarios

There are several security implications for this kind of attack, especially when thinking of a larger company with many active users.

Denial of Service

The issue may be used to embed links to large files resulting in a Denial of Service (DoS) or a Distributed Denial of Service (DDoS). This can affect the local system because a large amount of data is downloaded with each request by the user. Alternatively, the whole company can be affected because multiply users are requesting a large amount of data, leading to a complete exhaustion of bandwidth or resulting in a Denial of Service at the firewall or company proxy.

This issue may also be used to perform crafted requests to resources on cloud infrastructure, leading to a ban of the companies IP address and thus to a Denial of Service for all other resources (e.g. websites) hosted at the same cloud provider.

Tracking (GDPR)

Because the default configuration of the IIS also sends a complete referrer, the embedded link may be used to track users and store all transmitted information, depending on the SharePoint application in use. This may lead to a breach according to GDPR regulations.

Internal path disclosure (default setting of IIS 10.0)

Because of the default configuration of the IIS web server, internal paths are also sent with each requests, improving the tracking and resulting into internal path disclosure.

Some attacks like Denial of Service, stored cross site scripting (XSS), cross site request forgery (CSRF) via GET and similar can be relayed by providing a link for other users to execute. If an attack link is embedded, each user visiting a site with the "profile picture" embedded, automatically performs the

Reputation damage

The profile picture parameter can also be used to embed links to inappropriate or blocked sites, which are logged and/or blocked by company proxy. This may result into one or more employees being approached and possible given notice for inappropriate behavior.

Additional Thoughts

Because the impact would be even higher if all MS Office products would be affected, we also tested the Office 365 integration for the SharePoint on premise solution. However, even valid profile pictures in SharePoint on premise were not synced to Office365. If the pictures would be synced, there is a possibility that malicious links would be uploaded to all office products like Outlook, Teams, One Drive and SharePoint online.

References

- Microsoft Office SharePoint XSS Vulnerability Official MSRC Entry
- MITRE Entry for CVE-2020-1456
- Official blog post by it.sec GmbH

Home About Writings Consulting Impressum

This work is licensed under a Creative Commons Attribution 4.0 International License. In other words, share generously but provide attribution.