




1.Edit user information and save it



2.The profile picture address in the packet capture request is changed payload:1" onerror=alert('xss') class="1"



3. Any place where the user's avatar is loaded triggers a Cross Site Scripting



4.User information should be added and modified with XSS detection

Assignees

No one assigned

Labels

None yet

**Projects** 

None yet

Milestone

No milestone

Development

No branches or pull requests

1 participant

