## **snyk** Vulnerability DB

Snyk Vulnerability Database > npm > react-native-fast-image

## Information Exposure

Affecting react-native-fast-image package, versions <8.3.0



## Overview

react-native-fast-image is a FastImage, performant React Native image component.

 $"somehost.com", authorization: "..." \ \} \ is loaded, all other subsequent images will use the same headers, this can lead to signing the same headers are the same headers. The same headers is a signing that the same headers are the same headers are the same headers. The same headers are the same headers are the same headers are the same headers are the same headers. The same headers are the same headers. The same headers are the same headers a$ credentials or other session tokens being leaked to other servers.


## References

- GitHub Commit
- GitHub Issue
- GitHub PR

PRODUCT Snyk Open Source Snyk Code Snyk Container Snyk Infrastructure as Code Test with Github Test with CLI RESOURCES Vulnerability DB Blog FAQs COMPANY About Jobs Do Not Sell My Personal Information CONTACT US



Q Search by package name or CVE



Found a mistake?

Report a new vulnerability

Report a new vuln

Press Kit

Events

FIND US ONLINE

TRACK OUR DEVELOPMENT





© 2022 Snyk Limited

Registered in England and Wales. Company number: 09677925

Registered address: Highlands House, Basingstoke Road, Spencers Wood, Reading, Berkshire, RG7 1NT.