


XSS vulnerability in u5cms version 8.3.5 #49





Then view the source code, you can find the entered parameters and their existence in the href attribute of the a tag

If the parameter passed in is a payload carefully constructed by the attacker, it may cause more serious HTML injection. And if possible, I strongly suggest you check more carefully whether the parameters entered by the user are legal when handling user input and output in the program.

Best wishes!



mrolli mentioned this issue on Aug 20

Sanitize GET parameter q #52





Assignees			
No one assigned			
Labels			
None yet			
Projects			
None yet			
Milestone			
No milestone			

Development

No branches or pull requests

2 participants

